

(Position)

E-mail address

## NEW MEXICO ENERGY, MINERALS and NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170

www.emnrd.state.nm.us/ocd/District 3/district3.htm

FAILURE TO REPAIR

BRADENHEAD TEST REPORT					CVD APR27'07
(Submit 2 copies to above address)					DIL CONS. DIV.
April 1	-			DIST. 3	
Date of TestMarch_	?/2007Ope	rator <u>Williar</u>	<u>ns</u>	API #30-0 <u>39217</u>	70300
Property Name Rosa Well No. 64 Location: Unit A Section 29 Township 31N Range 05W					
Well Status (Shut-In or Producing) Tubing 7Z Intermediate Casing 217 Bradenhead 146 - 0					
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH					
TIME <u>BRADENHEAD</u>	PRESSURES: INTERMEDIATE	CASING		BRADENHEAD FLOWED_	INTERMEDIATE FLOWED
5 minutes O HS —	> 115	110	Steady Flow	·	
10 minutes 0 #75 -	7 110	108	Surges		
15 minutes 0 +08 -	7 108	106	Down to Nothi	ng	
20 minutes		· · · · · · · · · · · · · · · · · · ·	Nothing		X
25 minutes		<del> </del>	Gas	X	<del></del>
30 minutes		<u> </u>	Gas & Water_		
			Water		
If bradenhead flowed water, check all of the descriptions that apply below:					
CLEAR FRESH SALTY SULFUR BLACK					
126					
5 MINUTE SHUT-IN BRADENHEAD 126 INTERMEDIATE 0					
REMARKS: Repacked well head fitting to seal off any					
leaks and retested by field technician Bradenhead					
pailed test. 4-20-07 5 Brooks Pressures one					
bailed test. 4-20-07 5. Brooks Pressures ore on Interprediate not Bradenhead. confirmed by G.T. 4-26  By gh Witness_					
ByWitness					
•	0 /				

OIL CONS. DIV. DIST. 3



Exploration & Production P.O. Box 640 Aztec, NM (505) 634-4244

April 24, 2007

Mr. Charles Perrin Aztec OCD District office 1000 Rio Brazos Rd. Aztec, NM 87410

Re: Bradenhead Test Anomaly Rosa Unit # 64

Mr. Perrin:

Williams Exploration has unsuccessfully tested the bradenhead of the Rosa Unit # 64. As part of the testing process, Williams had a 3<sup>rd</sup> party contractor verify wellhead integrity. After verifying the wellhead, Williams was still unable to attain a seal. An AFE is being written to repair the well and will be submitted for partner approval.

Williams is sensitive to monitor the well closely while waiting for the remedial well work to occur. The repair has been scheduled with the responsible engineer and the AFE process has begun. The repair will be expedited subject to rig.

If you require clarification or additional information, please do not hesitate to call me at 505-634-4244.

Respectfully,

Sherry Brooks Team Leader Williams E&P 970-563-3302