	reced in lied of Form	n 3160-5		KΛ	UD MAY1'07
	UNITED STATES	S .	•		L CONS. DIV.
	DEPARTMENT OF BUREAU OF LAND				DIST. 3
	Sundry Notices and Repo	rts on Wells			DIJI. U
				5.	Lease Number
				_	SF-078438
i. T	ype of Well GAS				If Indian, All. or Tribe Name
				7.	Unit Agreement Name
	lame of Operator BURLINGTON		47 60.		
_	RESOURCES OIL &	& GAS COMPANY LP	949. 975. 1955	3>	San Juan 32-9 Unit SWD
	11 - 0 DI - N - 00	<u> </u>	672 172	, 8.	Well Name & Number
3. A	Address & Phone No. of Opera	itor	· · · · · · · · · · · · · · · · · · ·		ਿਨ੍ਹੇ San Juan 32-9 Unit SWD #
. H	PO Box 4289, Farmington, NM	87499 (505) 326-9700		9.	API Well No.
	ocation of Well, Footage, Sec.	., T, R, M			30-045-28563
3	ec., T—N, R—W, NMPM	7	5 (10.	Field and Pool
	Unit A (NENE), 15' FNL &	½ 240' FEL, Sec. 18, 73 2	N, R9W NMPM		Morris Bluf Ent. County and State San Juan, NM
	HECK APPROPRIATE ROY	TO INDICATE NATI	RE OF NOTICE, REPORT, C	THEP D	\TA
			RE OF HOTICE, REPORT, C	iiien da	11/1
	e of Submission: lotice of Intent	Type of Action: Abandonment	☐ Change of Plans	☐ Othe	ar·
1 1 1 1 1			I I CHANGE OF FIAUS		
		Recompletion	New Construction	LJ Out	<i>.</i> .
⊠s	ubsequent Report	☐ Recompletion ☐ Plugging ☑ Casing Repair	☐ New Construction ☐ Non-Routine Fracturing ☐ Water Shut-off	Out	
⊠ S □ F	ubsequent Report inal Abandonment Describe Proposed or Complet	☐ Recompletion ☐ Plugging ☑ Casing Repair ☐ Altering Casing ed Operations	New Construction Non-Routine Fracturing Water Shut-off Conversion to Injection		
S S F F S S S S S S S S S S S S S S S S	ubsequent Report inal Abandonment escribe Proposed or Complet /6/07 MIRU Drake 29. TO IU BOP. TOOH w/ tbg. Pum IH w/ gauge ring to 8200' in agged @ 8155'. Pressure up /D slickline. TOOH w/ tbg. ner to 1200 PSI, OK. TOOH ate 2 BPM @ 700 PSI. PT be / 600 PSI. Hole in csg. 509 /ob, lead w/ 93 bbls lite @ 1 /qz. To 2000 PSI, ok. TOOH	☐ Recompletion ☐ Plugging ☐ Casing Repair ☐ Altering Casing ed Operations OH w/ plug, RIH & se ped 500 gal 15% HCL POOH. RIH & set plug to 1200 PSI, flow we TIH & set RBP @ 815 H w/ pkr. 2/20/07 TI eackside 2 BPM @ 600 O' to 5143', 2/20/07 N 12.1 ppg, tail w/ 15 bbl I & L/D pkr. TIH w/ bl I & 196'. PT to 2000 Ps min. Dig out WH.	☐ New Construction ☐ Non-Routine Fracturing ☐ Water Shut-off	OOH, PT p ND inj vo bbls in 5 rrieving to POOH se 1200 PSI, 200 PSI, & steve H 23 bbls o rreak circ	lug 1500 PSI, OK. ND W lves. 2/7/07 RU slickline 5 min. RIH & pull plug, bol. POOH w/ equalizer st t pkr @ 7708', PT 4-1/2' OK. PUH set pkr @ 5090 OK. Set pkr @ 5112', 2 Bi layden w/ OCD. Pumped s f H2O SITP 1840 PSI. P . Drill cmnt F/ 4948', cir
S S I S S I S I S I S I S I S I S I S I	ubsequent Report inal Abandonment rescribe Proposed or Complet /6/07 MIRU Drake 29. TO IU BOP. TOOH w/ tbg. Pum IH w/ gauge ring to 8200' in agged @ 8155'. Pressure up /D slickline. TOOH w/ tbg. ner to 1200 PSI, OK. TOOH ate 2 BPM @ 700 PSI. PT b 2 600 PSI. Hole in csg. 509 iob, lead w/ 93 bbls lite @ 1 qz. To 2000 PSI, ok. TOOH " csg. Drill cmnt F/ 5165' T ropped off to 800 PSI in 7 ONTINUE ON NEXT PAGE	☐ Recompletion ☐ Plugging ☐ Casing Repair ☐ Altering Casing ed Operations OH w/ plug, RIH & se ped 500 gal 15% HCL POOH. RIH & set plug to 1200 PSI, flow we TIH & set RBP @ 815 H w/ pkr. 2/20/07 TI cackside 2 BPM @ 600 O' to 5143'. 2/20/07 N 12.1 ppg, tail w/ 15 bbl I & L/D pkr. TIH w/ bbl / 5196'. PT to 2000 Ps min. Dig out WH. E>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>	New Construction Non-Routine Fracturing Water Shut-off Conversion to Injection 1.875 of is plug @ 8198'. PC Acid, flush w/ 180 bbls FW. @ 8155' POOH. Flow well 30 If up tbg POOH, RIH w/ ret O', PT RBP to 1200 PSI, OK. A set pkr @ 5200', PT to 12 PSI. Set pkr @ 5143', PT 13 Iotified Jim Lovato w/ BLM S CL B @ 14.6. Displaced w/ ade bit & tagged @ 4948', b	OOH, PT p ND inj vo bbls in 5 rrieving to POOH se 1200 PSI, 200 PSI, & steve H 23 bbls o rreak circ	lug 1500 PSI, OK. ND W lves. 2/7/07 RU slickline 5 min. RIH & pull plug, bol. POOH w/ equalizer st t pkr @ 7708', PT 4-1/2' OK. PUH set pkr @ 5090 OK. Set pkr @ 5112', 2 Bi layden w/ OCD. Pumped s f H2O SITP 1840 PSI. P . Drill cmnt F/ 4948', cir
S S F F S S S S S S S S S S S S S S S S	ubsequent Report inal Abandonment escribe Proposed or Complet /6/07 MIRU Drake 29. TO IU BOP. TOOH w/ tbg. Pum IH w/ gauge ring to 8200' i agged @ 8155'. Pressure up /D slickline. TOOH w/ tbg. ner to 1200 PSI, OK. TOOH ate 2 BPM @ 700 PSI. PT b 2 600 PSI. Hole in csg. 509 iob, lead w/ 93 bbls lite @ 1 qz. To 2000 PSI, ok. TOOH " csg. Drill cmnt F/ 5165' T ropped off to 800 PSI in 7	☐ Recompletion ☐ Plugging ☐ Casing Repair ☐ Altering Casing ed Operations OH w/ plug, RIH & se ped 500 gal 15% HCL POOH. RIH & set plug to 1200 PSI, flow we TIH & set RBP @ 815 H w/ pkr. 2/20/07 TI cackside 2 BPM @ 600 O' to 5143'. 2/20/07 N 12.1 ppg, tail w/ 15 bbl I & L/D pkr. TIH w/ bbl / 5196'. PT to 2000 Ps min. Dig out WH. E>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>	New Construction Non-Routine Fracturing Water Shut-off Conversion to Injection 1.875 of is plug @ 8198'. PC Acid, flush w/ 180 bbls FW. @ 8155' POOH. Flow well 30 If up tbg POOH, RIH w/ ret O', PT RBP to 1200 PSI, OK. A set pkr @ 5200', PT to 12 PSI. Set pkr @ 5143', PT 13 Iotified Jim Lovato w/ BLM S CL B @ 14.6. Displaced w/ ade bit & tagged @ 4948', b	OOH, PT p ND inj vo bbls in 5 rrieving to POOH se 1200 PSI, 200 PSI, & steve H 23 bbls o rreak circ	lug 1500 PSI, OK. ND W lves. 2/7/07 RU slickling 5 min. RIH & pull plug, bol. POOH w/ equalizer s t pkr @ 7708', PT 4-1/2 OK. PUH set pkr @ 509 OK. Set pkr @ 5112', 2 B layden w/ OCD. Pumped f H2O SITP 1840 PSI. F
3. D 5 7 8 to 6 7 d 6 C	ubsequent Report inal Abandonment Pescribe Proposed or Complet /6/07 MIRU Drake 29. TO BU BOP. TOOH w/ tbg. Pum IH w/ gauge ring to 8200' agged @ 8155'. Pressure up /D slickline. TOOH w/ tbg. ner to 1200 PSI, OK. TOOH ate 2 BPM @ 700 PSI. PT b 2 600 PSI. Hole in csg. 509 iob, lead w/ 93 bbls lite @ 1 qz. To 2000 PSI, ok. TOOH " csg. Drill cmnt F/ 5165' T ropped off to 800 PSI in 7 ONTINUE ON NEXT PAGE hereby certify that the foregon	☐ Recompletion ☐ Plugging ☐ Casing Repair ☐ Altering Casing ed Operations OH w/ plug, RIH & se ped 500 gal 15% HCL POOH. RIH & set plug to 1200 PSI, flow we TIH & set RBP @ 815 H w/ pkr. 2/20/07 TI cackside 2 BPM @ 600 O' to 5143'. 2/20/07 N 12.1 ppg, tail w/ 15 bbl I & L/D pkr. TIH w/ bbl / 5196'. PT to 2000 Ps min. Dig out WH. E>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>	New Construction Non-Routine Fracturing Water Shut-off Conversion to Injection 1.875 of is plug @ 8198'. PC Acid, flush w/ 180 bbls FW. @ 8155' POOH. Flow well 30 If up tbg POOH, RIH w/ ret O', PT RBP to 1200 PSI, OK. If & set pkr @ 5200', PT to 12 PSI. Set pkr @ 5143', PT 13 Isotified Jim Lovato w/ BLM S CL B @ 14.6. Displaced w/ ade bit & tagged @ 4948', b SI. OK. TOOH. Test csg. 100	OOH, PT p ND inj vo D bbls in s rieving to POOH se 1200 PSI, 200 PSI, 4 steve H 23 bbls o reak circ D PSI, OK	lug 1500 PSI, OK. ND W lves. 2/7/07 RU slickling 5 min. RIH & pull plug, bol. POOH w/ equalizer s t pkr @ 7708', PT 4-1/2 OK. PUH set pkr @ 509 OK. Set pkr @ 5112', 2 B layden w/ OCD. Pumped f H2O SITP 1840 PSI. F
S S S S S S S S S S S S S S S S S S S	ubsequent Report inal Abandonment Pescribe Proposed or Complet /6/07 MIRU Drake 29. TO BU BOP. TOOH w/ tbg. Pum IH w/ gauge ring to 8200' agged @ 8155'. Pressure up /D slickline. TOOH w/ tbg. ner to 1200 PSI, OK. TOOH ate 2 BPM @ 700 PSI. PT b 2 600 PSI. Hole in csg. 509 iob, lead w/ 93 bbls lite @ 1 qz. To 2000 PSI, ok. TOOH " csg. Drill cmnt F/ 5165' T ropped off to 800 PSI in 7 ONTINUE ON NEXT PAGE hereby certify that the foregon	☐ Recompletion ☐ Plugging ☐ Casing Repair ☐ Altering Casing ed Operations OH w/ plug, RIH & se ped 500 gal 15% HCL POOH. RIH & set plug to 1200 PSI, flow we TIH & set RBP @ 815 H w/ pkr. 2/20/07 TI eackside 2 BPM @ 600 O' to 5143'. 2/20/07 N 12.1 ppg, tail w/ 15 bbl M & L/D pkr. TIH w/ bl M & 5196'. PT to 2000 PS min. Dig out WH. E>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>	New Construction Non-Routine Fracturing Water Shut-off Conversion to Injection 1.875 of is plug @ 8198'. PC Acid, flush w/ 180 bbls FW. @ 8155' POOH. Flow well 30 If up tbg POOH, RIH w/ ret O', PT RBP to 1200 PSI, OK. If & set pkr @ 5200', PT to 12 PSI. Set pkr @ 5143', PT 13 Isotified Jim Lovato w/ BLM S CL B @ 14.6. Displaced w/ ade bit & tagged @ 4948', b SI. OK. TOOH. Test csg. 100	OOH, PT p ND inj vo D bbls in 5 rieving to POOH se 200 PSI, 200 PSI, 4 steve H 23 bbls o break circ D PSI, OK	lug 1500 PSI, OK. ND Walves. 2/7/07 RU slicklines min. RIH & pull plug, bol. POOH w/ equalizer states pkr @ 7708', PT 4-1/2' OK. PUH set pkr @ 5090 OK. Set pkr @ 5112', 2 Bayden w/ OCD. Pumped stayden w/ OCD. PSI, Drill cmnt F/ 4948', cir. Test csg. 2000 PSI,
Signed Id. I Signed	ubsequent Report inal Abandonment Describe Proposed or Complet /6/07 MIRU Drake 29. TO IU BOP. TOOH w/ tbg. Pum IH w/ gauge ring to 8200' agged @ 8155'. Pressure up /D slickline. TOOH w/ tbg. ner to 1200 PSI, OK. TOOH ate 2 BPM @ 700 PSI. PT b 2600 PSI. Hole in csg. 509 ob, lead w/ 93 bbls lite @ 19 resg. Drill cmnt F/ 5165' T ropped off to 800 PSI in 7 ONTINUE ON NEXT PAGE hereby certify that the foregory at a control of the control of	☐ Recompletion ☐ Plugging ☐ Casing Repair ☐ Altering Casing ed Operations OH w/ plug, RIH & se ped 500 gal 15% HCL POOH. RIH & set plug to 1200 PSI, flow we TIH & set RBP @ 815 H w/ pkr. 2/20/07 TI packside 2 BPM @ 600 O' to 5143'. 2/20/07 N 12.1 ppg, tail w/ 15 bbl I & L/D pkr. TIH w/ bbl I & 15196'. PT to 2000 Ps min. Dig out WH. E>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>>	New Construction Non-Routine Fracturing Water Shut-off Conversion to Injection 1.875 of is plug @ 8198'. PC Acid, flush w/ 180 bbls FW. @ 8155' POOH. Flow well 30 If up tbg POOH, RIH w/ ret O', PT RBP to 1200 PSI, OK. If & set pkr @ 5200', PT to 12 PSI. Set pkr @ 5143', PT 13 Isotified Jim Lovato w/ BLM S CL B @ 14.6. Displaced w/ ade bit & tagged @ 4948', b SI. OK. TOOH. Test csg. 100	OOH. PT p ND inj vo bbls in 5 rrieving to POOH se 200 PSI, & steve H 23 bbls o break circ OPSI, OK	lug 1500 PSI, OK. ND Walves. 2/7/07 RU slicklines min. RIH & pull plug, sool. POOH w/ equalizer state pkr @ 7708', PT 4-1/2' OK. PUH set pkr @ 5090 OK. Set pkr @ 5112', 2 Bilayden w/ OCD. Pumped stayden w/ OCD. Pumped stayden w/ OCD. Pumped stayden w/ OCD. PSI. P. Drill cmnt F/ 4948', cir. Test csg. 2000 PSI,
IS SIGNED THE CONT	ubsequent Report inal Abandonment Describe Proposed or Complet /6/07 MIRU Drake 29. TO IU BOP. TOOH w/ tbg. Pum IH w/ gauge ring to 8200' in agged @ 8155'. Pressure up /D slickline. TOOH w/ tbg. ner to 1200 PSI, OK. TOOH ate 2 BPM @ 700 PSI. PT b 600 PSI. Hole in csg. 509 iob, lead w/ 93 bbls lite @ 1 pz. To 2000 PSI, ok. TOOH " csg. Drill cmnt F/ 5165' T ropped off to 800 PSI in 7 ONTINUE ON NEXT PAGE hereby certify that the foregor	☐ Recompletion ☐ Plugging ☐ Casing Repair ☐ Altering Casing ed Operations OH w/ plug, RIH & se ped 500 gal 15% HCL POOH. RIH & set plug to 1200 PSI, flow we TIH & set RBP @ 815 H w/ pkr. 2/20/07 TII backside 2 BPM @ 600 O' to 5143'. 2/20/07 N 12.1 ppg, tail w/ 15 bbl 1 & L/D pkr. TIH w/ b 1 / 5196'. PT to 2000 Ps min. Dig out WH. >>>>>>>>>>> ing is true and correct. (A) / Philana Thon e use)	New Construction Non-Routine Fracturing Water Shut-off Conversion to Injection 1.875 of is plug @ 8198'. PC Acid, flush w/ 180 bbls FW. @ 8155' POOH. Flow well 30 If up fbg POOH, RIH w/ ref O', PT RBP to 1200 PSI, OK. A set pkr @ 5200', PT to 10 PSI. Set pkr @ 5143', PT 13 Iotified Jim Lovato w/ BLM S CL B @ 14.6. Displaced w/ ade bit & tagged @ 4948', b SI. OK. TOOH. Test csg. 100	DOH. PT p ND inj vo D bbls in 5 rrieving to POOH se 1200 PSI, 200 PSI, & steve H 23 bbls o break circ D PSI, OK	lug 1500 PSI, OK. ND Walves. 2/7/07 RU slicklines min. RIH & pull plug, bol. POOH w/ equalizer states pkr @ 7708', PT 4-1/2' OK. PUH set pkr @ 5090 OK. Set pkr @ 5112', 2 Bayden w/ OCD. Pumped stayden w/ OCD. PSI, Drill cmnt F/ 4948', cir. Test csg. 2000 PSI,

San Juan 32-9 Unit SWD #5 30-045-28563 Continued from page 1

> 2/26/07 TIH w/pkr- isolate holes @ 5019' to 5206'. PUH & set pkr @ 5019', pressure up below pkr to 2000 PSI, leaked off. SIW & monitor overnight. POOH & L/D pkr.. TIH open-ended to 5206'. 2/27/07 Spot 300' balanced cmnt plug @ 5206', PUH to 4575'. Reverse out 25 bbls- no cmnt. Pressure up to 1250 PSI, wait 15 min., pressure up to 1750 PSI. SIW. Pumped total 5-1/2 bbls cmnt into form. 2/28/07 WOC. 3/1/07 TIH w/ bit & tagged cmnt @ 5008'. Drill out cmnt 5001' - 5229', COUT stringers to 5319'. Circ hole clean. PT sqz to 1000 PSI, OK. TIH w/ ret. Tool & bit to 8143' (sand on RBP) Circ sand off RBP, latch onto RBP, displaced hole w/ clean fluid. Release RBP, POOH. ND BOP, NU WH. PT 7" csg., pressure up, test failed, dropped 250 PSI in 30 min. ND WH, NU BOP. RIH w/ gauge ring stop @ 7844'. PT 7" csq & 4-1/2" liner to 1000 PSI. Dropped to 600 PSI in 2 min. 500 PSI in 4 min. Pumped into csq @ 1/2 BPM @ 600 PSI. TIH & set RBP @ 8154'. PT at 8123', 2000 PSI, OK. TOOH to TOL @ 7660 & set pkr. PT 4-1/2 at 2000 PSI, OK. Test annulus to 1300 PSI, dropped to 700 PSI @ ½-3/4 BPM, kill pump- 0 PSI in 4 min. TOOH w/ pkr. Bail w/ slickline F/ 8178' T/ 8193'. TIH w/ pkr & set @ 5200'- isolate csq. leak. PT @ 5200',5091',5152', to 2000 PSI- OK. Test @ 5091' dropped 300 PSI in 30 min. TOOH & set pkr @ 30'. TIH w/pkr & set @ 5091', PT interval 5091' to 8154' to 1785 PSI- leaked in 1 hour. PT interval surface to 5091' to 1800 PSI- leaked off in one hour. TIH set pkr @ 5215'- PT 5215' to 8150'- 1800 PSI-leaked in 1 hour. Move pkr to 4998', PT 4998' to surf-1800 PSI- no leak off. Move pkr to 5277', PT 5277' to 8150'- 1850 PSI- leaked off. Move pkr 6454', PT 6454' to 8150'- 1800 PSI- leaked in 1 hour. Move pkr to 7621', PT 7629' - 8150' - 1800 PSI- leaked off to 1670 PSI in one hour, bleed to 500 PSI, held for one hour- OK. Release pkr- PUH to 4991'. TIH & set pkr @ 7685'. PT 7685' to 8150'-1800 PSI- held OK. Release pkr, POOH. TIH open-ended to 5215'. 3/15/07 Pumped balanced plug 5115' to 4915', reverse out approx ≩ bbls of cmnt. Sqz 3.1 bbls cmnt into formation @ 2000 PSI, SWI w/ 1970 PSI. WOC. 3/19/07 TIH w/ Bit to 4905'. Drilled hard cmnt 4905' to 5091'. Establish circ. drilled hard Cmnt. to 5215', circ. hole-PT sqz to 800 PSI for one hour-held OK, POOH & L/D bit. TIH w/ ret. tool to RBP @ 8147', tagged sand. Circ. hole clean, release RBP, POOH, TOOH w/tbg. 3/23/07 TIH w 4-1/2 (176 jts) 10.5# K-55 ST& C tbg. & set @ 8198', w/ SN @ 8188'. RIH w/ gauge ring, tagged @ 8135', Make 2-bail runs. Circ. & displaced. PT w/ third party. Henry Villanueva w/ OCD also on loc. PT @ 500 PSI on chart- OK. ND BOP, NU WH. RU slickline, bail F/8191' T/8193', RIH pull X plug. RD & Released rig on 3/29/07 @ 1800 hrs.