UNITED STATES DEPARTMENT OF THE INTERIOR

GIL CONS. DIV.

BUREAU OF LAND MANAGEMENT					in the state of th	
	Sundry Notices and Reports of	on Wells				
1.	Type of Well GAS	MAR 2 7 Bureau of Land N Farmington Fi	2008 Manage men k	5. 6.	Lease Number SF-077922 If Indian, All. or Tribe Name	
3.4.	Name of Operator BURLINGTON RESCURCES OIL & G Address & Phone No. of Operator PO Box 4289, Farmington, NM 87 Location of Well, Footage, Sec., T, Unit P (SESE), 990' FSL & 330' F CHECK APPROPRIATE BOX TO Type of Submission Type of A	499 (505) 326-9700 R, M EL, Section 34, T30N, R12 D INDICATE NATURE Officion	NOTICE, REPORT,			
	Subsequent Report P	Abandonment Change of Recompletion New Cons lugging Non-Routin Casing Repair Water Sh Altering Casing Conversion	truction Fracturing	<u>Other – MIT</u>	<u>`, tubing repair</u>	
Bu	Describe Proposed or Completed (m a mechanical integrity test	(MIT) on the production	n casing a	nd pull tubing to repair a	
Sig	I hereby certify that the foregoing ned famolessing. us space for Federal or State Office us PROVED BY Original Signed: Step	Tamra Sessions	Title <u>Regulatory Te</u>	chnician	Date <u>3/27/2008</u> .	

ConocoPhillips Hudson #2 (FRC) MIT and Tubing Repair

Lat 36° 45′ 52″ N Long 108° 4′ 38" W

Prepared By:

Karen Mead

Date:

03/26/2008

BAE Peer review/approved By:

Date:

XX/XX/2008

Scope of work: The intent of this procedure is to perform a mechanical integrity test (MIT) on the 3 1/2" production casing and pull the tubing to repair a possible bridge. The wellbore will then be cleaned out and returned to production. Remaining reserves for the FRC are 213 MMscf.

Est. Cost:

Est. Rig Days: 5

WELL DATA:

API:

30045089500000

Location:

990' FSL & 330' FEL, T30N R12W Section 34 Unit P

PBTD: 1929' TD: 2137'

Perforations:

1728'-1864'; 1914'-1938 (FRC)

Well History: The Hudson #2 is a stand-alone Fruitland Coal well spud in July of 1946. It was a Pictured Cliffs well when drilled. The FRC was added in 1995 and the PC TA'd with what looks to be fill (176'). The records were unclear as to why they didn't clean out to the previous PBTD. In 2004, a workover was performed to repair the tubing. They lost fish downhole (1-1/2" IJ tubing) and milled it to a new PBTD of 1929' which covers 9' of the bottom 24' of perfs. What tubing they pulled out of the hole was badly corroded. This well has not produced since October of 2007. A fluid level performed on 01/30/08 indicates a fluid level @ 694' in the casing and 0' in the tubing with pressures of 73.7 and 77.4, respectively. The well is capable of producing 80 Mcfd. TOC on the 3-1/2" casing is at 600' according to a CBL run in 1995.

B2 Adapters are required on all wells other than pumping wells.

Artificial lift on well (type): Compressor

Est. Reservoir Pressure (psig): 100-300psi (FRC)

Well Failure Date: October 2007

Current Rate (mcfd): 0 Est. Rate Post Remedial (mcfd): 80

Earthen Pit Required: No

Special Requirements: 2 hour chart for MIT. RBP for 3-1/2" casing and packer

BAE Production Engineer: Karen Mead, Office: (505)324-5158, Cell: (505)320-3753

BAE Backup: Douglas Montoya, Office: (505)599-3425, Cell: (505)320-8523

MSO: Gracia Montoya Cell: (505) 320-4267

Lead: Donnie Thompson Cell: (505)320-2639

Area Foreman: Terry Nelson Cell: (505)320-2503

ConocoPhillips Hudson #2 (FRC) MIT and Tubing Repair

Lat 36° 45′ 52″ N **Long** 108° 4′ 38" W

PROCEDURE:

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COP safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2. MIRU workover rig. Check casing, tubing, and bradenhead pressures and record them in Wellview.
- 3. RU blow lines from casing valves and begin blowing down casing pressure. Avoid putting water on the well if possible, however kill well with 2% KCl or produced water if necessary. ND wellhead and NU BOPE.
- 4. Unseat donut, remove hanger, and pull 1-1/2" tubing. TOOH with tubing (detail below). Tubing is currently landed @ 1899'.

(58 jts) 1-1/2" 2.4# J-55 tubing

- (1) 1-1/2" Seat Nipple set @ 1866'
- (1-jt)-1-1/2″-2:4# J-55 tubing -- (1) Netsbad Callar act @ 1800/
- (1) Notched Collar set @ 1899'
- 5. Make note of corrosion or scale. Replace tubing as needed. Please notify engineer of any unusual findings. If scale on tubing then spot acid. Contact rig superintendent or BAE engineer for acid volume, concentration and displacement volume.

- Commence of the commence of

- 6. PU and TIH with a RBP and Packer for a 3-1/2'' 7.7# casing on the 1-1/2'' tubing. Set RBP within 50' of the FRC top perfs @ $\sim 1680'$ (top perf @ 1728') and set a packer to test RBP to 500psi for 10 min.
- 7. Unset packer and test casing to 500psi for 30 min on a 2 hour chart. If test passes, go to next step. If test fails, contact Rig Superintendent and BAE Production Engineer (be prepared to squeezing the hole(s).
- 8. Retrieve RBP set @ ~1680', TOOH with RBP.
- 9. TIH with tubing (detail below). TIH with tubing using Tubing Drift Check Procedure on the next page (tubing drift = 1.516'' ID). Recommended landing depth is @ +/-1899' (same as previous).
 - (1) 1-1/2" Muleshoe with Expendable Check
 - (1) 1-1/2" "F" Nipple
 - (1 jt) 1-1/2" 2.4# J-55 IJ Tubing
 - (1) 1-1/2" x 2' 2.4# J-55 IJ Pup Joint
 - (~58 jts) 1-1/2" 2.4# J-55 IJ Tubing to Surface
- 10. Tag for fill, PU additional joints as needed. Record the fill depth in Wellview. If fill is encountered, TIH and clean out to PBTD @ 1929'.
- 11. Run standing valve on shear tool, load tubing and pressure test tubing to 1000 psig. Pull standing valve.
- 12. ND BOP. NU wellhead. Make swab run if necessary to kick off well. Notify lease operator that well is ready to be returned to production. RDMO.

Recommended	Karen Mead	Approved	Approved		
BAE Engineer	Karen Mead	Expense Supervisor	Kelly Kolb		
Office	(505) 324-5158	Office	(505) 326-9582		
Cell	(505) 320-3753	Cell	(505) 320-4785		

