Form 3760-5 (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-013
Expires July 31, 201

5. Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS,				NMM 29340		
Do not use this form for proposals to drill or to re-enter anabandoned well. Use Form 3160-3 (APD) for such proposals. 9 3 2008			2008 6. II	6. If Indian, Allottee or Tribe Name		
			2000	ROUD OCT 7'08		
SUBMIT IN TRIPLICATE - Other instructions on page 2வர் Field Cailce				7. If Unit or CA/Agreement, Name and/or No DIL CONS. DIV.		
1 Type of Well Oil Well X Gas Well Other				Nell Name and No.		
2. Name of Operator			Car	racas 35A	# 16	
Energen Resources Corporation				PI Well No.		
3a. Address 3b. Phone No. (<i>include area code</i>)				30-039-30138		
2010 Afton Place, Farmington, NM 87401 505.325.6800 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)				10. Field and Pool, or Exploratory Area Basin Fruitland Coal		
1545' FNL, 1010' FEL Sec. 35, T32N, R05W, N.M.P.M.				in Fruitiand Co	жш	
SE/NE (H)				11. County or Parish, State		
			Ric	Rio Arriba NM		
12. CHECK APPROPRIATI	E BOX(ES) TO INDIC	ATE NATURE OF N				
TYPE OF SUBMISSION			PE OF ACTION			
1 FE OF SUBMISSION						
Notice of Intent	Acidize	Deepen	Production (Start	n (Start/Resume) Water Shut-Off		
	Alter Casing	Fracture Treat	Reclamation	Well in	ntegrity	
Subsequent Report	Casing Repair	New Construction	Recomplete	X Other		
	Change Plans	Plug and Abandon	Temporarily Aba	ndon		
Final Abandonment Notice	Convert to Injection	Plug Back	Water Disposal			
	Convert to injudicin					
uss performed from 08/11/08 through the state of the stat	cands, 508', set pk hold tailgate safe ag @ 2 BPM, 350#, 3 bllow w/10 bbls dye /gal, pump 50 sks full returns throug eze perfs @ 700'). Clean all surface l ce to 1500#, leakin 3.125" DC's. TIH, at of cement, press	ty meeting. Present bbls. pumped. (H2O. Start lead tail cement Class hout job. Displas Shut bradenhead ines out. RD HES g 200# #in 1 min tag TOC @ 640° ure test squeeze	ssure test surf Circulate out b d cement @ 3 bp ss G, 1.18 yiel ace cement w/8: & tbg in @ 400 S cement crew. nute, bleed psi . Establish rev e to 1000#, lea	ace lines to 30 radenhead to pi m, 130 sks 50/5 d, 15.6#/gal. bbls fresh H20 #, circulated 1 off tbg & csg, erse circ. w/ p king 400#/4 min	000#, all t. Pump 60 poz, All (2 bbls 0 bbls unset prod. H20.	
(continued on page 2)					D FOR RECORD	
14 I hereby certify that the foregoing is true and correct Name (Printed Typed) Vicki Donaghey	***************************************	Title Regula	tory Analyst	GCT	0 6 2008	
Signature View Normaline	1	Date 10/02/0		BY TISA	HELD OFFICE	
7,000	SPACE FOR FEDER					
Approved by	J	Title		Date		
Conditions of approval, if any, are attached Approval of this note the applicant holds legal or equitable title to those rights in the substitute the applicant to conduct operations thereon.		Office				
Title 18 U S C. Section 1001, and Title 43 U S C. Section 1212, r		knowingly and willfully to i	nake to any department or	agency of the United Stat	es any false,	
fictitious or fraudulent statements or representations as to any ma		<u>v</u>				
	MINICO	\mathcal{V}				

CARRACAS 35A #16 PAGE 2

- 3. RU Basin Logging, run CBL w/ GR-VDL collar log from 1500' 0'. Re-run same log under 1000#, log showed 90% bond to surface in most areas. RD Basin Logging. TIH with 23 jts. 2.375" tbg open-ended, 728'. Secure well. Wait on cement crew, SDON.
- 4. RU HES cement crew, pressure test surface lines 3000#, break circulation @ 720' w/5 bbls water @ 3 bpm, 0#. Mix 8 bbls Class G cement, 0.4 Halad-322, 1% CaCl2 @ 15.6#/gal. Spot cement w/2 bbls fresh water. TOOH w/tbg, secure well. Load csg w/1.7 bbls water, hesitate squeeze to 1500#, PSI leaking to 1000# in 3 minutes. Displaced 4.75 bbls TTL water behind squeeze in 30 minutes. Left TOC @ 630', holes @ 696'. Pressure up to 1500#. Shut casing in for the weekend. RD HES. SDOWE.
- 5. Pressure test casing squeeze, pressure test to 1400#, test held 15 minutes with no leakoff. Bleed PSI off, circulate hole clean with production water. Secure well, SION.
- 6. Squeeze work finished, continue with clean out.
- 7. Run production tubing, ND BOP. NU WH. RDMO.