submitted in lieu of Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

RECEIVED

AUG 1 C 2009

Bureau of Land Management

	Sundry Notices and Reports	on Wells	Farmington Field	Onice	
				5.	Lease Number SF-077764
1.	Type of Well GAS		•	6.	If Indian, All. or Tribe Name
_				7.	Unit Agreement Name
2.	Name of Operator · BURLINGTON				,
	RESOURCES OIL &	GAS COMPANY LP			
3.	Address & Phone No. of Operate	or		8.	Well Name & Number Schumacher 11 M
	PO Box 4289, Farmington, NM 8	37499 (505) 326-9700		9.	API Well No.
-					30-045-30066
4.	Location of Well, Footage, Sec.,	Г, R, М		10.	Field and Pool
Su	rf: Unit O (SWSE), 945' FSL & 18	300' FEL, Section 18, T30N	I, R10W, NMPM		
				11.	n DK/Blanco MV County and State San Juan Co., NM
12	. CHECK APPROPRIATE BOX	FO INDICATE NATURE	OF NOTICE, REPORT, OT	HER D	ATA
5	Type of Submission Type of X Notice of Intent	f Action Abandonment	Change of Plans	X	Other – Sqz MV perfs & run MIT drill out CIBPabove DK & produce DK stand-alone
		Recompletion	New Construction		RCVD AUG 14'09
	Subsequent Report	Plugging	Non-Routine Fracturing		OIL CONS. DIV.
	Final Abandonment	Casing Repair Altering Casing	Water Shut off Conversion to Injection		DIST. 3
	. Describe Proposed or Completed	l Operations		 	
Bu	rlington Resources wishes sqz remagand chart & then drill out CIBP &	ining MV interval in an atter	npt to stop water production f	rom this	well. Will conduct MIT on
Se	e attached procedure & wellbore sch	ematic.			
14	. I hereby cortify that the foregoin	g is true and correct.			
Sig	med Shorted Do	Rh.	onda Rogers Title Staff Re	gulatory	Technician Date 8/7/09
(T AI	his space for Federal or State Office PROVED BY <u>Original Signed: S</u>	use) tephen Mason Title			DateAUS 1 1 2003
Title	DNDITION OF APPROVAL, if any 18 U.S.C. Section 1001, makes it a crime for any person kr Justed States any false, fictitious or fraudulent statements or	lowingly and willfully to make any department	or agency of		

NMOCD

PC

ConocoPhillips SCHUMACHER 11M Water Shut-off

Lat 36° 48' 25.056" N

Long 107° 55' 18.588" W

PROCEDURE

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2. MIRU work over rig. Check casing, tubing, and bradenhead pressures and record them in Wellview.
- 3. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with 2% KCI, if necessary.
- 4. Pressure test tubing to 1000 psi before unseating the pump, release pressure.
- 5. TOOH with Rods (details below)

Number	Description
1	1-1/4" x 22' Polished Rod
3	3/4" Pony Rods (4', 6', 8')
88	7/8" Sucker rods
129	3/4" Sucker Rods
3	1-1/4" Sinker bar
1	3/4" Guided Pony (8')
1	2" x 1-1/2" x 14' RWAC-Z pump
•	
	}

6. ND wellhead and NU BOPE. PU and remove (tubing currently landed @ 5589, PBTD @ 7254)

7. TOOH with tubing (details below)

_	Number	Description
_	180	2-3/8" Tubing joints
	1	2-3/8" pup joint (2')
	1	2-3/8" F nipple (ID 1.78")
	1	2-3/8" Price type Cover Joint
	1	2-3/8" x 1-1/2" Crossover
	1	1-1/2" Mule Shoe
		1

Visually inspect tubing and record findings in Wellview. Make note of corrosion or scale. LD and replace any bad joints.

- 8. PU and TIH with a CIBP and Packer for 4-1/2" 10.5# casing, set CIBP @ ~5600' set packer and test CIBP to 500 psi for 10 min.
- 9. TOOH with tubing and packer. TIH with cement retainer set within 50' above top Point lookout perf, top perf @
- 10. RU cementers, establish an injection rate and then squeeze off Point Lookout interval from 5417'-5541'. Sting out of cement retainer leave approx. 1bbl cmt on top of retainer.
- RD Cementer TOOH with tubing PU cement retainer, TIH set cement retainer at ~4940'.
- 12. RU Cementers establish an injection rate and then squeeze off Menefee 4950'-5118'.

- 13. TOOH with tubing.
- 14. TIH with 3-7/8" bit and drill out cement retainers and excess cement left in the 4-1/2" casing to CIBP set at ~5600'.
- 15. Pressure test casing above CIBP to 500psi for 30 min on a 2 hour chart. If test is good continue to next step if no good, attempt to isolate holes, call Superintendent and Production Engineer to discuss plan of action.
- 16. TIH with 3-7/8" mill and drill out CIBPs @ ~5600', and @ 7254'. Fill may be present above CIBP @ 7254'.
- 17. After plugs are milled up. Continure in hole and tag for fill and CO to PBTD @ 7500'. Bottom perf is at 7470'. Call Production Engineer to inform of how much fill was tagged and therefore confirm/adjust landing depth.

18. TOOH

19. TIH with tubing:

Recommended

Tubing Drift ID:	1.901"
Land Tubing At:	7415'
Land F-Nipple At:	7413

Number	Description
1	2-3/8" Mule Shoe w/ expendable check
1	2-3/8" F nipple (ID 1.78")
1	2-3/8" tubing joint
· 1	2-3/8" x 2' Marker Joint
236	2-3/8" tubing joints
As Necessary	Pup Joints
1	2-3/8" Tubing joint

- 20. Run standing valve on shear tool, load and pressure test tubing to 1000 psig. Pull standing valve.
- 21. ND BOP, NU wellhead, blow out expendable check. Make swab run if necessary to kick off well. Notify Lease operator to return to well production. RDMO.