

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

RECEIVED

SEP 21 2009

Sundry Notices and Reports on Wells

Bureau of Land Management

Farmington Lease Number

SF - 080668

1. Type of Well
GAS

6. If Indian, All. or
Tribe Name

2. Name of Operator

BURLINGTON

RESOURCES OIL & GAS COMPANY LP

7. Unit Agreement Name
San Juan 27-4 Unit

3. Address & Phone No. of Operator

PO Box 4289, Farmington, NM 87499 (505) 326-9700

8. Well Name & Number
San Juan 27-4 Unit 147

9. API Well No.

30-039-22991

4. Location of Well, Footage, Sec., T, R, M

Surf: Unit A (NENE), 800' FNL & 1180' FEL, Section 3, T27N, R4W, NMPM

10. Field and Pool

Blanco Mesaverde

11. County and State

Rio Arriba Co., NM

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission

Type of Action

Notice of Intent

Abandonment

Change of Plans

X Other - Repair Tubing/MIT

X Subsequent Report

Recompletion

New Construction

RCVD SEP 29 '09

Final Abandonment

Plugging

Non-Routine Fracturing

OIL CONS. DIV.

Casing Repair

Water Shut off

DIST. 3

Altering Casing

Conversion to Injection

13. Describe Proposed or Completed Operations

08/03/2009 MIRU Key 10. ND WH NU BOP - Test BOP- Good Test.

08/04/2009 - 08/06/2009 POOH w/tbg. Set RBP @ 5850' & PKR @ 5830'. PT - PT Failed. Reset PKR to isolate leak. Found csg bad from 2810' - 3043'. POOH w/tbg & LD PKR.

08/06/2009 CALLED BLM & OCD VERBAL PERMISSION TO CONDUCT 1ST SQUEEZE.

08/07/2009 Pumped 10bbls spacer pm 65sx type III cmt. WOC. Pumped 20sx Type III neat cmt. WOC.

08/10/2009 - 08/11/2009 D/O cmt. PT 1st - failed C/O cmt. Circ clean.08/12/2009 CALLED BLM & OCD VERBAL PERMISSION TO CONDUCT 2ND SQUEEZE. RIH w/new plugs.

Pumped 40sx, 10bbls of Type III cmt w/1.3 displacement. WOC.

08/14/2009 Tag cmt @ 2805'. D/O cmt. Circ clean. PT - Good test.

08/17/2009 Run MIT on chart to 500# for 45 minutes - good test. RU W/L. Run CBL. TOC @ 2530'. RD W/L.

08/18/2009 - 08/20/2009 RIH & retrieve RBP @ 5850'. C/O to PBTD @ 6678'. RIH w/224 jts 2 3/8" 4.7 J-55 tbg & set @ 6616'. NU WH ND BOP RD RR @ 21:00hrs on 08/20/2009.

Chart Attached

14. I hereby certify that the foregoing is true and correct.

Signed Jamie Goodwin

Jamie Goodwin Title Regulatory Technician Date 9/21/09
ACCEPTED FOR RECORD

(This space for Federal or State Office use)

APPROVED BY _____ Title _____

Date

SEP 28 2009

CONDITION OF APPROVAL, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction

FARMINGTON FIELD OFFICE
BY _____

Provide copy of CBL to OGD
B

**ConocoPhillips
San Juan 27-4 Unit # 147
Tubing Repair and MIT**

Lat 36° 36' 25" N Long 107 ° 13' 60" W

PROCEDURE:

1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.
2. MIRU workover rig. Check casing, tubing, and bradenhead pressures and record them in Wellview.
3. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with 2% KCl, if necessary. ND wellhead and NU BOPE.
4. PU and release tubing hanger and tag for fill, adding additional joints as needed. PBTD is at 6678'. Record fill depth in Wellview.
5. TOOH with tubing (detail below).

223 ~ 2-3/8" 4.7# J-55 Tubing joints
1- 2-3/8" 4.7# J-55 seating nipple (0.79") (1.79" ID)
1- 2-3/8" 4.7# J-55 Tubing joint

Visually inspect tubing and record findings in Wellview. Make note of corrosion or scale. LD and replace any bad joints.

6. PU and TIH with RBP and packer for 4-1/2" 10.5# casing on the 2-3/8" tubing set RBP within 50' of the top Mesaverde perms @ 5849' and set a 4-1/2" packer 15'- 20' above RBP to test RBP to 500 psi for 10 min.
7. Unseat packer and test casing to 500 psi for 30 min on a 2 hour chart. If test passes, go to Step 12. If test fails, continue with the next step.
8. Utilize 4-1/2" and 7" packer (if necessary) to isolate the hole(s) in the casing, record location of holes and contact Rig Superintendent and Production Engineer to obtain necessary regulatory approvals and proper squeeze design. Drop 50'+ of sand on top of RBP.
9. RU Cement company, try to get injection rate and returns to surface with water, cement all squeeze holes, circulate to surface if possible.
10. TIH with bit and drill out excess cement left in casing to TOOH.
11. Perform a charted pressure test on casing (after squeezed) to 500 psi for 30 minutes on a 2 hour chart. If test fails call Rig Superintendent and Production Engineer. If test passes continue to step 12.
12. Circulate sand off of RBP, blow hole clear of fluid. Retrieve RBP. TOOH.

13. Utilize air package to clean out to PBTD (6678'). If scale is on the tubing, spot acid. Contact Rig Superintendent and Engineer for acid volume, concentration, and tubing volume. TOOH. LD tubing bailer (if applicable).
14. TIH with tubing (detail below). TIH with tubing using Tubing Drift Check procedure. Recommended landing depth is 6627'. Land FN @ 6626'.
 - 1- 2-3/8" Muleshoe/ Expendable Check (If fill was bailed during cleanout, Utilize a pump out plug in place of expendable check.)
 - 1- 2-3/8" F-Nipple (1.78")
 - 1- 2-3/8" 4.7# J-55 Tubing Joint (31')
 - 1 2-3/8" 4.7# J-55 put Joint
 - ~223 - 2-3/8" 4.7# J-55 Tubing Joints
 - Pups joints as necessary to achieve proper landing depth
15. Run standing valve, load tubing and pressure test tubing to 1000 psig. Pull standing valve. Swab down fluid.
16. Land tubing, ND BOPE, NU wellhead, and blow out expendable check. Notify MSO that well is ready to be turned over to production. Make a swab run, if necessary, to kick off the well. RDMO.



