Form 3160-5 (August 2007)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED

	OMB NO. 1004-0135
	Expires: July 31, 2010
5. Lease Ser JIC109	ial No.

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an

abandoned well. Use form 3160-3 (APD) for such proposals.

6. If Indian, Allottee or Tribe Name JICARILLA APACHE

SUBMIT IN TRIPLICATE - Other instructions on reverse side.					7. If Unit or CA/Agreement, Name and/or No.		
Type of Well					8. Well Name and No. JICARILLA B 1		
Name of Operator Contact: BRIDGET HELFRICH ENER VEST OPERATING LLC E-Mail: bhelfrich@enervest.net  Contact: BRIDGET HELFRICH  E-Mail: bhelfrich@enervest.net					9. API Well No. 30-039-06402-00-S1		
3a. Address 1001 FANNIN STREET SUIT HOUSTON, TX 77002-6708	No. (include area e 195-6537 15-1429	ode)	10. Field and Pool, o BASIN DAKOT	r Exploratory A			
4. Location of Well (Footage, Sec., 7			11. County or Parish,	and State			
Sec 22 T26N R5W SWNE 14 36.47563 N Lat, 107.34363 W			RIO ARRIBA C	OUNTY, NM			
12. CHECK APPI	ROPRIATE BOX(ES) TO	INDICAT	E NATURE OI	F NOTICE, RE	PORT, OR OTHE	R DATA	
TYPE OF SUBMISSION	TYPE OF ACTION						
Notice of Intent	Acidize	□ De	epen Production (Start/Resu		ion (Start/Resume)	☐ Water Shut-Off	
_	☐ Alter Casing	□ Fra	icture Treat	☐ Reclamation		■ Well Integrity	
☐ Subsequent Report	Casing Repair	□ Ne	w Construction	Recomp	lete	□ Other	
Final Abandonment Notice	Change Plans	□ Plu	g and Abandon	☐ Tempora	arily Abandon		
<b>'</b> /	Convert to Injection	□ Plu	ig Back	☐ Water Disposal			
Proposed Recompletion Procedure-Stage 1 Point Look 1. MIRU service rig on well. 2. Pull tbg out of hole & stand 3. MIRU elec line. RU EL, RIH 4. Run Csd Hole Gamma Ray 5. Set a 4-1/2" 8K composite to 6. NU frac stack (4-1/16" 5M) and csg to 3400 psi.	out 5200'-5500' (Interval = back. H w/3.927" gauge ring to 5 Cmt Bond Log f/5600' to oridge plug directly above with a tree saver. Test fra	300') 600'. TOC or 400	0'.		RCVD MA DIL CON		
<ol> <li>Prep frac tanks w/water for the stimulation job.</li> <li>Perf the "Point Lookout" sand as follows w/3-1/8" csg gun, 120 degree</li> </ol>					DIS	000 F-0	
14. Thereby certify that the foregoing is  Com  Name (Printed/Typed) BRIDGET	Electronic Submission #8 For ENER VEST ( nmitted to AFMSS for proce	OPERATING	LLC, sent to th EVE MASON on	e Rio Puerco	SXM0228SE)		
					<del></del>		
Signature (Electronic St	ubmission)		Date 05/14/	/2010			
	THIS SPACE FO	R FEDERA	AL OR STATE	OFFICE US	E		
Approved By STEPHEN MASON			TitlePETROL	EUM ENGINE	ER .	Date 05/17/20i	
Conditions of approval, if any, are attached certify that the applicant holds legal or equi which would entitle the applicant to conduct	Office Rio Puerco						
Title 18 U.S.C. Section 1001 and Title 43 U.States any false, fictitious or fraudulent st	J.S.C. Section 1212, make it a cratements or representations as to	ime for any po any matter w	rson knowingly an ithin its jurisdiction	id willfully to make 1.	e to any department or a	gency of the United	

## Additional data for EC transaction #86495 that would not fit on the form

## 32. Additional remarks, continued

phasing & 2 SPF.

a) Entrance hole diameter = 0.42", Penetration = 35".

Stage 1 (All perf depths are OH Log depths) Dated: 5200'-5500' Range - specific perfs are still being selected.

9. MIRU frac co. & frac dwn 4-1/2" csg per service co. recommendation.

Procedure-Stage 2 Menefee 4800'-5200' (Interval = 400')

10. RU EL, RIH w/3.927" gauge ring to 5200'.

11. Run & set 8K composite bridge plug @ 5200'. Test bridge plug to 3400 psi.
12. Perf the "Point Lookout" sand as follows w/3-1/8" csg gun, 120 degree phasing & 2 SPF.

a) Entrance hole diameter = 0.42", Penetration = 35".

Stage 2 (All perf depths are OH Log depths) Dated: 4800'-5200' Range - specific perfs are still being selected.

13. Frac Stage 2 down 4-1/2" csg per service co. recommendation.

14. RDMO the frac equipment.

- 15. MIRU workover rig and kill well w/KCL water if necessary.

- 16. PU 2-3/8" tbg w/a mill & drill out bridge plug & clean out to TD. POOH.
  17. PU 2-3/8" tbg w/SN & wash out & clean out to TD if necessary.
  18. Set tbg 50' f/the btm perfs and NU tree.
  19. Swab well in & begin flowback at +/- 30 BPH, adjust rate to keep the well from dying.
- a) If well dies, continue to swab until well kicks off.

20. RDWO rig and turn well to production.

Commingle application will be approved before commingle ops begin.