## UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SEP 3 0 2010

		Farmington Field Office
Sundry Notices and	Reports on Wells	อิureau of Land Manageme
	123ª D	5. Lease Number NM-02861
I. Type of Well GAS	RECEIVED	び) 6. If Indian, All. or Tribe Name
. Name of Operator BURLINGTON	OIL & GAS COMPANY LP	.3 5 7. Unit Agreement Name
	OIL & GAS COMPANY LP	96'
3. Address & Phone No. of Operator		
PO Box 4289, Farmington, NM 87499 (505) 326-9700		9. API Well No.
4. Location of Well, Footag	ge, Sec., T, R, M	30-045-20363
Unit O (SWSE), 1180' F	10. Field and Pool Basin Dakota	
		11. County and State Rio Arriba, NM
	E BOX TO INDICATE NATURE OF NOTICE, REF	PORT, OTHER DATA
Type of Submission  X Notice of Intent	Type of Action  Abandonment  Change of Plan	
Subsequent Report	Recompletion New Construct Plugging Non-Routine F Casing Repair Water Shut off	Fracturing
Final Abandonment	t Altering Casing Conversion to	Injection
13. Describe Proposed or Co Burlington Resources requests schematic.	permission to Temporary Abandon the subject well per	the attached procedure and current wellbor
Notify NMOCD 24 hrs prior to beginning operations	Must Comply with NMOCD Rules 19.15.25.12, 19.15.25.13 and 19.15.25.14	
4. I hereby certify that the	foregoing is true and correct.	
Signed Gotal Ta	Torystal Tafoya Title: Sta	off Regulatory Technician Date 9/30/
	ned: Stephen MasonTitle	Date OCT 0 1 2010
	, if any:  any person knowingly and willfully to make any department or agency of statements or representations as to any matter within its jurisdiction.	



## ConocoPhillips LODEWICK 11 Expense - TA

Lat 36° 32' 31.272" N

Long 107° 49' 33.996" W

## **PROCEDURE**

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2. MIRU work over rig. Check casing, tubing, and bradenhead pressures and record them in Wellview.
- 3. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with 2% KCl, if necessary.
- 4. ND wellhead and NU BOPE.
- 5. TOOH with tubing (details below).

Number	Description
206	2-3/8" Tubing joint s

Use Tuboscope Unit to inspect tubing and record findings in Wellview. Make note of corrosion or scale. LD and replace any bad joints. If needed, contact Rig Superintendent or engineer for acid, volume, concentration, and displacement volume.

- 6. RIH and drill out the Cement Retainer @ 5464'. Tag for fill. If fill is tagged, record it. No cleaning out needed, if fill is less than 6528'. If fill is nore than 6528' notify engineer for further instructions.
- 7. Rig up wireline unit to set the CBP 50' above top perforations at 6528'. MIT casing and pressure up to 560 psi for 30 min on 2 hour chart. If the test passes, RIH with tubing and circulate packer fluid and POOH and lay down tubing. MOL. If MIT fail, set the packer and test CBP. If the CBP test passes, MOL, if does not, reset CBP and repeat casing MIT.

