Submit I Copy To Appropriate District Office		ew Mexico nd Natural Resources	Form C-103 October 13, 2009
<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II			WELL API NO. 30-031-20853
1301 W. Grand Ave., Artesia, NM 88210 District III		ATION DIVISION	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410		St. Francis Dr.	STATE FEE X
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe,	NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOT (DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLI PROPOSALS.)		N OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name Santa Fe Railroad
1. Type of Well: Oil Well	Gas Well Other: Injec	ction Well	8. Well Number 51
2. Name of Operator			9. OGRID Number
Nacogdoches Oil & Gas Inc. 3. Address of Operator			256689
PO Box 23418 Nacogdoches TX.	75963		10. Pool name or Wildcat Hospah
4. Well Location Unit Letter B	550 : _660' _ feet from the _No	1485 orth line and 1987	feet from the East line
Section 7	Township 17N		NMPM McKinley County
		her DR, RKB, RT, GR, etc.	
. 12 Charle	Annuaniata Day ta Indi	eata Natura of Nation	Donart or Other Date
	Appropriate Box to Indi	cate Nature of Notice,	Report or Other Data
NOTICE OF IN PERFORM REMEDIAL WORK TEMPORARILY ABANDON PULL OR ALTER CASING DOWNHOLE COMMINGLE	CHANGE PLANS [SUB REMEDIAL WOR COMMENCE DRI CASING/CEMEN	ILLING OPNS. P AND A XX
OTHER:		☐ OTHER:	
13. Describe proposed or comp	oleted operations. (Clearly st	ate all pertinent details, an	d give pertinent dates, including estimated date
13. Describe proposed or compof starting any proposed we	ork). SEE RULE 19.15.7.14	ate all pertinent details, an	d give pertinent dates, including estimated dat mpletions: Attach wellbore diagram of
13. Describe proposed or comp of starting any proposed we proposed completion or rec	ork). SEE RULE 19.15.7.14 completion.	ate all pertinent details, and NMAC. For Multiple Con	mpletions: Attach wellbore diagram of
13. Describe proposed or composed we proposed completion or recomposed Santa Fe Railroad	ork). SEE RULE 19.15.7.14 completion. 1 #51 was plugged on 12	ate all pertinent details, and NMAC. For Multiple Con 2-10-10 using the follo	mpletions: Attach wellbore diagram of owing procedure:
13. Describe proposed or composed of starting any proposed we proposed completion or reconstruction of the Santa Fe Railroad 12-7-10-RIH with 2 3/	ork). SEE RULE 19.15.7.14 completion. 1 #51 was plugged on 12 8", 4.7 lb, J55 work stri	ate all pertinent details, and NMAC. For Multiple Con 2-10-10 using the follong to 1580'. Mix & pu	wing procedure: ump 30 sks of Portland @15.6 ppg,
13. Describe proposed or composed starting any proposed we proposed completion or recarging Santa Fe Railroad 12-7-10-RIH with 2 3/flush with 4 bw. POOI	ork). SEE RULE 19.15.7.14 completion. 1 #51 was plugged on 12 8", 4.7 lb, J55 work strictly. H, LD. Allow cement to	nate all pertinent details, and NMAC. For Multiple Con 2-10-10 using the follong to 1580'. Mix & pure setup overnight. With	wing procedure: ump 30 sks of Portland @15.6 ppg, essed by OCD.
13. Describe proposed or composed starting any proposed we proposed completion or reconstruction of the Santa Fe Railroad 12-7-10-RIH with 2 3/flush with 4 bw. POOI 12-8-10-RIH with wor	ork). SEE RULE 19.15.7.14 completion. 1 #51 was plugged on 12 8", 4.7 lb, J55 work strictly. H, LD. Allow cement to k string, tag TOC @ 114	ate all pertinent details, and NMAC. For Multiple Con 2-10-10 using the follong to 1580'. Mix & pure setup overnight. With 40'. Pull work string u	wing procedure: ump 30 sks of Portland @15.6 ppg,
13. Describe proposed or composed starting any proposed we proposed completion or recarging the Santa Fe Railroad 12-7-10-RIH with 2 3/flush with 4 bw. POOI 12-8-10-RIH with wor ppg. Pull up hole to 15 12-10-10- RIH with w	ork). SEE RULE 19.15.7.14 completion. 1 #51 was plugged on 12 8", 4.7 lb, J55 work strictly. Allow cement to k string, tag TOC @ 11-8'. Mix & pump 30 sks. ork string, found TOC @ 10-10 work string, found TOC @ 11-10 work string.	ate all pertinent details, and NMAC. For Multiple Con 2-10-10 using the follong to 1580'. Mix & pure setup overnight. With 40'. Pull work string ure, Portland @ 15.6 ppg.	wing procedure: Imp 30 sks of Portland @15.6 ppg, Lessed by OCD. Ip to 601'. Mix & pump 46 sks, 15.6
13. Describe proposed or composed starting any proposed we proposed completion or reconstruction of the Santa Fe Railroad 12-7-10-RIH with 2 3/flush with 4 bw. POOI 12-8-10-RIH with worppg. Pull up hole to 15 12-10-10- RIH with we to surface. Cement stal	ork). SEE RULE 19.15.7.14 completion. 1 #51 was plugged on 12 8", 4.7 lb, J55 work strictly. Allow cement to k string, tag TOC @ 116 8'. Mix & pump 30 sks. ork string, found TOC @ pilized at 8'.	ate all pertinent details, and NMAC. For Multiple Con 2-10-10 using the follong to 1580'. Mix & pure setup overnight. With 40'. Pull work string up, Portland @ 15.6 ppg, 20170'. Mix & pump 1	wing procedure: ump 30 sks of Portland @15.6 ppg, essed by OCD. up to 601'. Mix & pump 46 sks, 15.6 pOOH, LD. Allow to setup overnight
13. Describe proposed or composed starting any proposed we proposed completion or recarged The Santa Fe Railroad 12-7-10-RIH with 2 3/flush with 4 bw. POOI 12-8-10-RIH with wor ppg. Pull up hole to 15 12-10-10- RIH with we to surface. Cement stall 12-11-10- Mix 1 sk by	ork). SEE RULE 19.15.7.14 completion. 1 #51 was plugged on 12 8", 4.7 lb, J55 work strictly. Allow cement to k string, tag TOC @ 11-8'. Mix & pump 30 sks. ork string, found TOC @ 11-2 to the string of the string of the string. TOC @ 11-2 to the string of the string.	ate all pertinent details, and NMAC. For Multiple Con 2-10-10 using the follong to 1580'. Mix & pursetup overnight. With 40'. Pull work string up, Portland @ 15.6 ppg, 20 170'. Mix & pump 100.	mpletions: Attach wellbore diagram of wing procedure: amp 30 sks of Portland @15.6 ppg, essed by OCD. up to 601'. Mix & pump 46 sks, 15.6 p POOH, LD. Allow to setup overnight 17 sks of 15.9 ppg Portland. Filled well
13. Describe proposed or composed starting any proposed we proposed completion or recarged The Santa Fe Railroad 12-7-10-RIH with 2 3/flush with 4 bw. POOI 12-8-10-RIH with wor ppg. Pull up hole to 15 12-10-10- RIH with w to surface. Cement stal 12-11-10- Mix 1 sk by 12-12-10- Cement stal	ork). SEE RULE 19.15.7.14 completion. 1 #51 was plugged on 12 8", 4.7 lb, J55 work strictly. Allow cement to k string, tag TOC @ 11-8'. Mix & pump 30 sks. ork string, found TOC @ tilized at 8'. hand, fill well to surface bilized at surface. MI, No.	ate all pertinent details, and NMAC. For Multiple Con 2-10-10 using the following to 1580'. Mix & pure setup overnight. With 40'. Pull work string up, Portland @ 15.6 ppg. 20 170'. Mix & pump 10 te. OG welder, cut casing	mpletions: Attach wellbore diagram of wing procedure: amp 30 sks of Portland @15.6 ppg, essed by OCD. up to 601'. Mix & pump 46 sks, 15.6 p POOH, LD. Allow to setup overnight 17 sks of 15.9 ppg Portland. Filled well
13. Describe proposed or composed starting any proposed we proposed completion or recarged The Santa Fe Railroad 12-7-10-RIH with 2 3/flush with 4 bw. POOI 12-8-10-RIH with wor ppg. Pull up hole to 15 12-10-10- RIH with w to surface. Cement stal 12-11-10- Mix 1 sk by 12-12-10- Cement stal	ork). SEE RULE 19.15.7.14 completion. 1 #51 was plugged on 12 8", 4.7 lb, J55 work strict. A, LD. Allow cement to k string, tag TOC @ 11-8'. Mix & pump 30 sks ork string, found TOC @ 11-2 collized at 8'. hand, fill well to surface bilized at surface. MI, Next well information.	ate all pertinent details, and NMAC. For Multiple Con 2-10-10 using the following to 1580'. Mix & pursetup overnight. With 40'. Pull work string ure, Portland @ 15.6 ppg. 20 170'. Mix & pump 10 te. OG welder, cut casing ormation. Level location	mpletions: Attach wellbore diagram of wing procedure: amp 30 sks of Portland @15.6 ppg, essed by OCD. up to 601'. Mix & pump 46 sks, 15.6 p POOH, LD. Allow to setup overnight 17 sks of 15.9 ppg Portland. Filled well
13. Describe proposed or composed starting any proposed we proposed completion or recarged The Santa Fe Railroad 12-7-10-RIH with 2 3/flush with 4 bw. POOI 12-8-10-RIH with wor ppg. Pull up hole to 15 12-10-10- RIH with w to surface. Cement stal 12-11-10- Mix 1 sk by 12-12-10- Cement stal	ork). SEE RULE 19.15.7.14 completion. 1 #51 was plugged on 12 8", 4.7 lb, J55 work strict. A, LD. Allow cement to k string, tag TOC @ 11-8'. Mix & pump 30 sks ork string, found TOC @ 11-10 collized at 8'. hand, fill well to surface bilized at surface. MI, Nex A marker with well information of the surface of the surfac	ate all pertinent details, and NMAC. For Multiple Con 2-10-10 using the follong to 1580'. Mix & pure setup overnight. With 40'. Pull work string up, Portland @ 15.6 ppg, 20 170'. Mix & pump 10 ee. OG welder, cut casing ormation. Level locations are only.	mpletions: Attach wellbore diagram of wing procedure: amp 30 sks of Portland @15.6 ppg, essed by OCD. up to 601'. Mix & pump 46 sks, 15.6 p POOH, LD. Allow to setup overnight 17 sks of 15.9 ppg Portland. Filled well
13. Describe proposed or composed starting any proposed we proposed completion or recarged The Santa Fe Railroad 12-7-10-RIH with 2 3/flush with 4 bw. POOI 12-8-10-RIH with wor ppg. Pull up hole to 15 12-10-10- RIH with w to surface. Cement stal 12-11-10- Mix 1 sk by 12-12-10- Cement stal	ork). SEE RULE 19.15.7.14 completion. 1 #51 was plugged on 12 8", 4.7 lb, J55 work strict. A. LD. Allow cement to k string, tag TOC @ 11-8'. Mix & pump 30 sks. ork string, found TOC @ 11-2 collized at 8'. hand, fill well to surface bilized at surface. MI, Next A marker with well information of C-103 (Subsequent Receipt of C-103 (Su	ate all pertinent details, and NMAC. For Multiple Con 2-10-10 using the follong to 1580'. Mix & pure setup overnight. With 40'. Pull work string up, Portland @ 15.6 ppg, @ 170'. Mix & pump 10 ee. OG welder, cut casing ormation. Level locations re only. Rending export of Well	mpletions: Attach wellbore diagram of wing procedure: amp 30 sks of Portland @15.6 ppg, essed by OCD. up to 601'. Mix & pump 46 sks, 15.6 p POOH, LD. Allow to setup overnight 17 sks of 15.9 ppg Portland. Filled well
13. Describe proposed or composed starting any proposed we proposed completion or recarries and the Santa Fe Railroad 12-7-10-RIH with 2 3/flush with 4 bw. POOI 12-8-10-RIH with wor ppg. Pull up hole to 15 12-10-10- RIH with we to surface. Cement stall 12-11-10- Mix 1 sk by 12-12-10- Cement stall 12-13-10- Weld on P&	ork). SEE RULE 19.15.7.14 completion. 1 #51 was plugged on 12 8", 4.7 lb, J55 work strict. A, LD. Allow cement to k string, tag TOC @ 11-8'. Mix & pump 30 sks. ork string, found TOC @ 11-12 collized at 8'. hand, fill well to surface bilized at surface. MI, Next A marker with well informance of C-103 (Subsequent Re Plugging) which may be found @ under forms.	ate all pertinent details, and NMAC. For Multiple Con 2-10-10 using the follong to 1580'. Mix & pure setup overnight. With 40'. Pull work string up, Portland @ 15.6 ppg, @ 170'. Mix & pump 10 ee. OG welder, cut casing ormation. Level locations re only. Rending export of Well	mpletions: Attach wellbore diagram of wing procedure: amp 30 sks of Portland @15.6 ppg, essed by OCD. up to 601'. Mix & pump 46 sks, 15.6 p POOH, LD. Allow to setup overnight 17 sks of 15.9 ppg Portland. Filled well
13. Describe proposed or composed starting any proposed we proposed completion or recarged to the Santa Fe Railroad 12-7-10-RIH with 2 3/flush with 4 bw. POOI 12-8-10-RIH with wor ppg. Pull up hole to 15 12-10-10- RIH with we to surface. Cement stal 12-11-10- Mix 1 sk by 12-12-10- Cement stal 12-13-10- Weld on P& Spud Date:	ork). SEE RULE 19.15.7.14 completion. 1 #51 was plugged on 12 8", 4.7 lb, J55 work strictly. LD. Allow cement to k string, tag TOC @ 11- 8'. Mix & pump 30 sks. ork string, found TOC @ 11- 8'. Mix & pump 30 sks. ork string, found TOC @ 11- bilized at 8'. hand, fill well to surface oilized at surface. MI, No. A marker with well informarker with well informarker of C-103 (Subsequent Re Plugging) which may be found @ under forms. www.emrd.state.us/ocd	ate all pertinent details, and NMAC. For Multiple Con 2-10-10 using the follong to 1580'. Mix & pure setup overnight. With 40'. Pull work string up, Portland @ 15.6 ppg, 20 170'. Mix & pump 10 ee. OG welder, cut casing ormation. Level locations to only. Sending export of Well occions were page.	wing procedure: Imp 30 sks of Portland @15.6 ppg, Tessed by OCD. Ip to 601'. Mix & pump 46 sks, 15.6 The POOH, LD. Allow to setup overnight To sks of 15.9 ppg Portland. Filled well To sks of 15.9 well plate over stubs. The Pool of the
13. Describe proposed or composed starting any proposed we proposed completion or recarries and the Santa Fe Railroad 12-7-10-RIH with 2 3/flush with 4 bw. POOI 12-8-10-RIH with wor ppg. Pull up hole to 15 12-10-10- RIH with we to surface. Cement stall 12-11-10- Mix 1 sk by 12-12-10- Cement stall 12-13-10- Weld on P&	ork). SEE RULE 19.15.7.14 completion. 1 #51 was plugged on 12 8", 4.7 lb, J55 work strictly. LD. Allow cement to k string, tag TOC @ 11- 8'. Mix & pump 30 sks. ork string, found TOC @ 11- 8'. Mix & pump 30 sks. ork string, found TOC @ 11- bilized at 8'. hand, fill well to surface oilized at surface. MI, No. A marker with well informarker with well informarker of C-103 (Subsequent Re Plugging) which may be found @ under forms. www.emrd.state.us/ocd	ate all pertinent details, and NMAC. For Multiple Con 2-10-10 using the follong to 1580'. Mix & pure setup overnight. With 40'. Pull work string up, Portland @ 15.6 ppg, 20 170'. Mix & pump 10 ee. OG welder, cut casing ormation. Level locations to only. Sending export of Well occions were page.	wing procedure: Imp 30 sks of Portland @15.6 ppg, Tessed by OCD. Ip to 601'. Mix & pump 46 sks, 15.6 The POOH, LD. Allow to setup overnight To sks of 15.9 ppg Portland. Filled wells of the state of th
13. Describe proposed or composed starting any proposed we proposed completion or recarge The Santa Fe Railroad 12-7-10-RIH with 2 3/flush with 4 bw. POOI 12-8-10-RIH with wor ppg. Pull up hole to 15 12-10-10- RIH with w to surface. Cement stal 12-11-10- Mix 1 sk by 12-12-10- Cement stal 12-13-10- Weld on P& Spud Date:	ork). SEE RULE 19.15.7.14 completion. 1 #51 was plugged on 12 8", 4.7 lb, J55 work strictly. LD. Allow cement to k string, tag TOC @ 11- 8'. Mix & pump 30 sks. ork string, found TOC @ 11- 8'. Mix & pump 30 sks. ork string, found TOC @ 11- bilized at 8'. hand, fill well to surface oilized at surface. MI, No. A marker with well informarker with well informarker of C-103 (Subsequent Re Plugging) which may be found @ under forms. www.emrd.state.us/ocd	ate all pertinent details, and NMAC. For Multiple Con 2-10-10 using the follong to 1580'. Mix & pure setup overnight. With 40'. Pull work string up, Portland @ 15.6 ppg, 20 170'. Mix & pump 10 ee. OG welder, cut casing ormation. Level locations to only. Sending export of Well occions were page.	e and belieft. Attach wellbore diagram of the wing procedure: Imp 30 sks of Portland @15.6 ppg, and a sks of Portland @15.6 ppg, and a sks, a
13. Describe proposed or composed starting any proposed we proposed completion or recarged to the Santa Fe Railroad 12-7-10-RIH with 2 3/flush with 4 bw. POOI 12-8-10-RIH with wor ppg. Pull up hole to 15 12-10-10- RIH with we to surface. Cement stal 12-11-10- Mix 1 sk by 12-12-10- Cement stal 12-13-10- Weld on P& Spud Date:	ork). SEE RULE 19.15.7.14 completion. 1 #51 was plugged on 12 8", 4.7 lb, J55 work strict. LD. Allow cement to k string, tag TOC @ 11-8'. Mix & pump 30 sks. ork string, found TOC @ 11-10 collized at 8'. hand, fill well to surface oilized at surface. MI, New Amarker with well information of C-103 (Subsequent Replugging) which may be found @ under forms. www.emrd.state.us/ocd above is true and complete to	ate all pertinent details, and NMAC. For Multiple Con 2-10-10 using the follong to 1580'. Mix & pure setup overnight. With 40'. Pull work string up, Portland @ 15.6 ppg, 20 170'. Mix & pump 10 ee. OG welder, cut casing ormation. Level locations to only. Sending export of Well occions were page.	wing procedure: Imp 30 sks of Portland @15.6 ppg, Tessed by OCD. Ip to 601'. Mix & pump 46 sks, 15.6 The POOH, LD. Allow to setup overnight To sks of 15.9 ppg Portland. Filled well To sks of 15.9 well plate over stubs. The Pool of the
13. Describe proposed or composed starting any proposed we proposed completion or recarged the Santa Fe Railroad 12-7-10-RIH with 2 3/flush with 4 bw. POOI 12-8-10-RIH with wor ppg. Pull up hole to 15 12-10-10- RIH with we to surface. Cement stall 12-11-10- Mix 1 sk by 12-12-10- Cement stall 12-13-10- Weld on P& Spud Date: I hereby certify that the information SIGNATURE Mike Allen	ork). SEE RULE 19.15.7.14 completion. 1 #51 was plugged on 12 8", 4.7 lb, J55 work strict. A, LD. Allow cement to k string, tag TOC @ 11-8'. Mix & pump 30 sks. ork string, found TOC @ 11-8'. Mix & pump 30 sks. ork string, found TOC @ 11-8'. hand, fill well to surface oilized at 8'. hand, fill well to surface oilized at surface. MI, Nex A marker with well information of C-103 (Subsequent Replugging) which may be found @ under forms. www.emrd.state.us/ocd above is true and complete to TITLE	nate all pertinent details, and NMAC. For Multiple Con 2-10-10 using the following to 1580'. Mix & pure setup overnight. With 40'. Pull work string up, Portland @ 15.6 ppg, 20 170'. Mix & pump 10 ee. OG welder, cut casing ormation. Level locations are only. Seending export of Well of OCD web page.	mpletions: Attach wellbore diagram of wing procedure: amp 30 sks of Portland @15.6 ppg, essed by OCD. up to 601'. Mix & pump 46 sks, 15.6, POOH, LD. Allow to setup overnight 17 sks of 15.9 ppg Portland. Filled wells of at 5'. Weld plate over stubs. on.
13. Describe proposed or composed starting any proposed we proposed completion or recarged Santa Fe Railroad 12-7-10-RIH with 2 3/flush with 4 bw. POOI 12-8-10-RIH with wor ppg. Pull up hole to 15 12-10-10- RIH with we to surface. Cement stal 12-11-10- Mix 1 sk by 12-12-10- Cement stal 12-13-10- Weld on P& Spud Date:	ork). SEE RULE 19.15.7.14 completion. 1 #51 was plugged on 12 8", 4.7 lb, J55 work strictly. LD. Allow cement to k string, tag TOC @ 11- 8'. Mix & pump 30 sks. ork string, found TOC @ 11- bilized at 8'. hand, fill well to surface oilized at surface. MI, Next A marker with well information of C-103 (Subsequent Replugging) which may be found @ under forms. www.emnrd.state.us/ocd above is true and complete the comp	nate all pertinent details, and NMAC. For Multiple Con 2-10-10 using the following to 1580'. Mix & pure setup overnight. With 40'. Pull work string up, Portland @ 15.6 ppg. 20 170'. Mix & pump 10 ee. OG welder, cut casing cormation. Level locations are only. See the best of my knowledge of the best of my knowledge of the best of my knowledge with the oct of the best of my knowledge with the oct of my knowledge with the	mpletions: Attach wellbore diagram of awing procedure: Imp 30 sks of Portland @15.6 ppg, lessed by OCD. Ip to 601'. Mix & pump 46 sks, 15.6, POOH, LD. Allow to setup overnight 17 sks of 15.9 ppg Portland. Filled wells of at 5'. Weld plate over stubs. In special com PHONE:
13. Describe proposed or composed starting any proposed we proposed completion or recarged the Santa Fe Railroad 12-7-10-RIH with 2 3/flush with 4 bw. POOI 12-8-10-RIH with wor ppg. Pull up hole to 15 12-10-10- RIH with we to surface. Cement stall 12-11-10- Mix 1 sk by 12-12-10- Cement stall 12-13-10- Weld on P& Spud Date: I hereby certify that the information SIGNATURE Mike Allen	ork). SEE RULE 19.15.7.14 completion. 1 #51 was plugged on 12 8", 4.7 lb, J55 work stript. LD. Allow cement to k string, tag TOC @ 11-8'. Mix & pump 30 sks. ork string, found TOC @ 11-8'. Mix & pump 30 sks. ork string, found TOC @ 11-8'. hand, fill well to surface oilized at 8'. hand, fill well to surface oilized at surface. MI, Next A marker with well information of C-103 (Subsequent Re Plugging) which may be found @ under forms. www.emnrd.state.us/ocd above is true and complete to TITLE E-mail add TITLE	nate all pertinent details, and NMAC. For Multiple Con 2-10-10 using the following to 1580'. Mix & pure setup overnight. With 40'. Pull work string ure, Portland @ 15.6 ppg. 20 170'. Mix & pump 10 te. OG welder, cut casing ormation. Level locations are only. Sending export of Well occidence of the best of my knowledge. Other web page	mpletions: Attach wellbore diagram of wing procedure: amp 30 sks of Portland @15.6 ppg, essed by OCD. up to 601'. Mix & pump 46 sks, 15.6, POOH, LD. Allow to setup overnight 17 sks of 15.9 ppg Portland. Filled wells of at 5'. Weld plate over stubs. on. DATE 12-13-2010-7.9 DATE 12-13-2010-7.9 DATE 12-13-2010-7.9 Inspector, PHONE: (936)260-7620