submitted in lieu of Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

JAN 14 2011

Farmington Field Office Bureau of Land Management

Sundry Notices and Reports on Wells			
·			case Number F-0794 9 3
Type of Well GAS		6. If	Indian, All. or ribe Name
. Name of Operator			nit Agreement Name nn Juan 27-5 Unit
BURLINGTON RESCURCES OIL & GAS COMPANY LP			
. Address & Phone No. of Operator			'ell Name & Number an Juan 27-5 Unit 28
PO Box 4289, Farmington, NM 87499 (505) 326-9700		9. A	PI Well No.
Franking SWall Franks Co. T. D. M.		30	-039-06859
4. Location of Well, Footage, Sec., T, R, M Unit M (SWSW), 800' FSL & 800' FWL, Section 25, T27N, R5W, NMPM			eld and Pool anco MV / Tapacito PC
	,	11. C	ounty and State io Arriba, NM
2. CHECK APPROPRIATE BOX TO INDICATE NATURE OF N Type of Submission Type of Action			
X Notice of Intent Abandonment Recompletion Subsequent Report Plugging	Change of Plans New Construction Non-Routine Fracturing	X Othe	er – <u>Commingle</u>
Casing Repair Final Abandonment Altering Casing	Water Shut off Conversion to Injection		
3. Describe Proposed or Completed Operations Surlington Resources requests permission to remove the packer and convell per the attached procedure and current wellbore schematic. The DF		approval.	Tapacito Pictured Cliffs D JAN 21 '11 CONS. DIV. DIST. 3
4. I hereby certify that the foregoing is true and correct. igned	Title: Staff Regula	tory Technic	cian Date 114120
This space for Federal or State Office use) APPROVED BY Original Signed: Stephen Mason Title	·	Dat	e JAN 1 8 2011
CONDITION OF APPROVAL, if any: itle 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency be United States any false, lictitious or fraudulent statements or representations as to any matter within its jurisdiction.	<i>y</i> of .		

ConocoPhillips SAN JUAN 27-5 UNIT 28

Rig Uplift - Commingles

Lat 36° 32' 19.968" N

Long 107° 18' 54.828" W

PROCEDURE

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig. Check for obstruction in the tubing with slickline and locking 3 slip stop if necessary.
- 2. MIRU work over rig. Check casing, tubing, and bradenhead pressures and record them in Wellview.
- 3. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with 2% KCl, if necessary.
- 4, ND WH. NU BOPE. Remove tubings.
- 5, TOOH and lay down 1-1/4" tubing.

Number	Description
83	1-1/4" Tubing joint
1	1-1/4" perforated joint
14	1-1/4" Tubing joint
1	1-1/4" perforated joint
14	1-1/4" Tubing joint
1	1-1/4" perforated joint
1	1-1/4" Tubing joint

6. Change over to 2-3/8" handling tools. Unseat donut. Pickup and unseating packer by turning to the left. TOOH and inspect tubings and laydown packer. Use Tuboscope Unit to inspect tubing and record findings in Wellview. Make note of corrosion, scale, or paraffin and save a sample to give to the engineer for further analysis. LD and replace any bad joints. If needed, contact Rig Superintendent or engineer for acid, volume, concentration, and displacement volume.

Number	Description
116	2-3/8" Tubing joint
1	Guiberson Packer
65	2-3/8" tubing joints
1	Seat Nipple
1	2-3/8" Perf Joint
1	Bull Plug

- 7. TIH with tubing and cleanout to PBTD. Depending on how badly the tubing scale up, it is possible to use a scasing scraper.
- 8. TIH with tubing using Tubing Drift Procedure. (detail below).

Recommended	
Tubing Drift ID:	1.9
Land Tubing At:	5631'
Land F-Nipple At:	5630'

Number	Description
1	Expendable check
1	2-3/8" F Nipple
1	2-3/8" tubing joints (32')
1	2-3/8" pup joint
181	2-3/8" tubing joints
~X	2-3/8" pup joint (4.1')

9. If there is an air package on location, skip to the next step. Run standing valve on shear tool, load tubing, and pressure test to 500#. Monitor pressure for 15 mins, and make a swab run to remove the fluid from the tubing. Retrieve standing valve.

10. ND BOPE, NU Wellhead. Pressure test tubing slowly with an air package as follows: pump 3 bbls pad, drop steel ball, pressure tubing up to 500 psi, and bypass air. Monitor pressure for 15 mins., then complete the operation by pumping off the expendable check. Note in Wellview the pressure in which the check pumped off. Notify the MSO that the well is ready to be turned over to Production Operations. Make swab run to kick-off the well, if necessary, then RDMO.

Tubing Drift Check

Procedure

- 1. Set flow control in tubing. With air, on location, use expendable check. With no air on location, use wire line plug.
- 2. RU drift tool to a minimum 70' line. Drift tool will have an OD of at least the API drift specification of 1.901" for the 2 3/8",4.7# tubing, and will be at least 15" long. The tool will not weigh more than 10# and will have an ID bore the length of the tool, so fluids may be pumped through the tool if it becomes stuck.
- 3. Drop the tool into the tubing string and retrieve it after every 2 joints of tubing ran in hole. If any resistance to the tool movement is noticed, going in or out, that joint will be replaced.
- 4. In order to stimulate the plunger lift operation, all equipment must be kept clean and free of debris.

The drift tool should be measured with calipers before each job, to ensure the OD is the correct size for the tubing being checked. The maximum allowable wear of the tool is .003".



