submitted in lieu of Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT



JAN 1 4 2011

	Sundry Notices and Reports on Wetls		i ci continantina	r Field Oto
		5.	Lease SF-079	Number 514
I.	Type of Well GAS	6.	If India	an, All. or Name
2.	Name of Operator BURLINGTON	7.		greement Name an 29-7 Unit
	RESOURCES OIL & GAS COMPANY LP			
3.	Address & Phone No. of Operator	8.		ame & Number an 29-7 Unit 4A
	PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.	API W	ell No.
	Logation of Well Footogs Con T D M		30-039	-25574
4.	Location of Well, Footage, Sec., T, R, M Unit E (SWNW), 1980' FNL & 595' FWL, Section 10, T29N, R7W, NMPM			nd Pool a PC / Blanco MV
		11.		y and State riba, NM
12	CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OT	HER	DATA	
	Type of Submission Type of Action X Notice of Intent Abandonment Change of Plans		Other -	Commingle
	Recompletion New Construction Subsequent Report Plugging Non-Routine Fracturing		-	
	Casing Repair Water Shut off			
	Final Abandonment Altering Casing Conversion to Injection			
13.	Describe Proposed or Completed Operations			
	rlington Resources requests permission to remove the packer and commingle the dual La Jara II per the attached procedure and current wellbore schematic. The DHC will be submitted for			Blanco Mesaverde
	Au 2021AZ ic Resinder		RCUD	FEB 28'11
	DHC3526AZ is Rescribed 5-bait C107 to SANXA fe LOR DHC	1010.	/n#	roms DIV.
14	I hereby certify that the foregoing is true and correct.	† Y 7,40		,
17.	212-1			DIST. 3
Sig	ned	ory Te	chnician	Date 1/3/11
ÀΡ	nis space for Federal or State Office use) PROVED BY Fight M W Title		Date	JAN 1 8 2011
Title	NDITION OF APPROVAL, if any: 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make any department or agency of inited States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.			

NWOCD OPERATOR

ConocoPhillips SAN JUAN 29-7 UNIT 4A

Rig Uplift - Commingles

Lat 36° 44' 31.164" N

Long 107° 33' 52.848" W

PROCEDURE

- 1. Hold pre-job safety meeting. Comply with all NMOCD, BLM, and COPC safety and environmental regulations. Test rig anchors prior to moving in rig.
- 2. MIRU work over rig. Check casing, tubing, and bradenhead pressures and record them in Wellview.
- 3. RU blow lines from casing valves and begin blowing down casing pressure. Kill well with 2% KCl, if necessary,
- 4. ND wellhead and NU BOPE and Offset Spool. PU and remove tubing hanger, adding additional joints as needed (tubing currently landed @ 3180' & 5501", PBTD @ 5650').
- 5. TOOH with Short string of tubing (details below),

Number	Description			
100	2-3/8" Tubing joints			
1	2-3/8" Profile Nipple			
1	2-3/8" Mule shoe guide			

5a. Release packer and TOOH with long string of tubing (details below).

Number	Description	
111	2-3/8" Tubing joint	
1	FH Hyflo Packer	
63	2-3/8" tubing joints	
1	2-3/8" Profile nipple	
1	2-3/8" tubing joint	
1	2-3/8" Mule shoe guide	

Use Tuboscope Unit to inspect tubing and record findings in Wellview. Make note of corrosion, scale, or paraffin and save a sample to give to the engineer for further analysis. LD and replace any bad joints. If needed, contact Rig Superintendent or engineer for acid, volume, concentration, and displacement volume.

6. If fill is tagged, PU bailer and CO to PBTD (5650'), If fill is too hard or too much to bail, utilize the air package.

Save a sample of the fill and contact engineer for further analysis. TOOH, LD tubing bailer (if applicable). If fill could not be CO to PBTD, please call Production Engineer to inform how much fill was left and confirm/adjust landing depth.

7. TIH with tubing using Tubing Drift Procedure. (detail below).

Recommended Tubing Drift ID: 1.901" Land Tubing At: 5470' Land F-Nipple At: 5440'

Number	Description
1	1-1/2" Mule shoe guide
1	2-3/8" x 1-1/2" Crossover
1	2-3/8" tubing joint
1	2-3/8" F nipple (ID 1.78")
180	2-3/8" tubing joints
X	2-3/8" pup joint (as needed)
1	2-3/8" Tubing joint
	[",

- 8. If there is an air package on location, skip to the next step. Run standing valve on shear tool, load tubing, and pressure test to 500#. Monitor pressure for 15 mins, and make a swab run to remove the fluid from the tubing. Retrieve standing valve.
- 9. ND BOPE, NU Wellhead. Pressure test tubing slowly with an air package as follows: pump 3 bbls pad, drop steel ball, pressure tubing up to 500 psi, and bypass air. Monitor pressure for 15 mins., then complete the operation by pumping off the expendable check. Note in Wellview the pressure in which the check pumped off. Notify the MSO that the well is ready to be turned over to Production Operations. Make swab run to kick-off the well, if necessary, then RDMO.

Tubing Drift Check

Procedure

- 1. Set flow control in tubing. With air, on location, use expendable check. With no air on location, use wire line plug.
- 2. RU drift tool to a minimum 70' line. Drift tool will have an OD of at least the API drift specification of 1.901" for the 2 3/8",4.7# tubing, and will be at least 15" long. The tool will not weigh more than 10# and will have an ID bore the length of the tool, so fluids may be pumped through the tool if it becomes stuck.
- 3. Drop the tool into the tubing string and retrieve it after every 2 joints of tubing ran in hole. If any resistance to the tool movement is noticed, going in or out, that joint will be replaced.
- 4. In order to stimulate the plunger lift operation, all equipment must be kept clean and free of debris.

The drift tool should be measured with calipers before each job, to ensure the OD is the correct size for the tubing being checked. The maximum allowable wear of the tool is .003".

