Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			NMSF078502 6. If Indian, Allottee	or Tribe Name
SUBMIT IN TRIE	ons on reverse side. DEC	<i>1</i> ∕\	eement, Name and/or No.	
1. Type of Well	167.	8 Well Name and No.		
Oil Well Gas Well Oth 2. Name of Operator	ABY CORNEY CO	ON. SARIWALINA		
BP AMERICA PRODUCTION	Mail: corleym\@pp.com	30-045-08202-	30-045-08202-00-S1	
3a. Address P. O. BOX 3092 HOUSTON, TX 77253	b. Phone No. (include area code Ph: 281.366.4491 x: 281.366.0700	BLANCO MESAVERDE		
4. Location of Well (Footage, Sec., T.		11. County or Parish,	and State	
Sec 13 T29N R8W SWSW 099 36.72087 N Lat, 107.63284 W		SAN JUAN CO	UNTY, NM	
12. CHECK APPR	OPRIATE BOX(ES) TO I	NDICATE NATURE OF	NOTICE, REPORT, OR OTHE	ER DATA
TYPE OF SUBMISSION	SUBMISSION TYPE OF ACTION			
• N4: 6 I44	☐ Acidize	☐ Deepen	☐ Production (Start/Resume)	☐ Water Shut-Off
Notice of Intent ■ Notice of Intent	☐ Alter Casing	☐ Fracture Treat	☐ Reclamation	■ Well Integrity
☐ Subsequent Report	□ Casing Repair	■ New Construction	□ Recomplete	⊘ Other
☐ Final Abandonment Notice	□ Change Plans	□ Plug and Abandon	□ Temporarily Abandon	Workover Operations
	□ Convert to Injection	Plug Back	■ Water Disposal	
testing has been completed. Final Ab determined that the site is ready for fi BP America Production Comp the Menefee and Lewis Shale	andonment Notices shall be filed nal inspection.) any respectfully request pe formations in the subject w	only after all requirements, includer in the second or includer in the second of the s	ompletion in a new interval, a Form 31 ing reclamation, have been completed, acture stimulate in sedure.	, and the operator has
14. I hereby certify that the foregoing is	Electronic Submission #15	5614 verified by the BLM We PRODUCTION CO, sent to the sing by Matthew Halbert on	e Farmington	
Name (Printed/Typed) MARY CORLEY			DRIZED REPRESENTATIVE	
Signature (Electronic S		Date 10/30/2		
		R FEDERAL OR STATE	OFFICE USE	
Approved By 181 Jim Lovato		Title		DAREC - 2 200
Conditions of approval, if any, are attache certify that the applicant holds legal or equivalent would entitle the applicant to conductive the applicant to conduct the applicant the applicant to conduct the applicant th				
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent				or agency of the United

Vandewart A #3 Payadd Procedure

Procedure:

- 1. Check anchors. MIRU workover rig.
- 2. Check and record tubing, casing, and bradenhead pressures.
- 3. Blow down well. Kill with 2% KCL water ONLY if necessary.
- 4. Nipple down WH. NU BOPs.
- 5. Tag for fill and tally OH with 2-3/8" production tubing currently set at 5778'.
- 6. RU WL unit. Run GR log across Menefee and Lewis Shale from 4500' 5800' to select perforations.
- 7. TIH with bit and scraper for 4-1/2" casing to 5800'.
- 8. RU WL unit. RIH with 4-1/2" CIBP. Set CIBP at 5775'.
- 9. RIH with 3-1/8" casing guns with Schlumberger's Prospector, select-fire charge. Perforate Menefee formation (correlate to GR log).

Menefee perforations, 2 spf:

To be determined

- 10. RIH with 2-7/8" frac string and 4-1/2" packer. Set packer at 5525'.
- 11. Spearhead 500 gal 15% HCL, establish injection rate, and proceed with fracture stimulation according to Schlumberger schedule.
- 12. Flowback frac immediately.
- 13. Release packer and TOH with frac string and packer. LD frac string.
- 14. RU WL unit. RIH with 4-1/2" CIBP. Set CIBP at 5225'.
- 15. Pressure test casing to 2500 psi
- 16. RIH with 3-1/8" casing guns with Schlumberger's Prospector, select-fire charge. Perforate Lewis Shale formation (correlate to GR log).

Lewis Shale perforations, 2 spf:

To be determined

- 17. RU frac equipment and install wellhead isolation tool. Use 2% KCL-N2 foam in fracture stimulation.
- 18. Spearhead 500 gal 15% HCL, establish injection rate, and proceed with fracture stimulation according to Schlumberger schedule.
- 19. Flowback frac immediately.
- 20. TIH with tubing and bit. Cleanout fill and drill bridge plugs. Cleanout fill to PBTD at 5992'. Blow well dry at PBTD.
- 21. Rabbit tubing and RIH with 2-3/8" production tubing.
- 22. Land 2-3/8" production tubing at 5900'.
- 23. ND BOP's. NU WH. Test well for air. Return well to production.

Vandewart A #3

Sec. 13 T29N R8W API#: 30-045-08202

