Submit 1 Copy To Appropriate District     Office     District I	State of New Mexico Energy, Minerals and Natural Re	Sources AMENDED Form C-October 13,
District I 1625 N. French Dr., Hobbs, NM 88240 District II		WELL API NO.
1301 W. Grand Ave., Artesia, NM 88210	OIL CONSERVATION DIVI	5 Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410	1220 South St. Francis D	STATE N FEE
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505	Santa Fe, NM 87505	6. State Oil & Gas Lease No. 38390
SUNDRY NOTIC	CES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Na
	ALS TO DRILL OR TO DEEPEN OR PLUG BAC ATION FOR PERMIT" (FORM C-101) FOR SUCI	T .
PROPOSALS.)		Pepper  8. Well Number 2
	Gas Well 🛛 Other	
2. Name of Operator McElvain Oil & Gas Properties, Inc		9. OGRID Number 22044
3. Address of Operator	-	10. Pool name or Wildcat
1050 17 <sup>th</sup> St., Suite 2500, Denver, C	O 80265	Basin Fruitland Coal
4. Well Location		
Unit Letter M_ :	_1,260 feet from the South line	e and665feet from theWestline
Section 32	Township 31 N Range 13 W	
	11. Elevation (Show whether DR, RKB,	RT, GR, etc.)
	5,635' GR	
12. Check A	ppropriate Box to Indicate Nature	of Notice, Report or Other Data
	• •	•
NOTICE OF IN	· · · · · · · · · · · · · · · · · · ·	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK		EDIAL WORK ALTERING CASING
TEMPORARILY ABANDON DULL OR ALTER CASING		MENCE DRILLING OPNS. □ P AND A NG/CEMENT JOB □
DOWNHOLE COMMINGLE	MOETIFEE COMPE	NO/OLIVILINI JOB
DOWN IOLE COMMININGLE		
OTHER:	ОТН	
OTHER:  13. Describe proposed or compl	eted operations. (Clearly state all pertiner	nt details, and give pertinent dates, including estimate
OTHER:  13. Describe proposed or compl of starting any proposed wor	eted operations. (Clearly state all pertinents). SEE RULE 19.15.7.14 NMAC. For	
OTHER:  13. Describe proposed or compl of starting any proposed wor proposed completion or reco	eted operations. (Clearly state all pertiners). SEE RULE 19.15.7.14 NMAC. For ompletion.	nt details, and give pertinent dates, including estimate Multiple Completions: Attach wellbore diagram of
OTHER:  13. Describe proposed or compl of starting any proposed wor proposed completion or reco	eted operations. (Clearly state all pertinents). SEE RULE 19.15.7.14 NMAC. For ompletion. Four Corners Testing, pressure tested Cs.	nt details, and give pertinent dates, including estimate Multiple Completions: Attach wellbore diagram of g to 3000 psi 30 minutes – held. <b>Perf Lower</b>
OTHER:  13. Describe proposed or complor of starting any proposed work proposed completion or receded 4/19/2011 MIRU Blue Jet ran CBL.  Fruitland Coal 1542'-15: 4/20/2011 MIRU BJ Services – press	eted operations. (Clearly state all pertiners). SEE RULE 19.15.7.14 NMAC. For impletion. Four Corners Testing, pressure tested Cs. 32', 4 spf, 0.43" dia, 40 shots. Set packeture test lines to 4000 psi. Acidized w 50	nt details, and give pertinent dates, including estimate Multiple Completions: Attach wellbore diagram of g to 3000 psi 30 minutes – held. Perf Lower or @ 1401'. 0 gal HCl 15%. Released Pkr.
OTHER:  13. Describe proposed or compl of starting any proposed wor proposed completion or reco 4/19/2011 MIRU Blue Jet ran CBL. Fruitland Coal 1542'-15: 4/20/2011 MIRU BJ Services – press 4/21/2011 MIRU BJ Services- FRAM	eted operations. (Clearly state all pertiners). SEE RULE 19.15.7.14 NMAC. For ompletion. Four Corners Testing, pressure tested Cs 32', 4 spf, 0.43" dia, 40 shots. Set packeture test lines to 4000 psi. Acidized w 50 C Lower Fruitland Coal w/ 52,540# Bro	nt details, and give pertinent dates, including estimate Multiple Completions: Attach wellbore diagram of g to 3000 psi 30 minutes – held. Perf Lower or @ 1401'. 0 gal HCl 15%. Released Pkr.
OTHER:  13. Describe proposed or complosed starting any proposed work proposed completion or recompletion of the proposed completion of the proposed or completion of the proposed work proposed completion or recompletion or rec	eted operations. (Clearly state all pertiners). SEE RULE 19.15.7.14 NMAC. For ompletion. Four Corners Testing, pressure tested Cs. 32', 4 spf, 0.43" dia, 40 shots. Set packed ure test lines to 4000 psi. Acidized w 50 C Lower Fruitland Coal w/ 52,540# Bro. 089 psi, max pressure @ 1275 psi.	nt details, and give pertinent dates, including estimate Multiple Completions: Attach wellbore diagram of g to 3000 psi 30 minutes – held. Perf Lower or @ 1401'. 0 gal HCl 15%. Released Pkr.
OTHER:  13. Describe proposed or complost of starting any proposed work proposed completion or recompletion of starting any proposed work proposed completion or recompletion of recompletion of recompletion of the start of the	eted operations. (Clearly state all pertiners). SEE RULE 19.15.7.14 NMAC. For ompletion. Four Corners Testing, pressure tested Cs 32', 4 spf, 0.43" dia, 40 shots. Set packed ure test lines to 4000 psi. Acidized w 50 C Lower Fruitland Coal w/ 52,540# Bro 089 psi, max pressure @ 1275 psi. Sill well.	nt details, and give pertinent dates, including estimate Multiple Completions: Attach wellbore diagram of g to 3000 psi 30 minutes – held. <b>Perf Lower</b> or @ 1401'.  O gal HCl 15%. Released Pkr. own snd in 306 bbls 70Q N2 Foam.
OTHER:  13. Describe proposed or complost of starting any proposed work proposed completion or recompletion of starting any proposed work proposed completion or recompletion of recompletion	eted operations. (Clearly state all pertiners). SEE RULE 19.15.7.14 NMAC. For impletion. Four Corners Testing, pressure tested Cs. 32', 4 spf, 0.43" dia, 40 shots. Set packed ure test lines to 4000 psi. Acidized w 50 C Lower Fruitland Coal w/ 52,540# Brows 1089 psi, max pressure @ 1275 psi. (ill well.) 1520'. Four Corners Testing Csg pressure.	nt details, and give pertinent dates, including estimate Multiple Completions: Attach wellbore diagram of g to 3000 psi 30 minutes – held. <b>Perf Lower</b> or @ 1401'.  O gal HCl 15%. Released Pkr. own snd in 306 bbls 70Q N2 Foam.
OTHER:  13. Describe proposed or compl of starting any proposed wor proposed completion or reco 4/19/2011 MIRU Blue Jet ran CBL. Fruitland Coal 1542'-15: 4/20/2011 MIRU BJ Services – press 4/21/2011 MIRU BJ Services- FRAM Pumped @ Min Pressure I 4/22/2011 Flowback on 3/4" choke. K 4/26/2011 MIRU Blue Jet set RBP @ Middle Fruitland Coal I w/ 500 gal 15% HCL. Re	eted operations. (Clearly state all pertiners). SEE RULE 19.15.7.14 NMAC. For impletion. Four Corners Testing, pressure tested Cs. 32', 4 spf, 0.43" dia, 40 shots. Set packed ure test lines to 4000 psi. Acidized w 50 C Lower Fruitland Coal w/ 52,540# Brows 1275 psi. (Clearly believed). Set packed with the set of the s	nt details, and give pertinent dates, including estimate Multiple Completions: Attach wellbore diagram of g to 3000 psi 30 minutes – held. <b>Perf Lower</b> or @ 1401'.  O gal HCl 15%. Released Pkr. own snd in 306 bbls 70Q N2 Foam.
OTHER:  13. Describe proposed or compl of starting any proposed wor proposed completion or reco 4/19/2011 MIRU Blue Jet ran CBL. Fruitland Coal 1542'-15: 4/20/2011 MIRU BJ Services – press 4/21/2011 MIRU BJ Services- FRAM Pumped @ Min Pressure I 4/22/2011 Flowback on 3/4" choke. K 4/26/2011 MIRU Blue Jet set RBP @ Middle Fruitland Coal I w/ 500 gal 15% HCL. Re	eted operations. (Clearly state all pertiners). SEE RULE 19.15.7.14 NMAC. For impletion. Four Corners Testing, pressure tested Cs. 32', 4 spf, 0.43" dia, 40 shots. Set packed ure test lines to 4000 psi. Acidized w 50 C Lower Fruitland Coal w/ 52,540# Brown 1275 psi. (Ill well.) 1520'. Four Corners Testing Csg presses 437'- 1430', 4 spf, 0.43" dia, 28 shots. P	nt details, and give pertinent dates, including estimate Multiple Completions: Attach wellbore diagram of g to 3000 psi 30 minutes – held. <b>Perf Lower</b> or @ 1401'.  O gal HCl 15%. Released Pkr. own snd in 306 bbls 70Q N2 Foam.
OTHER:  13. Describe proposed or complof starting any proposed word proposed completion or recompletion of starting any proposed word proposed completion or recompletion of r	eted operations. (Clearly state all pertiners). SEE RULE 19.15.7.14 NMAC. For impletion. Four Corners Testing, pressure tested Cs. 32', 4 spf, 0.43" dia, 40 shots. Set packed ure test lines to 4000 psi. Acidized w 50 C Lower Fruitland Coal w/ 52,540# Brows 1275 psi. (Clearly believed). Set packed with the set of the s	nt details, and give pertinent dates, including estimate Multiple Completions: Attach wellbore diagram of g to 3000 psi 30 minutes – held. <b>Perf Lower</b> or @ 1401'.  O gal HCl 15%. Released Pkr. own snd in 306 bbls 70Q N2 Foam.
OTHER:  13. Describe proposed or compl of starting any proposed wor proposed completion or reco 4/19/2011 MIRU Blue Jet ran CBL. Fruitland Coal 1542'-15: 4/20/2011 MIRU BJ Services – press 4/21/2011 MIRU BJ Services- FRAM Pumped @ Min Pressure I 4/22/2011 Flowback on 3/4" choke. K 4/26/2011 MIRU Blue Jet set RBP @ Middle Fruitland Coal I w/ 500 gal 15% HCL. Re	eted operations. (Clearly state all pertiners). SEE RULE 19.15.7.14 NMAC. For impletion. Four Corners Testing, pressure tested Cs. 32', 4 spf, 0.43" dia, 40 shots. Set packed ure test lines to 4000 psi. Acidized w 50 C Lower Fruitland Coal w/ 52,540# Brows 1275 psi. (Clearly believed). Set packed with the set of the s	nt details, and give pertinent dates, including estimate Multiple Completions: Attach wellbore diagram of g to 3000 psi 30 minutes – held. <b>Perf Lower</b> or @ 1401'.  O gal HCl 15%. Released Pkr. own snd in 306 bbls 70Q N2 Foam.
OTHER:  13. Describe proposed or complor of starting any proposed work proposed completion or recompletion of	eted operations. (Clearly state all pertiners). SEE RULE 19.15.7.14 NMAC. For impletion. Four Corners Testing, pressure tested Cs. 32', 4 spf, 0.43" dia, 40 shots. Set packed ure test lines to 4000 psi. Acidized w 50 C Lower Fruitland Coal w/ 52,540# Brows 1989 psi, max pressure @ 1275 psi. (ill well.) 1520'. Four Corners Testing Csg pressing 437'- 1430', 4 spf, 0.43" dia, 28 shots. Pleased Pkr. Coal w/ 36,360# 16/30 Brown snd in 21	nt details, and give pertinent dates, including estimate Multiple Completions: Attach wellbore diagram of g to 3000 psi 30 minutes – held. <b>Perf Lower</b> or @ 1401'.  O gal HCl 15%. Released Pkr. own snd in 306 bbls 70Q N2 Foam.
OTHER:  13. Describe proposed or complof starting any proposed word proposed completion or recompletion of starting any proposed word proposed completion or recompletion of r	eted operations. (Clearly state all pertiners). SEE RULE 19.15.7.14 NMAC. For impletion. Four Corners Testing, pressure tested Cs. 32', 4 spf, 0.43" dia, 40 shots. Set packed ure test lines to 4000 psi. Acidized w 50 C Lower Fruitland Coal w/ 52,540# Brows 1989 psi, max pressure @ 1275 psi. (ill well.) 1520'. Four Corners Testing Csg pressing 437'- 1430', 4 spf, 0.43" dia, 28 shots. Pleased Pkr. Coal w/ 36,360# 16/30 Brown snd in 21	nt details, and give pertinent dates, including estimate Multiple Completions: Attach wellbore diagram of g to 3000 psi 30 minutes – held. <b>Perf Lower</b> or @ 1401'.  O gal HCl 15%. Released Pkr. own snd in 306 bbls 70Q N2 Foam.
OTHER:  13. Describe proposed or complor of starting any proposed work proposed completion or recompletion of	eted operations. (Clearly state all pertiners). SEE RULE 19.15.7.14 NMAC. For impletion. Four Corners Testing, pressure tested Cs. 32', 4 spf, 0.43" dia, 40 shots. Set packed ure test lines to 4000 psi. Acidized w 50 C Lower Fruitland Coal w/ 52,540# Bro. 089 psi, max pressure @ 1275 psi. Cill well.  10) 1520'. Four Corners Testing Csg press. 437'- 1430', 4 spf, 0.43" dia, 28 shots. Pleased Pkr.  11) Coal w/ 36,360# 16/30 Brown snd in 21	nt details, and give pertinent dates, including estimate Multiple Completions: Attach wellbore diagram of g to 3000 psi 30 minutes – held. Perf Lower er @ 1401'. 0 gal HCl 15%. Released Pkr. own snd in 306 bbls 70Q N2 Foam .  ure to 3000 psi for 30 minutes. Blue Jet -Perf kr @ 1304'. Tested lines @ 4399 psi. BJ Acidize 9 bbls 70Q N2 Foam.  RECEIVE 2/25/2011
OTHER:  13. Describe proposed or complor of starting any proposed work proposed completion or recolor 4/19/2011 MIRU Blue Jet ran CBL.  Fruitland Coal 1542'-15: 4/20/2011 MIRU BJ Services – press 4/21/2011 MIRU BJ Services- FRAGE Pumped @ Min Pressure 1 4/22/2011 Flowback on 3/4" choke. K 4/26/2011 MIRU Blue Jet set RBP @ Middle Fruitland Coal 1 w/ 500 gal 15% HCL. Re 4/27/2011 FRAC Middle Fruitland Completion operations continued  Spud Date:  2/16/2011	eted operations. (Clearly state all pertiners). SEE RULE 19.15.7.14 NMAC. For impletion. Four Corners Testing, pressure tested Cs. 32', 4 spf, 0.43" dia, 40 shots. Set packed ure test lines to 4000 psi. Acidized w 50 C Lower Fruitland Coal w/ 52,540# Brown B	nt details, and give pertinent dates, including estimate Multiple Completions: Attach wellbore diagram of g to 3000 psi 30 minutes – held. Perf Lower et @ 1401'.  0 gal HCl 15%. Released Pkr. own snd in 306 bbls 70Q N2 Foam.  ure to 3000 psi for 30 minutes. Blue Jet -Perf kr @ 1304'. Tested lines @ 4399 psi. BJ Acidize 9 bbls 70Q N2 Foam.  RECEIVE 2/25/2011
OTHER:  13. Describe proposed or complor of starting any proposed work proposed completion or recompletion of recompletion of starting any proposed work proposed completion or recompletion of recompletion of recompletion of recompletion of recompletion of recompletion of starting and starti	eted operations. (Clearly state all pertiners). SEE RULE 19.15.7.14 NMAC. For impletion. Four Corners Testing, pressure tested Cs. 32', 4 spf, 0.43" dia, 40 shots. Set packed ure test lines to 4000 psi. Acidized w 50 C Lower Fruitland Coal w/ 52,540# Bro. 089 psi, max pressure @ 1275 psi. (ill well.) 1520'. Four Corners Testing Csg press. 437'- 1430', 4 spf, 0.43" dia, 28 shots. Pleased Pkr. Coal w/ 36,360# 16/30 Brown snd in 21 Rig Release Date:	nt details, and give pertinent dates, including estimate Multiple Completions: Attach wellbore diagram of g to 3000 psi 30 minutes – held. Perf Lower or @ 1401'.  0 gal HCl 15%. Released Pkr. own snd in 306 bbls 70Q N2 Foam.  ure to 3000 psi for 30 minutes. Blue Jet -Perf kr @ 1304'. Tested lines @ 4399 psi. BJ Acidize 9 bbls 70Q N2 Foam.  RECEIVE 2/25/2011  ny knowledge and belief.
OTHER:  13. Describe proposed or complor of starting any proposed work proposed completion or recolor 4/19/2011 MIRU Blue Jet ran CBL.  Fruitland Coal 1542'-15: 4/20/2011 MIRU BJ Services – press 4/21/2011 MIRU BJ Services- FRAGE Pumped @ Min Pressure 1 4/22/2011 Flowback on 3/4" choke. K 4/26/2011 MIRU Blue Jet set RBP @ Middle Fruitland Coal 1 w/ 500 gal 15% HCL. Re 4/27/2011 FRAC Middle Fruitland Completion operations continued  Spud Date:  2/16/2011	eted operations. (Clearly state all pertiners). SEE RULE 19.15.7.14 NMAC. For impletion. Four Corners Testing, pressure tested Cs. 32', 4 spf, 0.43" dia, 40 shots. Set packed ure test lines to 4000 psi. Acidized w 50 C Lower Fruitland Coal w/ 52,540# Bro. 089 psi, max pressure @ 1275 psi. (ill well.) 1520'. Four Corners Testing Csg press. 437'- 1430', 4 spf, 0.43" dia, 28 shots. Pleased Pkr. Coal w/ 36,360# 16/30 Brown snd in 21 Rig Release Date:	nt details, and give pertinent dates, including estimate Multiple Completions: Attach wellbore diagram of g to 3000 psi 30 minutes – held. Perf Lower et @ 1401'.  0 gal HCl 15%. Released Pkr. own snd in 306 bbls 70Q N2 Foam.  ure to 3000 psi for 30 minutes. Blue Jet -Perf kr @ 1304'. Tested lines @ 4399 psi. BJ Acidize 9 bbls 70Q N2 Foam.  RECEIVE 2/25/2011
OTHER:  13. Describe proposed or complof starting any proposed word proposed completion or recold 4/19/2011 MIRU Blue Jet ran CBL.  Fruitland Coal 1542'-15: 4/20/2011 MIRU BJ Services – press 4/21/2011 MIRU BJ Services- FRAME Pumped @ Min Pressure 1 4/22/2011 Flowback on 3/4" choke. K 4/26/2011 MIRU Blue Jet set RBP @ Middle Fruitland Coal 1 w/ 500 gal 15% HCL. Re 4/27/2011 FRAC Middle Fruitland Completion operations continued  Spud Date:  2/16/2011  I hereby certify that the information a SIGNATURE	eted operations. (Clearly state all pertiners). SEE RULE 19.15.7.14 NMAC. For impletion. Four Corners Testing, pressure tested Cs. 32', 4 spf, 0.43" dia, 40 shots. Set packed ure test lines to 4000 psi. Acidized w 50 C Lower Fruitland Coal w/ 52,540# Bro. 089 psi, max pressure @ 1275 psi. Cill well.  10 1520'. Four Corners Testing Csg press. 437'- 1430', 4 spf, 0.43" dia, 28 shots. Pleased Pkr.  12 Coal w/ 36,360# 16/30 Brown snd in 21 Rig Release Date:  Rig Release Date:	nt details, and give pertinent dates, including estimate Multiple Completions: Attach wellbore diagram of g to 3000 psi 30 minutes – held. Perf Lower or @ 1401'.  0 gal HCl 15%. Released Pkr. own snd in 306 bbls 70Q N2 Foam.  ure to 3000 psi for 30 minutes. Blue Jet -Perf kr @ 1304'. Tested lines @ 4399 psi. BJ Acidize 9 bbls 70Q N2 Foam.  RECEIVE 2/25/2011  ny knowledge and belief.
OTHER:  13. Describe proposed or complof starting any proposed work proposed completion or recolor 4/19/2011 MIRU Blue Jet ran CBL.  Fruitland Coal 1542'-15: 4/20/2011 MIRU BJ Services – press 4/21/2011 MIRU BJ Services- FRAME Pumped @ Min Pressure If 4/22/2011 Flowback on 3/4" choke. Kf. 4/26/2011 MIRU Blue Jet set RBP @ Middle Fruitland Coal If w/ 500 gal 15% HCL. Ref. 4/27/2011 FRAC Middle Fruitland Completion operations continued  Spud Date:  2/16/2011  I hereby certify that the information a SIGNATURE	eted operations. (Clearly state all pertiners). SEE RULE 19.15.7.14 NMAC. For impletion. Four Corners Testing, pressure tested Cs. 32', 4 spf, 0.43" dia, 40 shots. Set packed ure test lines to 4000 psi. Acidized w 50 C Lower Fruitland Coal w/ 52,540# Bro. 089 psi, max pressure @ 1275 psi. Cill well.  10 1520'. Four Corners Testing Csg press. 437'- 1430', 4 spf, 0.43" dia, 28 shots. Pleased Pkr.  12 Coal w/ 36,360# 16/30 Brown snd in 21 Rig Release Date:  Rig Release Date:	nt details, and give pertinent dates, including estimate Multiple Completions: Attach wellbore diagram of g to 3000 psi 30 minutes – held. Perf Lower or @ 1401'.  0 gal HCl 15%. Released Pkr. own snd in 306 bbls 70Q N2 Foam.  ure to 3000 psi for 30 minutes. Blue Jet -Perf kr @ 1304'. Tested lines @ 4399 psi. BJ Acidize 9 bbls 70Q N2 Foam.  PECEIVE 2/25/2011  DIL CONS. DIV. DISTACT OF THE PROPERTY OF THE PROPERT
OTHER:  13. Describe proposed or complof starting any proposed word proposed completion or recold 4/19/2011 MIRU Blue Jet ran CBL.  Fruitland Coal 1542'-15: 4/20/2011 MIRU BJ Services – press 4/21/2011 MIRU BJ Services- FRAME Pumped @ Min Pressure 1 4/22/2011 Flowback on 3/4" choke. K 4/26/2011 MIRU Blue Jet set RBP @ Middle Fruitland Coal 1 w/ 500 gal 15% HCL. Re 4/27/2011 FRAC Middle Fruitland Completion operations continued  Spud Date:  2/16/2011  I hereby certify that the information a SIGNATURE	eted operations. (Clearly state all pertiners). SEE RULE 19.15.7.14 NMAC. For impletion. Four Corners Testing, pressure tested Cs. 32', 4 spf, 0.43" dia, 40 shots. Set packed ure test lines to 4000 psi. Acidized w 50 C Lower Fruitland Coal w/ 52,540# Bro. 089 psi, max pressure @ 1275 psi. Cill well.  10 1520'. Four Corners Testing Csg press. 437'- 1430', 4 spf, 0.43" dia, 28 shots. Pleased Pkr.  12 Coal w/ 36,360# 16/30 Brown snd in 21 Rig Release Date:  Rig Release Date:	nt details, and give pertinent dates, including estimate Multiple Completions: Attach wellbore diagram of g to 3000 psi 30 minutes – held. Perf Lower or @ 1401'.  0 gal HCl 15%. Released Pkr. own snd in 306 bbls 70Q N2 Foam.  ure to 3000 psi for 30 minutes. Blue Jet -Perf kr @ 1304'. Tested lines @ 4399 psi. BJ Acidize 9 bbls 70Q N2 Foam.  PRECEIVE 2/25/2011  Oll CONS. DIV. DIS pigma@McElvain.com PHONE: 303-893-0

Pepper #2 30-045-35210

## Completion Operations continued

4/29/2011 Flow back well. Released RBP @ 1520'

5/2/2011 MIRU Blue Jet, set RBP @ 1420'. Four Corners Testing- pressure test csg to 3000 psi for 30 minutes- Held. **Perf Upper Fruitland Coal** 1365'-1355'. 4 spf, 0.43" dia 40 shots. Pkr set @ 1239'. Test lines @ 4580 psi. Acidize w/ 400 gal 15 % HCL. Reset Pkr @ 1304'. Swab. Released Pkr.

5/3/2011 Frac Upper Fruitland Coal.-Pressure test lines to 4500 psi. Frac w/ 50,340# Brwn 16/30 snd in 233.6 bbls 70Q N2 Foam.

5/4/2011 Flow back well, swab.

5/5/2011 Released RBP & POOH. Bailed sand to PBTD @ 1648'.

5/6/2011 MU RIH with tapped plug, 1 jt tbg, 3' perforated sub, seating nipple & 49 jts of 2-7/8", 6.5#, J-55 tbg (SN: 1,598.6' KB; EOT: 1,634.20' KB). Hung tubing. ND BOP NU WH. RIH with 2.5" X 2" X 12' RWAC pump, 1-7/8" X 3' stabilizer, 2-1 1/4" X 25' K Bars, 1-7/8" X 3' stabilizer, 2-1 1/4" X 25' K Bars, 1-7/8" X 3' stabilizer, 20-7/8' rods with snap on guides, 38-7/8" plain rods, 1-7/8" X 8' sub, 1-7/8" X 4', 2-7/8" X 2', sub. 1-1/4" X 22' polished rod with liner. Loaded tbg with rig pump, long stroked pump, pressured to 450 psi, held.