

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐
well well

2. NAME OF OPERATOR
Texaco Inc.

3. ADDRESS OF OPERATOR
P.O. Box EE, Cortez, CO.81321

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 660' FNL & 500' FWL
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO: SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐ ☐

FRACTURE TREAT ☐ ☐

SHOOT OR ACIDIZE ☐ ☐

REPAIR WELL ☐ ☐

PULL OR ALTER CASING ☐ ☐

MULTIPLE COMPLETE ☐ ☐

CHANGE ZONES ☐ ☐

ABANDON* ☐ ☒

(other) ☐ ☐

AUG 08 1985

5. LEASE
NOO-C-14-20-3668

6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Navajo Allotted

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Dome Navajo 29-21-7

9. WELL NO.
1

10. FIELD OR WILDCAT NAME
Wildcat/Entrada

11. SEC. T. R. M. OR BLK. AND SURVEY OR AREA
Sec. 29, T21N, R7W

12. COUNTY OR PARISH
Sandoval

13. STATE
New Mexico

14. API NO.

15. ELEVATIONS (SHOW OF KDB; AND WD)
6802' GR

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Work completed 7/30/85
MIRUSU run tbg to 5998' KB. Spot 150' cmt plug 28 sx across Entrada 5998' to 5848' KB. Spot 37 Bbls 9.0 mud. Spot 150' Cmt. plug 28 sx across Dakota 4971' - 4821' KB. Spot 37 Bbls 9.0 mud. Spot 150' Cmt plug 28 sx across Gallup 3808 - 3658' KB. Circulate hole with 9.0 mud. Rig up casing jacks freepoint casing @ 1103' KB. Rigup wireline run cutoff shot hungup @ 675' KB. Pullout of hole. Perforate 2 way shot @ 910' KB spot 50 sx cmt, squeeze 25 sx into perfs. Shoot 2-way shot @ 618' KB. Spot 50 sx cmt, squeeze 25 sx into perfs. Shoot 2 way shot @ 230' KB. Spot 85 sx cmt plug squeeze into perfs. Place 50' plug in top of wellbore. Erect dry hole marker. Move all equipment off restore & seed location. Location ready for inspection.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED Ch-R. Mart TITLE Area Supt. DATE 8/6/85

Csg. left in Hole; 9 5/8" 32.3# 193' 7" 20.23# 26# 6180'

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

BLM (4) - AJS-JNH-ARM

*See Instructions on Reverse Side

NMOCC

APPROVED

AUG 14 1985

AREA MANAGER
FARMINGTON RESOURCE AREA