

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
SUNDRY NOTICES AND REPORTS ON WELLS

1. <b>OILWELL</b> <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. <b>NM-22036</b>
2. NAME OF OPERATOR <b>Gary Williams Production Company</b>		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR <b>1775 Sherman St., Ste 1925 Denver, CO 80202 (303) 831-4673</b>		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL AT SURFACE <b>2202' FSL, 1450' FWL, Section 4-T20N-R4W</b>		8. FARM OR LEASE NAME <b>Penistaja 4</b>
		9. WELL NUMBER <b>#11</b>
		10. FIELD AND POOL, OR WILDCAT <b>Wildcat</b>
		11. SEC., T., R., OR BLK. AND SURVEY <b>Section 4 - T20N - R4W</b>
14. PERMIT NO.	15 ELEVATIONS <b>6950' GL 6963' KB</b>	12. COUNTY OR PARISH <b>SANDOVAL</b>
		13. STATE <b>N.M.</b>

18. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIR WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETE <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(OTHER) _____	<input type="checkbox"/>
OTHER <input type="checkbox"/>			

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS

Request approval to abandon well per the attached procedure.

RECEIVED  
NOV 3 1994  
OIL CON. DIV.  
DIST. 3

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Atty-in-Fact DATE 2 May, 94

(This space for Federal or State Office use) HECTOR A. VILLALOBOS AREA MANAGER

APPROVED BY \_\_\_\_\_ TITLE RIO PUERCO RESOURCE AREA DATE NOV 1 1994

CONDITIONS OF APPROVAL, IF ANY:


**PENISTAJA #4-11**  
**Plug and Abandon Procedure**

SEE ATTACHED WELL DIAGRAM FOR TUBULAR DETAILS

1. Move in, rig up, service rig.
2. Pump tank bottoms into well.
3. Nipple up BOP's. Pick up tubing string and TIH to 3929'. Fill hole with gelled water.
4. TIH and set Class "H" cement plugs as follows: Plug #1, 25 sacks (30 cu. ft.) @ 3929' to 3829', 1/2 inside and 1/2 outside the 4-1/2" liner top @ 3879'. Plug #2, 25 sacks (30 cu. ft.) from 1220' to 1120'. Plug #3, 50 sacks (60 cu.ft.) from 237' to surface.
5. Cut off casing below ground level and erect dry hole marker.
6. Remove production equipment and reclaim location to BLM specifications.

March 31, 1994  
Charles H. Johns

Samuel Gary, Jr. & Associates  
 Penistaja 4-II Wellbore Diagram  
 NESW Sec. 4 T20 R4W  
 Sandoval County, NM



PREPARED BY: S.C. FREDRICKSON  
 PREPARED ON: 5/29/92  
 REVISED BY: C. H. JOHNS  
 REVISED ON: 4/1/94