

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 8901

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

--

7. UNIT AGREEMENT NAME

--

8. FARM OR LEASE NAME

EL NORTE *Federal*

9. WELL NO.

#2

10. FIELD AND POOL, OR WHDCAT

SNAKE EYES

11. SEC. T. R., M., OR BLK. AND
SURVEY OR AREA

Sec. 17-21N-8W

12. COUNTY OR PARISH 13. STATE

San Juan New Mexico

1. OIL ☐ GAS ☒ OTHER ☐ to abandon

2. NAME OF OPERATOR

DAVIS OIL COMPANY

3. ADDRESS OF OPERATOR

1230 Denver Club Bldg., - Denver, Colorado 80202

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660 FSL 660 FWL Sec. 17-T21N-R8W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6583 Gr.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

X

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We propose to plug and abandon the El Norte No. 2, as it has reached the economic limit.

The plugging procedure would be as follows:

1. Spot 50 sx cement plug across Dakota perfs (4614-16; 4626-30), pull tubing above cement and surface squeeze, leaving at least 50' of cement above top perforation.
2. Pull free casing, place 50 sx plug leaving 50' cement in stub and at least 50' cement above stub.
3. Place 95 sx plug from 450' (base Picture Cliffs at 400') to at least 300'.
4. Set dry hole marker in top surface pipe with 5 sx.
5. Clean and level location.

(It is anticipated that Larry Bedford, Inc. will do the work.)

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Production Engineer

DATE

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: