

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☐ gas ☐ other ☒ Injection
2. NAME OF OPERATOR
Getty Oil Company
3. ADDRESS OF OPERATOR
P.O. Box 3360, Casper, Wy 82602
4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
AT SURFACE: 1980' FNL & 1980' FWL (Unit F)
AT TOP PROD. INTERVAL: Same
AT TOTAL DEPTH: Same
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

- TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☐

SUBSEQUENT REPORT OF:

- ☐
☐
☐
☐
☐
☐
☐
☐

(other) Notice of Intent to P&A

RECEIVED

DEC 05 1983

(NOTE) Report results of multiple completion or zone change on Form 9-330.)

BUREAU OF LAND MANAGEMENT
FARMINGTON RESOURCE AREA

5. LEASE
Contract #68
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
Jicarilla Apache
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
Jicailia "B"
9. WELL NO.
6
10. FIELD OR WILDCAT NAME
Otero Gallup
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 32-T25N-R5W
12. COUNTY OR PARISH
Rio Arriba
13. STATE
New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
6755' DF

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Getty Oil Company requests approval to P & A this well according to the attached procedure. The well will be swab tested for two days before plugging to confirm that it is not productive.

Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Area Superintendent DATE 11/30/83

(This space for Federal or State office use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

NMOCC

*See Instructions on Reverse Side

[Signature]
[Signature]

PLUG AND ABANDONMENT PROCEDURE

JICARILLA "B" NO. 6

1. Move in and rig up workover unit.
2. Nipple down wellhead, nipple up BOP.
3. Pick up, trip in hole with 2 3/8" tubing workstring to 6000'.
4. Swab well for two days. A decision will be made at this time whether to proceed with the plugging or to install a pumping unit.
5. Trip out of hole with tubing.
6. Trip in hole with tubing and cement retainer to 6020'. Set cement retainer at 6020'.
7. Establish injection rate. Sting out of cement retainer. Spot cement at end of tubing. Sting into cement retainer and squeeze 22 sacks (26 cu ft) Class "B" cement into perfs. Spot 25 sacks (30 cu ft) of Class "B" cement from 6020' to 5799'.
8. Circulate hole with 9.2 mud from 5799' to surface.
9. Trip out of hole with tubing.
10. Move in and rig up wireline unit. Trip in hole with perforating guns to 4292'.
11. Perforate casing at 4292' with 4 shots and a 0.50 EHD. Trip out of hole with perforating guns.
12. Pick up cement retainer. Trip in hole with cement retainer and 2 3/8" tubing to 4282'. Set cement retainer at 4282'.
13. Establish injection rate. Sting out of cement retainer. Spot cement at end of tubing. Sting into cement retainer and squeeze 22 sacks (26 cu ft) Class "B" cement into perfs. Spot 25 sacks (30 cu ft) Class "B" from 4282' to 4061'.
14. Spot Class "B" cement plugs with 9.2 ppg mud in between plugs at the following intervals:

<u>Formation</u>	<u>Interval</u>	<u>No. Sacks (cu ft)</u>	
Chacra	3629'-3408'	25	(30)
Pictured Cliffs	2825'-2603'	25	(30)
Ojo Alamo	2323'-2102'	25	(30)

15. Trip out of hole with tubing.
16. Cut casing off with either a chemical cutter or wireline casing cutter at 2000'. Pull casing out of hole.

17. Trip in hole to 2050'. Spot 28 sacks (33 cu ft) of Class "B" cement from 2050' to 1947'.
18. Pull up hole to 380'. Spot 46 sacks (54 cu ft) of Class "B" cement from 380' to 280'.
19. Pull up hole to 180'. Reverse out any cement in tubing string. Wait on cement overnight.
20. Tag cement with tubing. Trip out of hole with tubing.
21. Cut off casing 4' below ground level.
22. Spot 25 sacks (30 cu ft) from 56' to 4'.
23. Set standard dry hole marker. Dry hole marker will have welded on it or permanently inscribed the following information:

Jicarilla "B" No. 6
Contract No. 68
Unit F Sec. 32-T25N-R5W
Rio Arriba County, New Mexico
24. Restore location to BIA requirements.

BEIWE

10-3-1983