

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well <input type="checkbox"/> Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other	5. Lease Designation and Serial No. Contract # 34
2. Name of Operator Texaco Exploration and Production Inc.	6. If Indian, Allottee or Tribe Name Jicarilla Apache
3. Address and Telephone No. 3300 N. Butler, Farmington N.M. 87401 (505)325-4397	7. If Unit or CA, Agreement Designation
4. Location of Well (Footage, Sec., T., R., M., or Survey Description) 1650' FSL & 1650' FEL of sec. 27, T25N-R5W	8. Well Name and No. Jicarilla C 6
	9. API Well No. 300390057090001
	10. Field and Pool, or Exploratory Area Basin Des Moines
	11. County or Parish, State Otero, Callup
	Rio Arriba, NM

CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment
<input type="checkbox"/> Subsequent Report	<input checked="" type="checkbox"/> Recompletion
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Plugging Back
	<input type="checkbox"/> Casing Repair
	<input type="checkbox"/> Altering Casing
	<input type="checkbox"/> Other _____
	<input type="checkbox"/> Change of Plans
	<input type="checkbox"/> New Construction
	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Water Shut-Off
	<input type="checkbox"/> Conversion to Injection
	<input type="checkbox"/> Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

1. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Texaco Exploration and Production proposes to abandon the Dakota completion in the subject well and recomplete the well in the Mesa Verde formation. The attached procedure will be followed.

RECEIVED
BLM
92 AUG 18 AM 10:09
019 FARMINGTON, N.M.

RECEIVED
AUG 20 1992
U.S. CON. DIV. J
DIST. 3

I hereby certify that the foregoing is true and correct

Signed [Signature] Title Area Manager

(This space for Federal or State office use)

Approved by _____ Title _____
Conditions of approval, if any:

NMOCD

**APPROVED
AS AMENDED**

AUG 18 1992

AREA MANAGER

Jicarilla C 6
Mesa Verde Workover Procedure

1. MIRUSU, NDWH, NUBOP.
2. POOH w/ Prod TBG.
3. RIH w/ CMT RET on 2 3/8" prod TBG to ~7130', establish a rate and pressure through RET and set. Abandon the Gallup completion by squeezing w/ 35 sx CMT + CSG volume between CMT RET and TD. Sting out of RET and spot 2 BBLs CMT on top of RET. POOH w/ TBG.
4. Press test CSG to 1000 psi. If CSG press test go to step 5. If CSG does not press test RIH w/ PKR and hunt leak. Identify top and bottom of leak. Evaluate CSG for repairs. If the CSG leak is located between 4379' and 5153' incorporated CSG repairs w/ Mesa Verde isolation.
5. Following CSG repairs, RU wireline and run GR-CCL-TDT (run required CBL-VDL in step 4). SDFE.
6. Perforate and stimulate Mesa Verde intervals determined from GR-CCL-TDT.
Proposed intervals: (I) 4380'-4675'
(II) 4740'-5085'
Intervals I and II to be completed and tested in two stages as follows.

Completion of interval II

1. Perforate selected intervals. POOH and RD wireline.
2. RIH w/ 5-1/2" PKR on 2-3/8" TBG, set PKR above perforated interval and flow test well through orifice well tester. Record flow data for Tight Gas Sand Designation. Flow well until a stabilized production rate is recorded.
3. Acidize perforated interval using 25 Gal/net-ft, divert acid using 2 PPG gelled salt stages. Flow/Swab load and flow test.
4. Stimulate interval II, Stimulation to be determined following logging.
5. Flow/Swab load and flow test interval.
6. POOH w/ TBG and PKR. RIH w/ 5-1/2" RBP on 2-3/8" TBG, set RBP above top perf of interval II. POOH w/ TBG.

Completion of interval I

1. Perforate selected intervals. POOH and RD wireline.
2. RIH w/ 5-1/2" PKR on 2-3/8" TBG, set PKR above perforated interval and flow test well through orifice well tester. Record flow data for Tight Gas Sand Designation. Flow well until a stabilized production rate is recorded.
3. Acidize perforated interval using 25 Gal/net-ft, divert acid using 2 PPG gelled salt stages. Flow/Swab load and flow test.
4. Stimulate interval II, Stimulation to be determined following logging.
5. Flow/Swab load and flow test interval.

7. Evaluate intervals I and II, if production is adequate RIH w/ production equipment. If production is not sufficient, SDF abandonment procedure.
8. NDBOP, NUWH (if necessary). RDMOSU.

8/18/92



JICARILLA C No. 6

Current Completion

WELL:

Jicarilla C No. 6

LOCATION:

1660' FSL & 1660' FEL, Unit J
NW/4, SE/4, Sec. 27, T26N, R06W
Rio Arriba County

PROPOSED MESA VERDE PERFORATIONS:

4390' - 4675'
4740' - 5085'

Dakota Perforations:

7022' - 7200'

PBTD' - 7133'
TD - 7370'

