

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPPLICATE*
(Other instructions on re-
verse side)

Form approved.
Budget Bureau No. 42-R1424.

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

5. LEASE DESIGNATION AND SERIAL NO.

Jicarilla Contract 148

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

Jicarilla Apache

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Jicarilla Contract 148

9. WELL NO.

9

10. FIELD AND POOL, OR WILDCAT

Basin Dakota

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

SW/4 Section 15,
T-25-N, R-5-W

12. COUNTY OR PARISH

Rio Arriba

13. STATE

New Mexico

1. OIL ☐ GAS ☒ OTHER ☐
WELL WELL

2. NAME OF OPERATOR

AMOCO PRODUCTION COMPANY

3. ADDRESS OF OPERATOR

501 Airport Drive, Farmington, New Mexico 87401

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

1145' FSL & 1650' FWL, Section 15, T-25-N, R-5-W

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6831' GL

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

FULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☒

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☐

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We are proposing to abandon the subject well due to uncommercial production and a casing leak above all potentially producing zones. This well will be abandoned in the following manner:

1. Set cement retainer above Graneros perforations and squeeze 80 sacks of cement into perforations. Spot cement plug of 10 sacks on retainer.
2. Perforate top of Mesaverde (4680') and squeeze under retainer with 100 sacks of cement. Spot cement plug of 10 sacks on retainer.
3. Squeeze casing leak at 2828' under a retainer with 120 sacks of cement. Spot cement plug of 10 sacks on retainer.
4. Perforate at 530' and circulate cement to surface with 200 sacks.
5. Spot 40' plug at surface.
6. Cut off wellhead and erect P&A marker.

7. Clean up location.

Verbal approval for the above procedure was acquired from Ed Schmidt on 12-10-76.

18. I hereby certify that the foregoing is true and correct

SIGNED Ed Schmidt

TITLE Area Engineer

DATE December 13, 1976

(This space for Federal or State office use)

APPROVED BY _____
CONDITIONS OF APPROVAL, IF ANY:

TITLE _____

DATE _____

APPROVED

DEC 17, 1976

E. A. SCHMIDT

Area Engineer

*See Instructions on Reverse Side

