

## UNITED STATES





## **Tubing Repair Procedure**

4/15/98

Canyon Largo Unit Com #318 DPNO 52571A

Dakota Field

1730' FNL & 1850' FWL, Unit F, Sec. 13, T-24-N, R-6-W Rio Arriba County, NM

Lat / Long: 36°18.9175' 107°25.3262'

**Project Summary:** The Canyon Largo Unit Com #318 is a Dakota producer drilled in 1983. The well is currently producing 59 MCFD. A recent wireline check showed an obstruction at 400' below surface.

- 1. Install and test location rig anchors. Prepare blow pit. Comply with all NMOCD, BLM, and Burlington regulations.
- MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. NU relief line. Blow down well and kill with 2% KCl water as necessary. ND wellhead and NU BOP. Send wellhead in for servicing (lease operator noted a leak).
  Note: Limit the amount of water put on the Dakota.
- 3. Pick up 2-3/8" tubing and RIH to tag fill, tally out of hole with 2-3/8" tubing. Visually inspect the tubing and replace any joints that are corroded or scaled up. If scale is present, then notify operation engineer for acid job volumes.
- 4. If fill covers any perforations, then clean out to PBTD with either air or a bailer. POOH.
- 5. RIH with expendable check, 1 jt., SN and 2-3/8" production tubing. Broach tubing going in the hole. Hang tubing at approximately 6500'. ND BOP, NU wellhead. Pump off check and blow well in. **Note:** if air packages is not used, then run tubing with plug in SN, land tubing, pull plug and swab well in.

7. RDMO PU. Turn well to production. Production Operations will set plunger lift.

Recommended:

Operations Enginee

Approval:

Drillind Superintenden

Contacts: Operations Engineer Kevin Midkiff 326-9807 (Office)

564-1653 (Pager)

Production Foreman Ward Arnold 326-9846 (Office)

326-8340 (Pager)