





Benny Hill
330-8261

Test

San Juan Basin Well Work Procedure



Well Name: Jicarilla Contract 148- 36
Version: #1
Date: 3/25/2002
Budget: DRA
Repair Type: TXA

Objectives:

1. TXA wellbore and perform mechanical integrity test. Hold for rehabilitation of the GP/DK or future SWD conversion.

23
Pertinent Information:

Location: Sec 13 T25N R5W
County: Rio Arriba
State: New Mexico
Lease:
Well Flac: 84637903
Lease Flac: 290476

Horizon: West Lindrith GP DK
API #: 30-039-23680
Engr: Allen Kutch
Phone: (281)366-7955
SAP X7-000PR

Economic Information:

APC WI: 1.00
Estimated Cost: \$10,000

Formation Tops: (Estimated formation tops)

Nacimiento:	Menefee:
Ojo Alamo:	Point Lookout:
Kirtland Shale:	Mancos Shale:
Fruitland:	Gallup: 6370
Pictured Cliffs:	Graneros:
Lewis Shale:	Dakota: 7310
Chacra:	Morrison:
Cliff House:	

Bradenhead Test Information:

Test Date: Tubing: Casing: BH:

Time	BH	CSG	INT	CSG
5 min				
10 min				
15 min				

Comments:

Hammond
BLM MAN
759-3485
#31
320-9141

Temporary abandonment procedure

1. Contact Federal and State agencies prior to starting work (NMOCD Charlie Perrin, 505-334-6178 X16, BLM Brian Davis 505-761-8756).
2. Check location for anchors. Install if necessary. Test anchors.
3. MIRUSU. Check and record tubing, casing and bradenhead pressures.
4. Blow down well and kill well, if necessary, with lease water.
5. POOH and LD pump and rods. ND wellhead. NU BOP's.
6. POOH with 2-3/8" tbg, visually inspecting.
7. Make bit x scraper run.
8. TIH with CIBP on tbg. Set CIBP at 6300' to temporarily abandon the GP/DK.
9. Load csg with inhibited lease water.
10. Attach chart recorder. Test casing to 550 psi for 30 minutes. Fax copy of chart to 281-366-0700, attention Allen Kutch.
11. RIH w/ 2-3/8" tbg. ND BOP, NU WH.
12. RDMO SU.

Jicarilla Contract 148-36 - Proposed TXA Configuration 3-25-2002
Rio Arriba County, NM
Unit H Section 23 T25N - R5W
Run 65
ATK

KB: 12' above GL

