Form approved. Budget Bureau No. 1004-0135 SUBMIT IN TRIPLICATES Expires August 31, 1985 Form 3160-5 DEPARTMENT OF THE INTERIOR verse side) UNITED STATES (November 1983) 5. LEASE DESIGNATION AND SERIAL NO. (Formerly 9-331) BUREAU OF LAND MANAGEMENT NM 43753 6. IF INDIAN, ALLOTTER OF TRIBE NAME SUNDRY NOTICES AND REPORTS ON WELLS (Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.


Use "APPLICATION FOR PERMIT" for such proposals.) 7. UNIT AGREEMENT NAME WELL GAS WELL S FARM OR LEASE NAME 2. NAME OF OPERATOR Post Federal Mallon Oil Company ADDRESS OF OPERATOR 2750 Security Life Building, Denver, CO 80202

LOCATION : WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below) #13-6 Gavilan Mancos/Gavilan Greenhorn-Graneros-Dakota
11. BBC, T. E., M., OR BLE AND
SURVEY OR ARBA At surface 1850' FNL & 1670' FWL Sec. 13, T25N, R2W RECEIVED 15. SLEVATIONS (Show whether DF, RT, GR, etc.) NM Rio Arriba 7450' GL MAR 1 8 1986 Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data SURSBOURNT REPORT OF: BUREAU OF LAND MANAGEMENT INTENTION TO: FARMINGTON RESOURCE AREA REPAIRING WELL WATER SHUT-OFF PULL OR ALTER CASING TEST WATER SHUT-OFF ALTERING CASING FRACTURE TREATMENT MULTIPLE COMPLETE PRACTURE TREAT ABANDON MENT SHOOTING OR ACIDIZING ABANDON* SHOOT OR ACIDIZA CHANGE PLANS (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) REPAIR WELL 17. DESCRIBE PROPOSED OR COMPLETED OFERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.) 3-15-86 Rigged up Petro Wireline. Ran GR-CLL from sand fill at 7841' RKB to tubing @ 5398' RKB. The frac treatment went into most perforations. It did not treat the following perforations: 7080, 7176, 7287, 7404, 7568. The following perfs are questionable: 7152, 7278, 7292, 7312, 7414, 7474, 7496, 7518, 7537, 7588. Trip tubing out of hole. Trip in hole and land tubing as follows: DEPTH LENGIH DESCRIPTION 10.50 0-11 KB to landing point 11-6555 213 jts 2-7/8" 6.5#/ft N-80 used tbg 6544.07 2.70 6555-6557 1 tubing anchor 6557-7583 1025.36 34 jts 2-7/8" 6.5#/ft N-80 used tbg .75 7583-7584 1 seating nipple 7584-7588 4.20 1 2-7/8" perforated sub 7588-7619 31.14 1 jt 2-7/8" mud anchor 7618.72 (NOTE: had to kill well several times to land tubing)

Nipple down BOP. Nipple up wellhead. Shut well in. SDFN.

Tile Completion Report by 4/28/86



OIL CONL DIV.

SIGNED that the foregoing laytrue and correct	TITLE Agent	PAGCEPTED TO RECORD
(This space for Federal or State office use) APPROVED BY	TITLE	PARMINGIO 1986
*Si	e Instructions on Reverse Side	BY

NMUCC