

NEW MEXICO OIL CONSERVATION COMMISSION
Santa Fe, New Mexico

MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

Indicate Nature of Notice by Checking Below

NOTICE OF INTENTION TO CHANGE PLANS		NOTICE OF INTENTION TO TEMPORARILY ABANDON WELL		NOTICE OF INTENTION TO DRILL DEEPER	
NOTICE OF INTENTION TO PLUG WELL		NOTICE OF INTENTION TO PLUG BACK		NOTICE OF INTENTION TO SET LINER	
NOTICE OF INTENTION TO SQUEEZE		NOTICE OF INTENTION TO ACIDIZE		NOTICE OF INTENTION TO SHOOT (Nitro)	
NOTICE OF INTENTION TO GUN PERFORATE		NOTICE OF INTENTION (OTHER)	X	NOTICE OF INTENTION (OTHER)	

OIL CONSERVATION COMMISSION
SANTA FE, NEW MEXICO

Farmington, New Mexico

April 27, 1961

(Place)

(Date)

Gentlemen:

Following is a Notice of Intention to do certain work as described below at the Shell Oil Company

Shell Oil Company Carson Unit Well No. 31-18 in B
(Company or Operator) (Unit)
NW 1/4 NE 1/4 of Sec. 18, T. 25N, R. 12W, NMPM, Lower Gallup Pool
(40-acre Subdivision) County. San Juan

FULL DETAILS OF PROPOSED PLAN OF WORK
(FOLLOW INSTRUCTIONS IN THE RULES AND REGULATIONS)

Status: Total Depth - 5070 PBD 5067
Casing - 4-1/2", 9.5#, J-55 cemented 5067' with 150 sacks.
Perforations - 4920-5030 (Four 1/2" holes/ft.)
Production - 98 B/D oil, 0.8% cut GOR 3000. Discovered leak in casing, set packer, attempted to pump from below packer. Last rate 5 B/D, 0 gas.



Plan to Repair Casing Failure:

Program:

1. Set drillable bridge plug at 4860'+ (above all perforations).
2. Locate position of hole in casing with retrievable cementer.
3. Cement hole using retrievable cementer set 300'+ above hole.
4. Drill out cement below hole and run swab test to determine if hole is repaired.
5. Drill out bridge plug, spot acid over perforations, and agitate acid with casing swab to restore well to normal productivity.

Note: Verbal approval obtained from Mr. E.C. Arnold by the undersigned by phone 4-27-61.

Approved MAY 1 1961, 19.....
Except as follows:

Shell Oil Company
Joe E. Dozier, Jr.
Company or Operator

Position District Production Superintendent
Send Communications regarding well to:

Approved
OIL CONSERVATION COMMISSION

By Original Signed Emery C. Arnold

Name Shell Oil Company

Title Supervisor Dist. # 3

Address P. O. Box 1200, Farmington, N. M.