

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil well ☐ gas well ☐ other ☐ Post Shot Reentry of Emplacement Hole

2. NAME OF OPERATOR
U.S. Dept. of Energy/El Paso Natural Gas Co.

3. ADDRESS OF OPERATOR
U.S. DOE, P.O. Box 14100, Las Vegas, NV 89114

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)
1218' FSL, 1770' FWL, Sec. 36,
AT SURFACE: T-29-N, R-4-W
AT TOP PROD. INTERVAL:
AT TOTAL DEPTH: Same as above (Vertical Hole)

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

TEST WATER SHUT-OFF ☐
FRACTURE TREAT ☐
SHOOT OR ACIDIZE ☐
REPAIR WELL ☐
PULL OR ALTER CASING ☐
MULTIPLE COMPLETE ☐
CHANGE ZONES ☐
ABANDON* ☒
(other) ☐

SUBSEQUENT REPORT OF:

☐
☐
☐
☐
☐
☐
☐
☐
☐
☐

5. LEASE SE 079161
Carson National Forest
6. IF INDIAN, ALLOTTEE OR TRIBE NAME
7. UNIT AGREEMENT NAME
8. FARM OR LEASE NAME
9. WELL NO.
GB-ER
10. FIELD OR WILDCAT NAME
Choza Mesa Pictured Cliffs
11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA
Sec. 36, T-29-N, R-4-W
12. COUNTY OR PARISH
Rio Arriba
13. STATE
New Mexico
14. API NO.
15. ELEVATIONS (SHOW DF, KDB, AND WD)
KDB-7227', DF-7226', GL-7211'

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

1. Run Wireline bridge plug using grease seal lubricator. Set bridge inside 2-7/8" tubing ± 10' above top of packer.
2. Fill tubing with water and test bridge plug with 200 psi surface pressure.
3. Remove upper portion of tree, nipple up annular BOP and tubing stripper.
4. Cut 2-7/8" tubing with jet cutter ± 10' above bridge plug. Circulate 7" casing with water.
5. Spot 125 ft³ of cement above packer inside 7" casing.
6. Pull 2-7/8" tubing. Run 3-1/2" drill pipe, circulate hole with mud, mill section in 7" casing from 3250' to 3270'.
7. Plugback 7" casing-top of existing plug to bottom of cellar with cement.
8. Remove tubing stripper, annular BOP, casing and tubing heads.
9. Cut 30", 20", and 7" casing strings at bottom of cellar, remove CMP and backfill with dirt.
10. A concrete monument containing a metal plaque with an inscription denoting the historical significance of the site will be erected over the abandoned emplacement well.

NOTE: Above operations are expected to be accomplished between 9-8-78 & 9-25-78. Set @ _____ Ft.
Subsurface Safety Valve: Manu. and Type _____

18. I hereby certify that the foregoing is true and correct

SIGNED [Signature] TITLE Dir., E&EA Div. DATE June 12, 1978

(This space for Federal or State office use)


APPROVED BY
CONDITIONS OF APPROVAL, IF ANY:

APPROVED

JUN 29 1978

E. A. SCHMIDT

*See Instructions, Reverse Side



RECEIVED

JUN 19 1978

U. S. GEOLOGICAL SURVEY
DURANCO, COLO.




FIGURE 10




FIGURE 11.