Form 3160-5 (November 1983) UNITED	STATES SUBMIT II	Y TRIPLICATE Budget Bureau I Expires August	No. 1004-0135	
(Formerly 9-331) DEPARTMENT OF THE INTERIOR (Other Instructions on Fe-BUREAU OF LAND MANAGEMENT		5. LEASE DESIGNATION NM-0702	5. LEASE DESIGNATION AND SERIAL NO.	
SUNDRY NOTICES AND (Do not use this form for proposals to drill or Use "APPLICATION FOR PI		6. IF INDIAN, ALLOTTEE OR TRIBE NAME N/A		
OIL GAS WELLX OTHER  2. NAME OF OPERATOR	7. UNIT AGREEMENT NAME N/A	7. UNIT AGREEMENT NAME N/A		
Snyder Oil Corporation 3. ADDRESS OF OPERATOR	8. FARM OR LEASE NAM. COLLINS 1			
P.O. 2038 Farmington, NM  4. Location of well (Report location clearly and in a See also apace 17 below)	9. WELL NO. 7800619011	7800619011		
See also space 17 below.) At surface	FLUCHER KUT	10. FIELD AND POOL, OR WILDCAT FLUCHER KUTZ PC		
1750' FNL & 1190' FWL, Sec 3	SURVEY OR AREA	11. SEC., T., E., M., OR BLK, AND SURVEY OR AREA		
14. PERMIT NO. 15. ELEVATIO	NS (Show whether DF, RT, GR, etc.)	12. COUNTY OF PARISH	13. STATE	
16. Check Appropriate Bo	ox To Indicate Nature of Notice		INT	
NOTICE OF INTENTION TO:	1	SUBSEQUENT REPORT OF:		
TEST WATER SHUT-OFF PULL OR ALTER	CASING WATER SHU-	F-OFF		
FRACTURE TREAT MULTIPLE COMP	[		II	
SHOOT OR ACIDIZE ABANDON*	- SHOOTING O		3/32	
REPAIR WELL CHANGE PLANS	(Other)	ABANDORMENT	1-1	
(Other)	(NOTE	: Report results of multiple completion or etion or Recompletion Report and Log form	Well	
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clear) proposed work. If well is directionally drilled, g nent to this work.)  Subject. Wol	ly state all pertinent details, and give ive subsurface locations and measured  1 Plugged and Aband	pertinent dates, including estimated date and true vertical depths for all markers :	of starting any ind zones perti-	
	il 6, 1994.	oned on		
Per	attached report.	APR V		
		OIL CO		
	Approved as to plugging Liebility under bond is resteration is or	of the well bore.  Stained until  Completed.	RECEIVED	
18. I hereby certify that the foregoing is true and correct				
SIGNED Wayne Converse	TITLE Enginee	DATE 04/11	/94	
(This space for Federal or State office use)				
APPROVED BY	TITLE	_ DATE:		
CONDITIONS OF APPROVAL, IF ANY:		APPROVE	D	
		100.1	_	
		2 APR 1 9 1994	_	
*	See Instructions on Reverse Side	pholison	<del>&gt;</del>	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any

Snyder Oil Corporation Collins #1
1750' FNL & 1190' FWL
Sec. 31, T29N, R10W
San Juan County, NM
NM-0702

## PLUG AND ABANDONMENT REPORT

## Cementing Summary:

- Plug #1 from 1858' to 1415' with 30 sxs Class B cement over PC perforations.
- Plug #2 from 1520' to 1363' with 11 sxs Class B cement inside casing.
- Plug #3 from 772' to 500' with 18 sxs Class B cement, inside casing.

## Plugging Summary:

- 3-31-94 Safety meeting. Drive rig and equipment to location. Rig repair. RU. SDFN.
- 4-4-94 Safety meeting. Service rig. ND wellhead, NU BOP. POH and LD 87 jts 1" tubing. PU 2" work tubing and RIH with open ended tubing to 1858'. Load hole with 40 bbls water. Plug #1 from 1858' to 1415' with 30 sx Class B cement over PC perfs. POH with tubing. WOC. SDFN.
- Safety meeting. Open up well, no pressure. TIH with tubing and tag cement @ 1742'. POH to 1735'. Load hole with 15 bbls water, pressure test csg to 500 psi, held ok. Spot 3 bbls of 8.4# 40 vis mud from 1735' to 1520'. POH to 1520'. Plug #2 from 1520' to 1363' with 11 sxs Class B cement inside casing. POH to 1243'; mix and spot 7 bbls of 8.4# 40 vis mud from 1243' to 770'. POH and LD tubing. Perforate 4 holes @ 765'. Repair pump truck. Attempt to pump into holes, pressured up to 1000#. Perforate 4 holes @ 675'. Attempt to pump into holes, pressured up to 1000#. Procedure change approved by W. Townsend, BLM. TIH with open ended tubing to 772'. Plug #3 from 772' to 500' with 18 sxs Class B cement inside casing. POH and LD tubing. WOC. SDFN.
- Safety meeting. TIH and tag cement @ 505'. POH to 500'; mix and spot 5 bbls 8.4# 40 vis mud from 500' to 160'. POH and LD tubing. Procedure change approved by W. Townsend with BLM. Perforate 4 holes @ 165'. Establish circulation with 8 bbls water out bradenhead. Plug #4 from 165' to surface with 67 sxs Class B cement, circulated 1 bbl of good cement out bradenhead. Shut well in. WOC. ND BOP. Cut wellhead off. Install P&A marker. Rig down and move off.

  Joe Rulabid with BLM was on location.