			Form app: Budget Bi	roved. ureau No. 1004-0135
omi 3160-5 November 1983)	UNITED STATES	SUBMIT IN TRIPLICATE* (Other instructions on re-	Expires A	ugust 31, 1985
Formerly 9–331) DE	PARTMENT OF THE INTERI	OR verse side)	5. LEASE DESIGN	VATION AND BERIAL NO.
	BUREAU OF LAND MANAGEMENT	Γ	14-20-6	03-2198
			6. IF INDIAN, AL	LOTTEE OR TRIBE NAME
(Do not use this form f	NOTICES AND REPORTS Of proposals to drill or to deepen or plug by APPLICATION FOR PERMIT—" for such proposals to drill or to deepen or plug by APPLICATION FOR PERMIT—"	ack to a different reservoir.	Navajo	Tribe 30-c45-1316
	ATT MICH TO THE TOTAL THE TOTAL TO THE TOTAL THE TOTAL TO THE TOTAL TH		7. UNIT AGREEM	ENT NAME
WELL GAS X	OTHER			
NAME OF OPERATOR		4 0 4 0 -	8. FARM OR LEA	•
Robert L.	Bayless NITN. STA	to pet Cyp.	Navajo`	Н
ADDRESS OF OPERATOR			9. WELL NO.	
P O Boy	168, Farmington, NM 87499	9	5	
LOCATION OF WELL (Report	location clearly and in accordance with any	State requirements.*	10. FIELD AND P	POOL, OR WILDCAT
See also space 17 below.) At surface 705' FSL & 660' FWL			Undesig	nated Mesa Verde
			11. SEC., T., B.,	M., OR BLK. AND
			SURVEY O	R ARZA
			N. Contion	12 2201 1141
	(C) =	. nn on oto		13, T29N, R14W
4. PERMIT NO.	15. ELEVATIONS (Show whether DF			
	5278 GL 52	287' RKB	San Jua	n NM
6. CI	neck Appropriate Box To Indicate N	Nature of Notice, Report, or C	Other Data	
	OF INTENTION TO:		ENT REPORT OF:	
	7		٦	
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	-	IRING WELL
FRACTUBE TREAT	MULTIPLE COMPLETE	FRACTURE TREATMENT	-[RING CASING
SHOOT OR ACIDIZE	ABANDON*	SHOOTING OR ACIDIZING	ABAN	DON MENT*
REPAIR WOLL	CHANGE PLANS	(Other)	of multiple comm	Notice of Well
(Other)		(Note: Report results Completion or Recompl		
We plan to aba	ndon this well using the a	ttached procedure.		
	<i>r</i>			-
			. :	
		DECEIVER		(a) (a)
			1	
		UU APR - 9 1997	7 - 3	
		5	الم	
		AM GAM DOW	. ن چ	્ છ
		OIL GON. DIV.	5	ah Si
	9			
8. I hereby certify that the	oregoing is true and correct			
SIGNED Tany	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	troleum Engineer	DATE	3/12/97
(This space for Federal	State office use) Duane W. Spencer			APP - 7 1997
APPROVED BY TITLE CONDITIONS OF APPROVAL, IF ANY:			DATE	

*See Instructions on Reverse Side

ROBERT L. BAYLESS ABANDONMENT PROCEDURE NAVAJO H NO. 5

- 1. Check for rig anchors, if necessary. Move in tank or rig pit. Haul an extra 20 joints 2 3/8" tubing to location.
- 2. Move in and rig up pulling unit. Blow well down to pit. Kill well if necessary. Rig up BOP.
- 3. Trip out and tally 2 3/8" tubing.
- 4. Trip in with tubing to 3370', (pick up extra tubing if necessary.) Load hole with water. Spot a 12 sx. Class B cement plug. Wait on cement. Tag top of plug, (it should be at about 3220'.)
- 5. Trip out to 950'. Spot a 24 sx. Class B cement plug. Wait on cement. Tag top of plug, (it should be at about 650'.)
- 6. Trip out with tubing. Rig up to perforate. Perforate 2 squeeze holes at 255'.
- 7. Pump water down casing and establish circulation through bradenhead valve. Pump about 75 sx Class B cement or until cement circulates. Wait on cement.
- 8. Nipple down BOP and cut off wellhead. Install P&A marker. Rig down and move out rig. Haul away fluids as necessary. Restore location.