/							Form C-10	12
Submit 3 Copies To Appropriate District	State of New Mexico			Revised March 25, 1999				
Office District I	Energy, Minerals and Natural Resources			WELL API NO.				Ϋ́
1625 N. French Dr., Hobbs, NM 87240 District II	OIL CONSERVATION DIVISION			30-045-24438				_
811 South First, Artesia, NM 87210	2040 South Pacheco			5. Indicate Type of Lease				1
District III 1000 Rio Brazos Rd., Aztec, NM 87410	Santa Fe, NM 87505			STATE FEE X				_
District IV 2040 South Pacheco, Santa Fe, NM 87505		1		6. State Oil	& Gas L	ease No.		
	ES AND REPORTS ON	WEL		7 Lease Na	me or U	nit Agree	ment Name:	$\dashv$
(DO NOT USE THIS FORM FOR PROPO DIFFERENT RESERVOIR. USE "APPLIC PROPOSALS.)	SALS TO DRILL OR TO DEE	PEN O	HHPUOIGEBANGKIOA	7. Lease Iva	inc or o	mi rigice	ment rame.	
1. Type of Well: Oil Well Gas Well X	Other		SULLIVAN FRAME COM B				ļ	
2. Name of Operator	Outer 7			8. Well No.				7
XTO Energy Inc.				#1				
3. Address of Operator				Pool name or Wildcat     BLANCO MESAVERDE/OTERO CHACRA				ŀ
2700 Farmington Ave., Bldg. 4. Well Location	K. Ste 1 Farmington,	NM 8	7401	I DIRIYCO ME	القار المدار المدا	OIMO C	alracata	7
	117F Coat Coas the	NOR	TH line and	880 1	eet from	the	WEST lir	ne
Unit Letter:	1175 feet from the	1401	inie and	<del></del> -	ect mom			
Section 30	Township 29	N	Range 10W	NMPM_	10000000	County	san <b>Juan</b>	***
	10. Elevation (Show wh		DR, RKB, RT, GR, et	c.)				
11 Check	Appropriate Box to Ind			Report, or	Other I	Data		
NOTICE OF INT		iouto	SUB	SEQUEN	T REP	ORT O	F:	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	x	REMEDIAL WORK	02402.1			NG CASING	
TEMPORARILY ABANDON	CHANGE PLANS		COMMENCE DRILL	ING OPNS.		PLUG A	AND ONMENT	
PULL OR ALTER CASING	MULTIPLE COMPLETION		CASING TEST AND CEMENT JOB			ADAIL	Offiner	
			OTHER:					Г
OTHER:	10 (01-11-11-11-11-11-11-11-11-11-11-11-11-1	11		rive pertinent	dates in	cluding e	stimated date	
12. Describe Proposed or Complete of starting any proposed work). or recompilation.	SEE RULE 1103. For M	e an p ultiple	Completions: Attacl	n wellbore dia	igram of	proposed	l completion	
XTO Energy Inc. plans to	have A Plus Well Serv	ice t	urnkey P&A this w	ell per the	eir atta	ched pr	ocedures	
XIO Energy Inc. plans to	nave A Plus Meli Serv	ice t	onine, rur and	<b>-</b>		<b>-</b>		
I hereby certify that the information above	ve is true and complete to the	best of	my knowledge and beli	ief.				_
ν	) 4						. (0.0. (0.0.	
SIGNATURE Kay 1	Carla	_ TIT	LE OPERATIONS ENG	INEER		DATE	4/22/02	
Type or print name RAY MARTIN					Telepho	ne No.	505-324-109	<u>,,,                                  </u>
(This space for State use)	NO DE ANALUS PROPEN					API	ີ່ວາກາ	12
APPROVED BY			AND THE PARTY OF T	مع∧ حادات ای	Sec. 31	. 16 1		!Z

# PLUG AND ABANDONMENT PROCEDURE

3/19/02

### Sullivan Frame Com B #1

Otero Chacra 1175' FNL & 880' FWL, Section 30, T29N, R10W San Juan County, New Mexico, API #30-045-24438

Note: All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures. All cement will be ASTM Type II, mixed at 15.6 ppg with a 1.18 cf/sx yield.

- Install and test location rig anchors. Prepare blow pit. Comply with all NMOCD, BLM, and XTO safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. NU relief line and blow down well; kill with water as necessary. ND wellhead and NU BOP. Test BOP.
- 2. TOH and tally 83 joints 1-1/2" EUE tubing total 2801'. RIH with 7" gauge ring or casing scraper and tag PBTD at 2925' or as deep as possible.
- 3. Plug #1 (Chacra perforations and top, 2652' 2552'): TIH and set a 7" cement retainer at 2652'. Pressure test tubing to 1000#. Load casing with water and circulate the well clean. Pressure test casing to 500#. If casing does not test, then spot or tag subsequent plugs as appropriate. Mix 28 sxs cement and spot a balanced plug inside above the CR to isolate the Chacra perforations and to cover the top. PUH to 1755'.
- 4. Plug #2 (Pictured Cliffs top, 1755' 1655'): Mix 28 sxs cement and spot a balanced plug inside casing to cover the Pictured Cliffs top. PUH to 1400'. If the casing leaks may combine plugs #2 and #3.
- 5. Plug #3 (Fruitland top, 1400' 1300'): Mix 28 sxs cement and spot a balanced plug inside casing to cover Fruitland top. PUH to 675'.
- Plug #4 (Kirtland and Ojo Alamo tops, 675' 450'): Mix 52 sxs cement and spot a balanced plug inside casing to cover the Kirtland and Ojo Alamo tops. PUH to 347'.
- 7. Plug #5 (9-5/8" casing shoe, 347' Surface): Pressure test the bradenhead to 500#. With the tubing at 347', establish circulation out the casing valve. Mix 75 sxs cement and spot a balanced plug inside casing from 347' to surface, circulate good cement out casing valve. TOH and LD tubing. Shut in well and WOC.
- 8. ND BOP and cut off casing below surface casing flange. Install P&A marker with cement to comply with regulations. RD, move off location, cut off anchors and restore location.

# Sullivan Frame Com B #1

#### Current

Otero Chacra / API #30-045-24438

NW, Section 30, T-29-N, R-10-W, San Juan County, NM Today's Date: 3/19/02 Spud: 9/15/80 Comp: 11/4/80 Elevation: 5466' GL 12-1/4" Hole Ojo Alamo @ 500' Kirtland @ 625' Fruitland @ 1350' Pictured Cliffs @ 1705' Chacra @ 2683' Chacra Perforations: 2702' -2803' Baker "D" Packer @ 2990' DV Tool at 3205' Mesaverde @ 3275' Mesaverde Perforations:

8-3/4" Hole

Cement circulated to surface, (calc 50% efficiency)

9-5/8" 36#, K-55 Casing set @ 297' 300 sxs cement (Circulated to Surface)

#### Well History

Oct '80: Bradenhead tested to 500#, but bleed down to 400#. Had some gas pressure.

Jan '95: Plug MV Zone: Found MV tubing with heavy corrosion and parted at 2925'. Ran casing inspection log. Set CR at 2925' and squeezed off MV with ? sxs. Swabbed Chacra zone and landed tubing at 2801'.

Oct '00: Swabbed Chacra zone for 3 days: made 25 runs and recovered 25 bbls fluid.

1-1/2' Tubing set at 2801' (83 joints, 2.9#, EUE)

Cmt Retainer set at 2925' (1995)

Cement with 875 sxs (1444 cf), good returns while cementing, but not reported to have circulated to surface.

3625' - 4272' P&A'd in 1995

7" 23#, K-55 Casing at 4529' Cement with 340 sxs (467 cf) circulated cement to surface before

# Sullivan Frame Com B #1

## Proposed P&A

Otero Chacra / API #30-045-24438

Today's Date: 3/19/02 Spud: 9/15/80 Comp: 11/4/80 Elevation: 5466' GL

12-1/4" Hole

Cement circulated to surface, (calc 50% efficiency)

9-5/8" 36#, K-55 Casing set @ 297' 300 sxs cement (Circulated to Surface)

> Plug #5: 347' - Surface Cement with 75 sxs

Plug #4: 675' - 450' Cement with 52 sxs

Plug #3: 1400' - 1300' Cement with 28 sxs

Plug #2: 1755' - 1655' Cement with 28 sxs

Set Cmt Ret @ 2652'

Plug #1: 2652' - 2552' Cement with 28 sxs

Chacra Perforations: 2702' -2803'

Cmt Retainer set at 2925' (1995)

Baker "D" Packer @ 2990'

DV Tool at 3205'

Cement with 875 sxs (1444 cf), good returns while cementing, but not reported to have circulated to surface.

Mesaverde Perforations: 3625' - 4272' P&A'd in 1995

7" 23#, K-55 Casing at 4529' Cement with 340 sxs (467 cf) circulated cement to surface before

Ojo Alamo @ 500'

Kirtland @ 625'

Fruitland @ 1350'

Pictured Cliffs @ 1705'

Chacra @ 2683'

Mesaverde @ 3275'

8-3/4" Hole

