In Lie	u of
Form	3160
(June	1990)

D

UNITED STATES DEPARTMENT OF INTERIOR BUREAU OF LAND MANAGEMENT

MODICE AND DEDODITE ON WELLS

FORM APPROVED
Budget Bureau No. 1004-013
Expires: March 31, 1993

Budget Bur	eau Ino	. IU	04-01.)
Expires:	March	31,	1993	

If Unit or CA, Agreement Designation

SUNDRY NUTICE AND REPORTS ON WELLS	
o not use this form for proposals to drill or to deepen or reentry to a different reservoir. TO DRILL!" for permit for such proposals	Use "APPLICATION
TO DRILL" for permit for such proposals	4.4

Lease Designation and Serial No. SF-078767

If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE Type of Well 1. Other Oil Well X Gas Well Name of Operator 2. WILLIAMS PRODUCTION COMPANY Address and Telephone No. 3. PO BOX 3102 MS 37-2, TULSA, OK 74101 (918) 573-6254 Location of Well (Footage, Sec., T., R., M., or Survey Description) 4 2090' FSL and 790' FEL NE/4 SE/4 SEC 06-31N-05W

Well Name and No. R ROSA UNIT #241

ROSA UNIT

API Well No. 9. 30-039-24511

5.

10.

Field and Pool, or Exploratory Area BASIN FRUITLAND COAL

County or Parish, State 11. RIO ARRIBA, NM

CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION		
Notice of Intent X Subsequent Report Final Abandonment	Abandonment Recompletion Plugging Back Casing Repair Altering Casing Other <u>Cavitation Complete</u>	Change of Plans New Construction Non-Routine Fracturing Water Shut-Off Conversion to Injection Dispose Water (Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well 13. is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

05-23-2000 Load out equip, road rig to loc. RU rig & spot equip. SICP = 800 psi, SITP = 30 psi. Blow well down. NDWH, NU BOP stack & HCR's. NU blooie lines & pres test stack to 2500 psi. POOH laying down w/99 jts 2 3/8" tbg. Tally in w/TIW ret tool, 10 DC's & 44 jts 3 ½" DP. Screw into & release hanger @ 2921'. TOOH w/liner, LD same. TIH w/underreamer. RU power swivel & break circ w/20 bph air/soap mist. Underream from 2990'- 3003'

05-24-2000 Underream from 3003'-3140' TD, circ clean. TOOH w/underreamer. TIH w/6 1/4" bit to 3140'(no fill). CO on bottom w/10 bph air/soap mist, med ret's = fine coal & black water. Blow well dry. PU bit to 3000'. Natural surge, 4 hr SI = 444 psi. Flow natural. Surge from 3000' (2 times) w/5 bbls air/soap mist ahead, pressure to 800 psi, ret's lite. Surge (2 times) w/ 5 bbls air/soap mist ahead, pres to 1000 psi, ret's lite

05-25-2000 Surge from 3000' (2 times) w/5 bbls air/soap mist ahead, pres to 1200 psi & (2 times) @ 1400 psi, lite ret's. Tag 20' of fill & CO. CO on bottom w/15 bph air/soap mist & 5 bbl sweeps, heavy ret's = 90% fine to 1/4" coal & 10% shale. Blow dry & PU bit to 2996'. Break over with air only @ 1660 psi, med ret's = fine coal dust. Tag 15' of fill & CO. CO on bottom, ret's heavy fine coal & black water, (coal running). Blow dry with air only

Continued on back I hereby certify that the foregoing is true and correct 14. Title Production Analyst Date June 26, 2000 (This space for Federal or State office use) Title Approved by_ Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, the mous or fraudulent statements or representations as to any matter within its jurisdiction.

05-26-2000 Blow dry w/air only. TOOH w/bit. Gauge well on 2", all gauges dry & avg 225 mcfd. Breakover w/air only @ 1350 psi, heavy ret's = fine to ¼" coal. Surge from surface (4 times) w/400# air ahead, pump 5 bbls air/soap mist, pres to 1200 psi w/air, heavy-med ret's = fine to ¼" coal. Natural surge 2 hr SI = 450 psi. ret's lite coal & heavy wtr. Flow natural. Natural surge, 4 hr SI = 530 psi, extra heavy ret's = fine to 2" size coal. Flow natural

05-27-2000 Natural surge, 2 hr si = 390 psi, ret's It & bridge off. TIH & tag/co bridges @ 2160', 2290', 2385' & 2995', tag 40' of fill & co. CO on bttm w/15 bph a/s mist & 5 bbl sweeps. Blow dry w/air only. TOOH w/bit. Natural surge, 4 hr si = 740 psi, hvy ret's = coffee grd to 1" size coal & trace shale. Flow natural. SI f/4 hr natural surge

05-28-2000 Natural surge f/surface (4 times), 1^{st} 4 hr si = 720 psi, 2^{nd} = 700 psi, 3^{rd} = 680 psi, 4^{th} = 620 psi, med-hvy rert's = 1/8" to 1" coal & hvy wtr. Flow natural 2 hrs each surge

05-29-2000 Natural surge, 4 hr SI = 630 psi, lt ret's = fine coal & hvy wtr. Flow natural, well bridged or logged off. Surge w/air only to 1200 psi, lt ret's = fine coal & hvy wtr. TIH & tag 40' of fill @ 3100'. CO to TD w/15 bph air/soap mist. CO on bttm w/15 bph a/s mist & 5 bbl sweeps, hvy ret's = 90% fine to %" size coal & 10% shale

05-30-2000 CO on bottom. Blow dry w/air only. TOOH w/bit. Flow natural, gauge well on 2" line, all gauges med mist & avg 552 mcfd.

Natural surge, 4 hr si = 780 psi, ret's heavy coal & heavy wtr. Natural surge, 2 hr si = 540 psi, ret's med coal & heavy wtr. Flow natural, well loading up & unloading heavy water w/fine coal. Natural surge, (2 times) 1st 4 hr si = 800 psi, 2nd 2 hr si = 540 psi, ret's med coal & heavy wtr

05-31-2000 Flow natural. Natural surge, 4 hr si = 740 psi, hvy ret's. Surge f/surface w/2 bbls & 1 gal soap ahead, pres to 1340 psi w/air only, hvy ret's = dust to ¼" dry coal. Natural surge, 2 hr si = 360 psi, ret's lt & bridge off. Pres bridge up w/2 bbls & 1 gal soap ahead, pres to 1500 psi w/air only, hvy ret's. Flow nat, ret's hvy black wtr w/fine coal. Natural surge, 4 hr si = 680 psi, extra hvy ret's = ¼" to 2" size coal, plug both blooie lines. Pump wtr to unplug blooie lines & bridges in csg. Flow natural

06-01-2000 Natural surge, 2 hr si = 420 psi, ret's hvy coal, bridge off. TiH & tag/CO bridges @ 1562', 1873', 2404' & 2965'. CO f/2965'-3140' TD w/15 bph air/soap mist & 5 bbl sweeps, ret's heavy coal. CO on bottom w/20 bph a/s mist, heavy – med ret's = dust to coffee ground size coal

06-02-2000 CO on bottom w/20 bph air/soap mist & 5 bbl sweeps. Blow dry w/air only. TOOH w/bit. Attempt to gauge well on 2", well loading up & unloading heavy water out 2". Natural surge, 4 hr si = 780 psi, ret's heavy water & lite coal fines. SI for natural surge

06-03-2000 Natural surge, 4 hr si = 800 psi, ret's heavy coal & heavy wtr, flow nat. Natural surge, 3 hr si = 660 psi, ret's heavy coal & water, flow nat. Natural surge, 2 hr si = 610 psi, lite ret's & bridge off. Surge from surface w/air only (5 times) pressure to 850 psi, heavy ret's = coffee to ½" size coal, well unloading on own. Flow natural. Natural surge, 4 hr si = 830 psi, ret's heavy coal & lite water

06-04-2000 Natural Surge, 2 hr si = 540 psi, ret's heavy coal & water. Flow natural. Natural surge, 4 hr si = 660 psi, flow nat & bridge off. TIH & tag bridge @ 3025'. CO from 3025'- 3120' w/15 bph air/soap mist & 5 bbl sweeps, heavy ret's = 75% coal & 25% shale. Bridge off & get tight, PU bit to 3050'. CO from 3050'- 3110' w/15 bph air/soap mist, heavy ret's

06-05-2000 CO f/3110', bridge off & get tight. PU bit to 2996' & break circ. CO & work on ratty open hole from 3010'- 3059' w/15 bph air/soap mist, ret's heavy shale

06-06-2000 CO from 3059'- 3140' (TD) w/20 bph air/soap mist, heavy ret's = 50% coal & 50% shale. CO on bottom w/20 bph a/s mist, ret's med fine coal & ¼" shale. Attempt to blow dry, bucket test = 10.5 bph. TOOH w/bit. Flow natural, well unloading heavy black water. Natural surge, 4 hr si = 730 psi, ret's heavy coal & water. Flow natural, ret's heavy water w/fine coal

06-07-2000 Natural surge (4 times) 1st 4 hr si = 740 psi, heavy ret's = fine to 2" size coal. 2nd 4 hr si = 740 psi, ret's extra heavy coal & shale, plug blooie lines. 3rd 3 hr si = 700 psi, ret's heavy fine to 2" size coal & ½" shale. 4th 3 hr si = 680 psi, ret's heavy coal & shale. Flow natural 2 hrs each surge, ret's steady 2" flow of formation water w/fine coal

06-08-2000 Natural surge f/surface (5 times) 1st 3 hr si = 680 psi, 2nd = 700 psi, 3rd = 710 psi, extra hvy ret's = fine to 3" size coal, 4th 3 hr si = 740 psi, 5th = 740 psi, med-hvy rets = fine to 1.5" coal. Flow natural 2 hrs each surge


06-09-2000 Natural surge, 3 hr si = 500 psi, ret's lite & bridge off. Surge w/air to break bridge & pack off. TIH & tag, CO bridge @ 2330'. Continue in with bit & tag bridge @ 2986'. CO from 2986'- 3096' w/15 bph air/soap mist & 5 bbl sweeps, ret's heavy coal & shale

06-10-2000 CO from 3096' - 3140' (TD) w/20 bph air/soap mist & 5 bbl sweeps, ret's heavy shale & med fine to $\frac{1}{2}$ " coal. CO from 3140' w/20 bph a/s mist & 5 bbl sweeps, ret's med fine to $\frac{1}{4}$ " coal

06-11-2000 CO from 3140' (TD) w/20 bph air/soap mist & 5 bbl sweeps, ret's med fine coal. Attempt to blow dry w/air only, bucket test = 3.5 bph. PU bit to 2970'. Flow natural. Gauge well on 2" open line, all gauges heavy mist & avg 1388 mcfd. TIH & tag/CO 5' of fill from 3135'-3140'. CO from 3140' w/15 bph air/soap mist, ret's lite fine coal & lite shale. TOOH laying down w/dc's, CO to run 5 ½"

06-12-2000 MU hanger, TIH w/5 ½" liner, tag 8' of fill @ 3132'. Wash liner down to 3140' w/10 bph air/soap mist. Set hanger @ 2905' KB. POOH laying down 3 ½" DP. Tally in with 4 ¾" mill & 97 jts 2 3/8" tbg. Mill off perfs from 3002'- 3139'. TOOH w/mill. TIH w/prod tbg. Unload well w/air. Land tbg in hanger @ 3090' KB w/99 jts total. NDBOPs & bloole lines, NUWH. Gauge well on 2" open line, all gauges lite mist & avg 1065 mcfd. Turn well to production department, release rig

ROSA UNIT #241 FRUITLAND COAL



Total Depth @ 3140'

Hole Size	Casing	Cement	Volume	Top of CMT
12-1/4"	9-5/8", 40#	160 sx	189 cu. Ft	Surface
8-3/4"	7", 23#	660 sx	1009 cu. Ft	Surface
6-1/4"	5-1/2", 15.5#	n/a	n\a	n/a