Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR

BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0135

	Expi	res:	Nove	nber	30
ease	Serial	No.	,		

•2•	Lease serial IND.
	NMSF - 076337

SUNDKY N	UTICES AND REPORTS ON WELLS
Do not use this	form for proposals to drill or to re-enter an
	Use form 3160-3 (APD) for such proposals

abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name		
SUBMIT IN TRI	PLICATE - Other instruc	ctions on rever	se side.		7. If Unit or CA/Ag	reement, Name and/or No.	
1. Type of Well			W.18 2003	——————————————————————————————————————	8. Well Name and N	0	
Oil Well 🛛 Gas Well 🔲 Ott	her	* * * * * * * * * * * * * * * * * * *		\$1	W D HEATH B	1	
2. Name of Operator BP AMERICA PRODUCTION	MARY CORLE E-Mail: corleym@						
3a. Address P.O. BOX 3092 HOUSTON, TX 77253	3b. Phone No. (include area code) Ph: 281.366.4491 Fx: 281.366.0700			10. Field and Pool, or Exploratory BLANCO MESAVERDE			
4. Location of Well (Footage, Sec., 7	., R., M., or Survey Description)			11. County or Parisi	ı, and State	
Sec 31 T30N R9W NENE 990					SAN JUAN COUNTY, NM		
12. CHECK APPI	ROPRIATE BOX(ES) TO	O INDICATE N	ATURE OF	NOTICE, RI	EPORT, OR OTH	ER DATA	
TYPE OF SUBMISSION							
Notice of Intent ■ Notice of Intent Not	☐ Acidize	☐ Deeper	☐ Deepen		ion (Start/Resume)	☐ Water Shut-Off	
Notice of Intent	☐ Alter Casing	=	☐ Fracture Treat		ation	□ Well Integrity	
☐ Subsequent Report	☐ Casing Repair	□ New C	onstruction	☐ Recomp		☑ Other	
☐ Final Abandonment Notice	☐ Change Plans		☐ Plug and Abandon		arily Abandon	Z Cuiter	
	☐ Convert to Injection ☐ Plug Back		_	□ Water Disposal			
determined that the site is ready for fi BP America respectfully reque Menefee and Lewis Shale forn	est permission to add nav	by perforating a erde Pool as pe	ind fracture si	timulating the			
14. I hereby certify that the foregoing is	true and correct. Electronic Submission # For BP AMERICA PR	10823 verified by	the BLM WellPANY, sent t	I Information o the Farming	System yton		
Name (Printed/Typed) MARY CORLEY			Title AUTHORIZED REPRESENTATIVE				
Signature (Electronic S	$\overline{}$	<u></u>	ate 03/19/2	002			
	THIS SPACE FO	R FEDERAL	OR STATE	OFFICE US	SE 		
	/ Jim Lovato		Title		Date	MAR 2 5 2002	
Conditions of approval, if any, are attached certify that the applicant holds legal or equ which would entitle the applicant to condu	utable title to those rights in the	not warrant or subject lease	Office				

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

WD Heath GC B 1 Payadd Procedure

Sec 31, T30N, R9W API #: 30-04509042

- 1. Check anchors. MIRU workover rig.
- 2. Kill with 2% KCL water if necessary. Nipple down WH. NU BOPs and diversion spool with 3" outlets and 3" pipe to the blow tank. Pressure test BOPs to 500 psi.
- 3. Tag for fill and tally OH with 2-3/8" production tubing. Visually inspect tubing while POOH.
- 4. TIH with bit and scraper for 4 1/2" liner to 4650'.
- 5. TIH with tubing-set RBP. Set RBP at 4100'. Load hole with 2% KCL.
- 6. Pressure test casing to 2500 psi. Unset RBP and POH.
- 7. RIH with CIBP and 3-1/8" casing guns 1 SPF 120 deg phasing with Schlumberger's Prospector, select-fire charge. Set CIBP at 4680'. Perforate Menefee and Lewis shale (correlate to GR log).
- 8. RIH with 2-3/8" frac string with retrievable packer. Set packer at 4300'
- 9. RU frac equipment and install wellhead isolation tool. Use 2% KCL-N2 foam in fracture stimulation.
- 10. Frac Menefee according to pump schedule.
- 11. Flowback frac fluid immediately.
- 12. POH with frac string.
- 13. RIH and set CIBP at 4100'
- 14. Breakdown each Lewis perforation interval with hydrochloric acid.
- 15. RU frac equipment and install wellhead isolation tool. Use 2% KCL-N2 foam in fracture stimulation.
- 16. Frac the Lewis shale according pump schedule.
- 17. Flowback frac fluid immediately.
- 18. TIH with tubing and bit. Cleanout fill and drill bridge plugs set at 4100' and 4680'. Clean out fill to PBTD at 4826'. Blow well dry at PBTD.

- 19. RIH with 2-3/8" production tubing and land at 4790'.
- 20. Swab water from the tubing with the sandline.
- 21. ND BOP's. NU WH. Test well for air. Return well to production.