Form 3160-5 (June 1990)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993
5. Lease Designation and Serial No.

		SF-078139
SUNDRY NOTICES AND REPORTS ON WELLS		6. If Indian, Allottee or Tribe Name
	or to deepen or reentry to a different reservoir.	
Use "APPLICATION FOR	PERMIT—" for such proposals	
SUBMIT IN TRIPLICATE		7. If Unit or CA, Agreement Designation
1. Type of Well		
Oil Well Well Other		8. Well Name and No.
2. Name of Operator		Federal B #1
Amoco Production Company Attn: John Hampton J. Address and Telephone No.		30 045 09118
	00201	10. Field and Pool, or Exploratory Area
P.O. Box 800, Denver, Colorado 80201 4. Location of Well (Footage, Sec., T., R., M., or Survey Description)		Basin Dakota
200000000000000000000000000000000000000		11. County or Parish, State
900' FSL, 1650' FEL, Sec. 28, T30N-R11W		
		San Juan, New Mexico
OUTOK ADDDODDIATE DOV/-	TO INDICATE NATURE OF NOTICE DEDC	ORT OR OTHER DATA
12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPO	oni, on other bara
TYPE OF SUBMISSION	TYPE OF ACTION	
X Notice of Intent	Abandonment	Change of Plans
Touce of Inten	Recompletion	New Construction
Subsequent Report	Plugging Back	Non-Routine Fracturing
	Casing Repair	Water Shut-Off
Final Abandonment Notice	Altering Casing	Conversion to Injection
	M Other BradenHead Repair	Dispose Water
	·	(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)
13. Describe Proposed or Completed Operations (Clearly state all	pertinent details, and give pertinent dates, including estimated date of star	ting any proposed work. If well is directionally drilled,
give subsurface locations and measured and true vertice	al depths for all markers and zones pertinent to this work.)*	
	tached workover procedure required t	to eliminate
bradenhead pressure.		•
		0
In addition Among also regular	ts approval to construct a temporary	
roturn fluide This nit will h	pe reclaimed if utilized, upon comple	etion of This procedure.
recum ridios. This pre will i	se rectained if defilized, apost compac	
i e e e e e e e e e e e e e e e e e e e		ECI BB 24
·*I	 	
ĺ.		NED NETON.
}	DECEIAEU	₩ - D
	IM SA	z 0
	CEP 3 1992	RECEIVED BLM 6 24 PM I: 06 RHINGTON, N.M
	SEP 3 1992	W. M. 90
	SEP 3 1992	90 :
	MAN TO SERVICE OF THE	90 H
		. N.M
14. I hereby certify that the foregoing is true and correct	,	•
(1) 1/2 1/2	MAN TO SERVICE OF THE	APBROYEDD
Signed John Nangolon / 3 29	,	•
(1) 1/2 1/62	,	APBROVEDO

NMOCD


of willfully to make to say demanders to

t the Matte to the constant of the Mark to when the

FEDERAL B #1 - DAKOTA COMPLETION 280-30N-11W BRADENHEAD REPAIR PROCEDURES

- 1. Contact Federal or State agency prior to starting repair work.
- 2. Locate anchors and test, or install if necessary.
- MIRUSU. Check and record tubing, casing and bradenhead pressures.
- 4. Blow well down and kill well, if necessary, with 2% KCL water.
- 5. NDWH. NUBOP's and test.
- TIH and tag PBTD to check for fill. Tally OOH w/tbg, visually inspecting and replacing bad joints as necessary.
- 7. TIH w/bit and scraper to top of perforations. TOOH.
- 8. TIH w/RBP x pkr. Set RBP at 6700'. TOOH one joint and set packer. Pressure test RBP to 2000#.
- 9. Pressure test casing above packer to 2000#. If casing does not test, continue. Otherwise contact Sandi Braun at X5245 for further procedures.
- 10. Isolate leak and establish injection rate and pressure into leak. Attempt to circulate to surface.
- 11. Release pkr, spot sand on RBP and TOOH w/pkr.
- 12. RIH w/pkr or cement retainer depending on depth of hole and circulating pressure.
- 13. Mix and pump sufficient cement (at least 100% excess) to achieve cement returns at surface. Shut bradenhead valve and attempt to obtain a 1000# squeeze pressure: WOC.
- 14. TIH w/bit and scraper and DO cmt. Pressure test casing to 2000#. TOOH w/bit and scraper.
- 15. TIH w/retrieving head and circulate sand off RBP and latch onto plug and POOH.
- 16. TIH and CO to PBTD, if necessary.
- 17. TIH w/muleshoe, SN one joint above and production string. Land tubing at 6900'.
- 18. NDBOP and NUWH.
- 19. Swab well in and return to production.
- 20. RDMOSU.

FEDERAL B #1 LOCATION -280 30N 11W SINGLE DK ORIG.COMPLETION - 1/64 LAST FILE UPDATE - 1/92 BY CSW



LOGS: IES - 6500'- SURF - 1/3/64