UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells			
	5.	Lease Number SF-077764	
l. Type of Well GAS	6.	If Indian, All. or Tribe Name	
	7.	Unit Agreement Name	
. Name of Operator			
MERIDIAN OIL	8.	Well Name & Number	
. Address & Phone No. of Operator		Schumacher #1	
PO Box 4289, Farmington, NM 87499 (505) 326-9700	9.		
	30-045-09511		
. Location of Well, Footage, Sec., T, R, M	10.	Field and Pool Blanco Mesaverde	
1750'FNL, 1650'FEL, Sec.17, T-30-N, R-10-W, NMPM	11.	County and State San Juan Co, NM	
2. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE,	REPORT, OTHER	DATA	
Type of Submission Type of Action			
X Notice of Intent Abandonment	Change of Pla		
Recompletion	New Construct	ion	
Subsequent Report Plugging Back	Non-Routine F	racturing	
	F.7 - 4		
Casing Repair	Water Shut of	f Injection	
	Water Shut of	ff Injection	
Casing Repair	Water Shut of	f Injection	
	Water Shut of	f Injection	
Final Abandonment Casing Repair Altering Casing X Other - Pay add 3. Describe Proposed or Completed Operations	Water Shut of Conversion to		
Final Abandonment Final Abandonment X Other - Pay add Casing Repair Altering Casing X Other - Pay add The proposed or Completed Operations It is intended to add pay the producing Mesaverde	Water Shut of Conversion to	the subject well	
Final Abandonment Casing Repair Altering Casing X Other - Pay add 3. Describe Proposed or Completed Operations	Water Shut of Conversion to	the subject well	
Final Abandonment Final Abandonment X Other - Pay add Casing Repair Altering Casing X Other - Pay add The proposed or Completed Operations It is intended to add pay the producing Mesaverde	Water Shut of Conversion to	the subject well	
Final Abandonment Final Abandonment X Other - Pay add Casing Repair Altering Casing X Other - Pay add The proposed or Completed Operations It is intended to add pay the producing Mesaverde	Water Shut of Conversion to	the subject well	
Final Abandonment Final Abandonment X Other - Pay add Casing Repair Altering Casing X Other - Pay add The proposed or Completed Operations It is intended to add pay the producing Mesaverde	Water Shut of Conversion to	the subject well	
Final Abandonment Final Abandonment X Other - Pay add Casing Repair Altering Casing X Other - Pay add The proposed or Completed Operations It is intended to add pay the producing Mesaverde	Water Shut of Conversion to	the subject well	
Final Abandonment Final Abandonment X Other - Pay add Casing Repair Altering Casing X Other - Pay add The proposed or Completed Operations It is intended to add pay the producing Mesaverde	Water Shut of Conversion to	the subject well	
Final Abandonment — Casing Repair Altering Casing X Other - Pay add 3. Describe Proposed or Completed Operations It is intended to add pay the producing Mesaverde according to the attached procedure and wel	Water Shut of Conversion to	the subject well	
Final Abandonment The state of the proposed of the producing Mesaverde according to the attached procedure and well in the state of the attached procedure and well in the state of the attached procedure and well in the state of the attached procedure and well in the state of the attached procedure and well in the state of the s	Water Shut of Conversion to	the subject well	
Final Abandonment — Casing Repair Altering Casing X Other - Pay add 3. Describe Proposed or Completed Operations It is intended to add pay the producing Mesaverde according to the attached procedure and well DEC	formation of the libore diagram	the subject well	
Final Abandonment — Casing Repair Altering Casing X Other - Pay add 3. Describe Proposed or Completed Operations It is intended to add pay the producing Mesaverde according to the attached procedure and well DEC	formation of the libore diagram	the subject well	
Final Abandonment — Casing Repair Altering Casing X Other - Pay add 3. Describe Proposed or Completed Operations It is intended to add pay the producing Mesaverde according to the attached procedure and well DEC OIL Co	formation of the libore diagram 1 5 1995	the subject well	
Final Abandonment — Casing Repair Altering Casing X Other - Pay add 3. Describe Proposed or Completed Operations It is intended to add pay the producing Mesaverde according to the attached procedure and well DEC OIL Co	formation of the libore diagram	the subject well	
Final Abandonment — Casing Repair Altering Casing X Other - Pay add 3. Describe Proposed or Completed Operations It is intended to add pay the producing Mesaverde according to the attached procedure and well DEC OIL CO	formation of the libore diagram 1 5 1995 ONo DIVA	the subject well	
Final Abandonment — Altering Casing — X Other - Pay add 3. Describe Proposed or Completed Operations It is intended to add pay the producing Mesaverde according to the attached procedure and well DEC OIL Co	formation of the libore diagram 1 5 1995 ONo DIVA	the subject well	
Final Abandonment — Casing Repair Altering Casing — Other - Pay add 3. Describe Proposed or Completed Operations It is intended to add pay the producing Mesaverde according to the attached procedure and well DEC OIL CO	formation of the libore diagram 1 5 1995 ONO DIVO	the subject well Sign M MAIL ROOM ON WELLINGTON, NM	
Final Abandonment This intended to add pay the producing Mesaverde according to the attached procedure and well according to the attached procedure and well to the attached procedure and well according to the attached procedure and the attached procedure according to the attached procedure and the attached procedure according to the attached procedure	formation of the libore diagram 1 5 1995 ONo DIV.	the subject well ON PARCELVED ON PARCE 12/4/95 Date 12/4/95	
Final Abandonment — Final Abandonment — Altering Casing — Nother - Pay add 3. Describe Proposed or Completed Operations It is intended to add pay the producing Mesaverde according to the attached procedure and well DEC OIL Completed Operations It is intended to add pay the producing Mesaverde according to the attached procedure and well OIL Completed Operations It is intended to add pay the producing Mesaverde according to the attached procedure and well OIL Completed Operations	formation of the libore diagram 1 5 1995 ONO DIVO	the subject well Sign M MAIL ROOM ON WEST -5 PH12: 39	

DISTRICT MANAGER

Pertinent Data Sheet -Schumacher #1

Location: NE/4 1750' FNL. 1650' FEL. Unit G. Section 17, T30N, R10W,

Lat. 36.814346, Long. 107.903534 by TDG

San Juan County, New

Field: Blanco Mesaverde Elevation: 6434' GL

KB: 10'

TD: 5842'

PBTD: 5797'

Spud Date: 08-31-51 **Completed:** 02-02-52

DP No: 47991A

Prop. No: 012588100

Fed. No: SF 077764

Casing/Liner Record:

Hole Size	Csg Size	Wt. & Grade	Depth Set	<u>Cement</u>	Top/Cement
12 1/4"	10 3/4"	30# SW	250'	150 SX	to surface
8 3/4°	7"	20# J-55	5111'	200 SX	TOC unknown
		Squeeze @	1770'	150 SX	500' (TS)
6 1/4"	4 1/2"	10.5# J-55	5812'	150 SX	2900' (TS)

Tubing Record: 2 3/8" 4.7 # J-55 tubing set at 5607'. Seating Nipple @ 5575'.

Formation Tops:

4600' Ojo Alamo: 1650' Cliff House: Kirtland: 4792' 1767' Menefee: Fruitland: 2608' Point Lookout: 5287'

Pictured Cliffs: 30051

Logging Record: Cased Hole Comp., Neutron, Temp. Survey

Stimulation: Originally shot open hole with 1248 quarts of SNG.

Workover History:

Sidetracked 09-30-85 @ 5125'.

Squeezed Ojo Alamo @ 1770' with 150 SX of cement. TOC @ 500' by T.S.


Sand water fractured Lower Point Lookout 5487'-5661' with 81,200 gallons of water and 58,000# of sand.

Sand water fractured Massive Point Lookout 5304'-5460' with 97,200 gallons of water and 46,000# of sand.

SCHUMACHER #1

AS OF 7/14/95 BLANCO MESAVERDE

1750' FNL, 1650' FEL C 17 T30N R10W SAN HIAN COUNTY NM



Schumacher #1 - Mesaverde

Cliffhouse and Menefee Payadd Lat-Long by TDG: 36.814346 - 107.903534 NE/4 Section 17, T30N-R10W August 24, 1995

- Hold safety meeting. MIRU. Comply with all MOI, BLM and NMOCD rules and regulations. Install 13 frac tanks and 1x400 bbl rig tank. Fill each frac tank with 5#'s of biocide and filtered (25 micron) 1% KCl water.
- 2. Obtain and record all wellhead pressures. ND WH, NU BOP. TOOH w/ 2-3/8" tubing set at 5607'. Replace bad tubing as necessary.
- 3. TIH with 2-3/8" tubing, 4-1/2" (10.5#) casing scraper and 3-7/8" bit. CO to PBTD of 5797'. TOOH.
- 4. TIH w/ 4-1/2" CIBP and set CIBP @ 5275'. Load hole w/ 1% KCL water and pressure test to 1000 psi. Spot Menefee interval (± 4900' ± 5200') w/ 250 gallons of inhibited 15% HCL acid. TOOH.
- 5. RU wireline and run CBL-GR-CCL from ± 5275' to TOC under 1000 psi surface pressure. Run CNL from 5275' to 4600'. Send copy of logs to engineering and perforation intervals will be provided. TIH w/ 7" fullbore packer and two joints of 2-7/8" N-80 frac string. Set packer and pressure test casing and CIBP to 3800 psi. Release packer and TOOH standing back frac string.
- 6. Perforate the Menefee interval (± 4900' ± 5200') top down using 3-1/8" HSC guns with 12 gram charges and 0.31" diameter holes. (Intervals will be provided after reviewing logs.) Inspect guns to ensure all perforations fired. RD wireline.
- 7. TIH w/ 4-1/2" fullbore packer and two joints of 2-7/8" N-80 frac string. Set packer.
- 8. **Maximum allowable treating pressure is 3800 psi during acid job.** Pump 1500 gallons of 15% HCL acid @ maximum rate pressure will allow dropping 7/8" diameter RCN ball sealers spaced evenly throughout the job (2 balls per perforation hole). Release packer and TOOH standing back frac string.
- 9. RU wireline, run 4-1/2" junk basket and knock balls off perforations.
- 10. TIH w/ 4-1/2" fullbore packer and two joints of 2-7/8" N-80 frac string. Set packer.
- 11. Hold safety meeting. Maximum allowable surface treating pressure is 3800 psi.
- 12. Pressure test surface lines to 4800 psi. (1000 psi over maximum treating pressure but less than the working pressure of the lines.) Fracture stimulate the Menefee interval @ 30 BPM using 30# linear gel and 80m lbs of sand tagging w/ Irridium. (Final stimulation procedure will be attached after reviewing logs.) Do not over displace during flush. Shut in well immediately after completion of the stimulation until pressure falls to zero.
- 13. Release packer and TOOH standing back frac string. Check and inspect packer. RU wireline and set a 4-1/2" RBP @ ± 4800'. Load hole w/ 1% KCL water and pressure test RBP to 3800 psi. Dump sand on top of RBP w/ dump bailer.
- 14. Perforate Cliffhouse interval (± 4600' ± 4750') using 3-1/8" HSC guns with 12 gram GOEX charges (0.26" and .22" diameter holes through 4-1/2" and 7" respectively). (Perforation interval will be provided after reviewing logs.) Inspect guns to ensure all perforations fired. RD wireline.
- 15. TIH w/ 4-1/2" fullbore packer and two joints of 2-7/8" N-80 frac string. Set packer.

- 16. **Maximum allowable treating pressure is 3800 psi during acid job.** Pump 1500 gallons of 15% HCL acid @ maximum rate pressure will allow dropping 7/8" diameter RCN ball sealers spaced evenly throughout the job (2 balls per perforation hole). Release packer and TOOH standing back frac string.
- 17. RU wireline, retrieve balls w/ 4-1/2" junk basket and report number of hits.
- 18. TIH w/ 4-1/2" fullbore packer and two joints of 2-7/8" N-80 frac string. Set packer.
- 19. Hold safety meeting. Maximum allowable surface treating pressure is 3800 psi.
- 20. Pressure test surface lines to 4800 psi. (1000 psi over maximum treating pressure but less than the working pressure of the lines.) Fracture stimulate the Cliffhouse interval @ 30 BPM using 30# linear gel and 105m lbs of sand tagging w/ Irridium. (Final stimulation procedure will be attached after reviewing logs.) Do not over displace during flush. Shut in well immediately after completion of the stimulation until pressure falls to zero.
- 21. Release packer and TOOH laying down frac string.
- 22. TIH w/ retrieving head and CO to RBP @ ± 4800' until sand production is minimal. Obtain pitot gauge for Cliffhouse interval. Release RBP @ 4800' and TOOH.
- 23. TIH w/ 3-7/8" bit and drill up CIBP set @ 5275'. CO to PBTD (5797'). PU above the Mesaverde perforations and flow the well naturally, making short trips for clean up when necessary. Obtain pitot gauge for Mesaverde after clean up.
- 24. When sand has diminished, TOOH.
- RU wireline company. Run After Frac GR from 5661' to top of tracer activity. RD wireline.
- 26. TIH with one joint of 2-3/8", 4.7#, J-55 tubing w/ expendable check, an F-nipple, then the remaining 2-3/8" production tubing. CO to PBTD (± 5797'). Land tubing near bottom perforation (5661').
- 27. ND BOP's, NU WH. Pump off expendable check. Obtain final pitot. RD and MOL. Return well to production.

Approval:

zg capa.....a...

Approval:

Northwest Basin Team Leader