UNITED STATES

DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

| Sunary | Notices and Report | ts on Wells | / D 1 DH 4 | / |
|---|---|---------------------------------------|------------------|-----------------------------|
| | | <u> </u> | 5. | Lease Number |
| | | a the second | | SF-080314 |
| m of Woll | | 414 | | "If Indian, All. o |
| Type of Well | | | ٥. | Tribe Name |
| GAS | | | | IIIDE Hame |
| | | 19 19 19 19 | 7. | Unit Agreement Na |
| . Name of Operator | | | ્ૈ <u>ત્ર</u> | • |
| | , | 2000 | (C) | |
| RESOURCES | | JUL 2000 | 1 (2) | |
| | OIL & GAS COMPANY | S DECEIVE | | Well Name & Numbe |
| | | CILOCAL | . ස්වූ 8. ධ්ය | Harrison #1 |
| Address & Phone No. of O | | 26-9700 DIST. 3 | S. | |
| PO Box 4289, Farmington | ., NM 87499 (505) | 10 | 9. | API Well No. |
| | | | | 30-045-11124 |
| Location of Well, Footag | | 957 | 10. | Field and Pool |
| 1190'FSL, 1650'FWL, Sec. | 31, T-32-N, R-10-W | , NMPM | | Blanco Mesaverde |
| | | | 11. | County and State |
| | | | | San Juan Co, NM |
| 2. CHECK APPROPRIATE BOX T | | | ORT, OTHER | DATA |
| Type of Submission | | ype of Action | | |
| $_{	exttt{X}}$ Notice of Intent | | | nange of Pla | |
| | Recomple | | w Construc | |
| Subsequent Repor | t Plugging | Back No | on-Routine | Fracturing |
| | | | | |
| | Casing R | epair Wa | ater Shut o | |
| Final Abandonmer | | | ater Shut o | |
| Final Abandonmer | | epair Wa | ater Shut o | |
| Final Abandonmen Describe Proposed or | Altering Other - | epair Wa Casing Co | ater Shut o | |
| | Altering Other - Completed Operation g and abandon the | epair Wa Casing Co | ater Shut o | o Injection |
| 3. Describe Proposed or It is intended to plu | Altering Other - Completed Operation g and abandon the | epair Wa Casing Co | ater Shut o | o Injection |
| 3. Describe Proposed or It is intended to plu | Altering Other - Completed Operation g and abandon the | epair Wa Casing Co | ater Shut o | o Injection |
| 3. Describe Proposed or It is intended to plu | Altering Other - Completed Operation g and abandon the | epair Wa Casing Co | ater Shut o | o Injection |
| 3. Describe Proposed or It is intended to plu procedure & wellk | Completed Operation ag and abandon the core diagram. | epair War Casing Co | ater Shut o | o Injection |
| It is intended to plu procedure & wellk | Completed Operation ag and abandon the core diagram. | epair War Casing Co | ater Shut o | o Injection |
| It is intended to plu procedure & wellk | Completed Operation ag and abandon the core diagram. | epair Wa Casing Co ns subject well a | ect. | o Injection o the attached |
| It is intended to plu procedure & wellk | Completed Operation ag and abandon the core diagram. | epair War Casing Co | ect. | o Injection o the attached |
| It is intended to plu procedure & wellk | Completed Operation ag and abandon the bore diagram. the foregoing is Title | epair Wa Casing Co ns subject well a | ect. | te 5/30/00 |

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Harrison #1

Blanco Mesaverde / AIN 2729501

Latitude / Longitude: 36° 56.2720' / 107° 55.5899' 1190' FSL and 1650' FWL, Section 31, T-32-N, R-10-W

San Juan Co., New Mexico

PLUG & ABANDONMENT PROCEDURE

04-21-00

Note: All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures.

- 1. Install and test location rig anchors. Prepare blow pit. Comply with all NMOCD, BLM, and Burlington safety regulations. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. NU relief line. Blow down well; kill with water as necessary.
- 2. ND wellhead and NU BOP. Test BOP. TOOH and tally 165 joints 2-3/8" tubing, visually inspect tubing. If necessary LD and PU workstring. Round trip a 4-1/2" gauge ring to 4481'.
- 3. Plug #1 (Mesaverde perforations, 4481' 4381'): Set a 4-1/2" wireline CIBP at 4481'. TIH with open ended tubing and tag CIBP. Load 4-1/2" casing with water and circulate clean. Pressure test casing to 500#. If casing does not test, then spot or tag subsequent plugs as appropriate. Mix 12 sxs Class B cement and spot a balanced plug inside 4-1/2" casing above CIBP to isolate Mesaverde perforations. TOOH with tubing.
- 4. Cut and Pull Casing: Perforate 2 squeeze hole at 2850'. Establish circulation to surface out 4-1/2" X 7" casing valve. ND BOI and tubing head. Prepare a Hot Work Permit. Weld 4-1/2" slip on collar on casing stub and pick up on 4-1/2" casing Determine free point by stretch calculation. Jet cut or collar split the 4-1/2" casing at approximately 2800'. Pull 4-1/2" casin out of well and LD.
- 5. Plug #2 (Casing Stub and Pictured Cliffs top, 2850' 2690'): Perforate 3 squeeze holes in 7" casing at 2790'. TIH and set 7 cement retainer at 2740'. Pressure test tubing to 1000#. Load 7" casing with water and circulate clean. Pressure test 7" casin to 500#. Establish rate under retainer into squeeze holes. Mix and pump 70 sxs Class B cement, squeeze 30 sxs outside casin from 2790' to 2690', pump 26 sxs below cement retainer and spot 14 sxs on top of cement retainer to cover casing stub an Pictured Cliffs top. TOOH with tubing.
- 6. Plug #3 (Fruitland top, 2330' 2230'): Perforate 3 squeeze holes at 2330'. TIH and set 7" cement retainer at 2280'. Establis rate under retainer into squeeze holes. Mix and pump 58 sxs Class B cement, squeeze 30 sxs outside casing, pump 14 sxs belo cement retainer and spot 14 sxs above the cement retainer to cover Fruitland top. TOOH with tubing.
- Plug #4 (Kirtland and Ojo Alamo tops, 1160' 980'): Perforate 3 squeeze holes at 1160'. Establish rate into squeeze holes casing tested. TIH and set 7" cement retainer at 1110'. Establish rate into squeeze holes. Mix and pump 97 sxs Class B cement squeeze 53 sxs outside casing, pump 14 sxs below cement retainer and spot 30 sxs above cement retainer to cover through O Alamo top. POOH and LD tubing.
- 8. Plug #5 (10-3/4" casing shoe, 265' to Surface): Perforate 3 HSC squeeze holes at 265'. Establish circulation of bradenhead valve. Mix and pump approximately 120 sxs Class B cement down the 7' casing from 265' to surface, circula good cement out bradenhead valve. Shut in well and WOC.
- 9. ND BOP and cut off wellhead below surface casing. Install P&A marker to comply with regulations. RD, MOL, cut anchors, and restore location.


Approval:

Drilling Superintendent

Harrison #1

Current
Blanco Mesaverde
AIN: 2729501
SW Section 31, T-32-N, R-10-W
San Juan County, NM

Latitude / Longitude: 36° 56.2720' / 107° 55.5899'



Harrison #1

Proposed P&A

Blanco Mesaverde AIN: 2729501 SW Section 31, T-32-N, R-10-W San Juan County, NM

Latitude / Longitude: 36° 56.2720' / 107° 55.5899'

Today's Date: 5/24/00 Spud: 7/29/52 Completed: 9/27/52 El: 5973 GI

10-3/4" 40.3# Csg set @ 215' 100 sxs cement (Circulated to Surface)

Perforate @ 265'

Plug #5 265' - Surface Cmt with 120 sxs Class B

Plug #4 1160' - 980' Cmt with 99 sxs Class B. 54 sxs outside casing and 45 sxs inside.

Cmt Retainer @ 1110'

Perforate @ 1160'

Plug #3 2330' - 2230' Cmt with 59 sxs Class B 30 sxs outside casing and 29 sxs inside.

Plug #2 2850' - 2690' Cmt with 71 sxs Class B 30 sxs outside 7" from 2

to 2690' and 41 sxs insid

Cmt Retainer @ 2280'

Perforate @ 2330'

Cmt Retainer @ 2740'

Perforate 7" @ 2790'

Jet Cut 4-1/2" Casing @ 2800' Perforate 4-1/2" Casing @ 2850"

TOC in 9" at 3267' (Calc, 75%) TOC in 7" at 3343' (Calc, 75%)

Whipstock @ 3885'

Plug #1 4481' - 4381' Cmt with 12 sxs Class E

Set CIBP at 4481'

7" 20# J-55/H-40 Casing set @ 4408' Cemented with 225 sxs

Mesaverde Perforations: 4531' - 5060'

4-1/2" 10.5#, Casing set @ 5205' Cemented with 150 sxs (266 cf) 50/50 Poz with 4% gel & 12# gilsonite

12-1/4" hole Ojo Alamo @ 1030 Kirtland @ 1110' 4 Fruitland @ 2280 Pictured Cliffs @ 2740' Mesaverde @ 4530 9" hole 5 - Set CR at 3914' and sqzd with total 450 sxs cmt; whipstock again, drilled to 5205', set 4-1/2" casing.

- 4 Whipstock again at 4238', drilled to 6417'; stuck square drill collar, fished out of hole.
- 3 Whipstock at 4200', drilled to 4790', hole wet; squeezed off.
- 2 Cut off stuck tubing; squeezed off MV open hole (1969)
- 1 Mesaverde Open Hole Interval: 4408' 5326', Nitro shot (1952)

6-1/4" hole

TD 5205'