

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

Sundry Notices and Reports on Wells

1. Type of Well
GAS

2. Name of Operator
BURLINGTON RESOURCES OIL & GAS COMPANY

3. Address & Phone No. of Operator
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M
800' FNL, 930' FEL, Sec. 31, T-32-N, R-9-W, NMPM

5. Lease Number
SF-078509

6. If Indian, All. or Tribe Name

7. Unit Agreement Name
San Juan 32-9 Unit

8. Well Name & Number
San Juan 32-9 U #41

9. API Well No.
30-045-11189

10. Field and Pool
Blanco Mesaverde

11. County and State
San Juan Co, NM

RECEIVED
JUN 19 1998

OIL COAL DIV.
DEPT. OF THE INTERIOR

12. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OTHER DATA

Type of Submission	Type of Action	
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Abandonment	<input type="checkbox"/> Change of Plans
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Recompletion	<input type="checkbox"/> New Construction
<input type="checkbox"/> Final Abandonment	<input type="checkbox"/> Plugging Back	<input type="checkbox"/> Non-Routine Fracturing
	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> Water Shut off
	<input type="checkbox"/> Altering Casing	<input type="checkbox"/> Conversion to Injection
	<input checked="" type="checkbox"/> Other - Tubing repair	

13. Describe Proposed or Completed Operations


It is intended to repair the tubing in the subject well according to the attached procedure.

RECEIVED
98 JUN 11 PM 3:17
OIL COAL DIV. NM

14. I hereby certify that the foregoing is true and correct.

Signed [Signature] (KLM5) Title Regulatory Administrator Date 6/5/98
no

(This space for Federal or State Office use)
APPROVED BY IS/Duane W. Spencer Title _____ Date JUN 17 1998
CONDITION OF APPROVAL, if any:



San Juan 32-9 Unit No. 41
Mesa Verde
800' FNL, 930' FEL
Unit A, Section 31, T-32-N, R-09-W
Latitude / Longitude: 36° 56.7773 / 107° 48.8837'
DPNO: 69892
Tubing Repair Procedure

Project Summary: San Juan 32-9 Unit No. 41 was drilled in 1956 and tubing has not been pulled since the well was put into production. We propose to pull the tubing, check for fill, replace any worn or scaled tubing and install a plunger lift.

1. Hold safety meeting. Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Test rig anchors and build blow pit prior to moving in rig. **Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.**
2. MOL and RU workover rig. Obtain and record all wellhead pressures. NU relief line. Blow well down and kill with 2% KCL water if necessary. NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. Test secondary seal and replace/install as necessary.
3. The Mesa Verde tubing is 2-3/8", 4.7#, J-55 set at 6086'. Release donut, pick up additional joints of tubing and tag bottom (record depth.) PBD should be at +/- 6105'. TOOH with tubing. Visually inspect tubing for corrosion and replace any bad joints. Check tubing for scale build up and notify Operations Engineer.
4. If fill covers any perforations then TIH with 4-3/4" bit and a watermelon mill on 2-3/8" tubing to below perforations, cleaning out with air/mist. **NOTE: When using air/mist, minimum mist rate is 12 bph.**
5. PU above the perforations and flow the well naturally, making short trips for clean up when necessary. TOOH with tubing. TIH with one joint of 2-3/8" tubing with an expendable check on bottom and a seating nipple one joint off bottom. Run a broach on sandline to insure that the tubing is clear. Land tubing at approximately 6040'. ND BOP and NU WH. Pump off expendable check. Connect to casing and circulate air to assure that expendable check has pumped off. Obtain pitot gauge up the tubing. If well will not flow on it's own, make swab run to SN. RD and MOL. Return well to production.

Recommended:

Kevin Midkiff 5/22/98
Operations Engineer

Approved:

Bruce D. Boys 6-1-99
Drilling Superintendent

Kevin Midkiff
Office - 599-9807
Pager - 564-1653

