

SEC.13 1:45

submitted in lieu of Form 3160-5

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Noti	ces and Reports on Wells	3	(10 m. 1.1, 1.1	
1. Type of Well GAS	[0] [N]	5. ECENVE	Lease Number SF-077648 If Indian, All. or Thibe Name	
2. Name of Operator	· · · · · · · · · · · · · · · · · · ·	JUN 2 2 1999		
BURLINGTON RESOURCES OIL 6	GAS COMPANY	L CON. DI DIST. 38.	Well Name & Number	
3. Address & Phone No. of Operat	or		Davis #2A	
PO Box 4289, Farmington, NM	87499 (505) 326-9700	9.	API Well No. 30-045-22266	
4. Location of Well, Footage, Se 800'FNL, 1820'FEL, Sec.11, T-31-			Field and Pool Blanco Mesaverd e	
	B	11.	County and State San Juan County, NM	
12. CHECK APPROPRIATE BOX TO IND Type of Submission	ICATE NATURE OF NOTICE, Type of Acti		DATA	
X Notice of Intent	Abandonment	Change of Pla New Construct		
Subsequent Report	Plugging Back Casing Repair	Non-Routine Fracturing		
Final Abandonment	Altering Casing _X_ Other - Plugging Pr	Conversion to		

13. Describe Proposed or Completed Operations

It is intended to plug the Cliffhouse Interval in the subject well according to the attached procedure.

14. I hereby certify that the foregoing is true and correct.	
Signed Machine Title Regulatory Administrator	tra
(This space for Federal or State Office use) APPROVED BY /S/ Duane W. Spencer Title	JUN I , 1000
CONDITION OF APPROVAL, if any:	

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

NMOCD

<u>Davis #2A</u> Mesaverde 800'FNL, 1820' FEL Unit B, Section 11, T-31-N, R-12-W Latitude / Longitude: 36° 55.0754' / 108° 3.6950' DPNO: 1161701 Plug Cliffhouse Interval Procedure

CAUTION: This well produces H2S.

- 1. Hold safety meeting. Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, <u>approval is required before the job can be pumped</u>. If verbal approval is obtained, document approval in <u>DIMS/WIMS</u>. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
- 2. MOL and RU workover rig. Obtain and record all wellhead pressures. NU relief line. Blow well down and kill with 2% KCL water if necessary. ND WH and NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. Test secondary seal and replace/install as necessary.
- 3. Mesaverde, 2-3/8", 4.7# tubing is set at 5400'. Release donut, pick up additional joints of tubing and tag bottom. (Record depth.) PBTD should be at ± 5450'. TOOH with tubing. Visually inspect tubing for corrosion and replace any bad joints. Check tubing for scale build up and notify Operations Engineer.
- 4. TIH with 4-1/2" CIBP and set at ± 4680 '. TOOH.
- 5. TIH with 4-1/2" cement retainer on 2-3/8" tubing and set at ± 4357 '.
- 6. RU cement company. PU tubing to test position on the retainer. Pressure test tubing to 2500 psi. Set down on tubing to open check and establish an injection rate with water.
- 7. Squeeze below retainer into Cliffhouse perforations to 1000 psi with 62 sx of Class B cement (with .3% fluid loss). Displace cement with 16 Bbls of water (under displace by 1 Bbl.). Sting out of retainer and reverse circulate. TOOH with 2-3/8" tubing. WOC for a minimum of 18 hours.
- 8. TIH with 3-7/8"bit, 3-1/8" drill collars (if necessary) and 2-3/8" tubing. Drill out retainer and cement. Pressure test squeeze to 500 psi for 15 minutes. If test is not successful, note leak off rate and contact Operations Engineer.
- 9. CO to CIBP set at 4680'. Drill CIBP and push to bottom, cleaning out with air/mist. NOTE: When using air/mist, minimum mist rate is 12 bph. If scale is present, contact Operations Engineer to determine methodology for removing scale from casing and perforations.
- 10. TIH with one joint of 2-3/8" tubing with an expendable check on bottom and a seating nipple one joint off bottom then ½ of the 2-3/8" production tubing. Run a broach on sandline to insure that the tubing is clear. TIH with remaining 2-3/8" tubing and then broach this tubing. Replace any bad joints. CO to PBTD with air/mist. PU above the perforations and flow the well naturally, making short trips for clean up when necessary.
- 11. Land tubing at ±5220'. ND BOP and NU WH. Pump off expendable check. Connect to casing and circulate air to assure that expendable check has pumped off. Obtain pitot gauge up the tubing. If well will not flow up the tubing, make swab run to SN. RD and MOL. Return well to production.

Recommended:

M.E. Kutuy Operations Engineer

Approved:

Drilling Superintendent

Operations Engineer:

Mary Ellen Lutey Office - (599-4052) Home - (325-9387) Pager - (324-2671)

submitted in lieu	UNI DEPARTMEN	5 TED STATES T OF THE INTERIO F LAND MANAGEMEN				
k-	Sundry Noti	ces and Reports	on \$\$\$1,1\$/ -0	Pii 2: 35		
1. Type of Well GAS			070 F/@da.go	51GN; MM ⁻⁵⁻¹ 6.	Lease Number SF-077648 If Indian, All. or Tribe Name	
	<u></u>		<u> </u>	UN 1911	Unit Agreement Name	
2. Name of Operato BURLIN RESOUR	GTON	& GAS COMPANY	NUN 2	2 1939		
3. Address & Phone PO Box 4289, F 4. Location of Wel		87499 (505) 326			Well Name & Number Davis #2A API Well No. 30-045-22266 Field and Pool	
	-	31-N, R-12-W, NM	PM B		Field and Fool Blanco Mesaverde County and State San Juan Co, NM	
XSubseq	of Intent uent Report Abandonment	Abandonment Recompletic Plugging Ba Casing Repa Altering Ca	on New ack Non- air Wate	nge of Plans Construction Routine Fract er Shut off rersion to In	curing	
13.Describe Propos	sed or Complete	d Operations				
10-15-99 10-18-99					/L. Freepoint tbg, id. SDON.	
10-19/22-99 10-25-99		tools. Fishing. g tools & fish. T			. CO to 5060'. Spot	
 10-26-99 CO to PBTD @ 5450'. TOOH w/mill. TIH w/CIBP, set @ 4680'. SDON. 10-27-99 TIH w/cmt retainer, set @ 4298'. Est injection. Sqz Cliff House perfs w/177 sx Class "B" neat cmt w/0.3% fluid loss (209 cu ft). Reve 10 bbl cmt to surface. TIH w/bit. SDON. 						
10-28-99 10-29-99 10-30/31-99 11-1/2-99	D/O cmt retain D/O CIBP & cha Circ wtr out c	her . Circ hole c ase to PBTD. Circ of hole. Well mak CH w/RBP, set @ 4	: hole clean. ing 12 BPH. F	SDON. 'low well.		
11-3-99	(Verbal approv CIBP, set @	val from Jim Lova	I w/164 jts 2-		RBP & TOOH. TIH w/ 55 tbg, set @ 5151'.	
14. I hereby certif	ly that the for	egoing is true a	nd correct.	· · · · · · · · · · · · · · · · · · ·	<u> </u>	
signed MAAA	Cale	Title <u>Requlat</u>	ory Administr	<u>ator</u> Date 11/TLW	5/99	
(This space for Fe	deral or State					
APPROVED BY CONDITION OF APPRO	WAL, if any:	Title		Date		

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the OV : 1 8 1999 United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.