

State of New Mexico  
Energy, Minerals and Natural Resources Department  
Oil Conservation Division

Sundry Notices and Reports on Wells

1. Type of Well  
GAS

2. Name of Operator  
**MERIDIAN OIL**

3. Address & Phone No. of Operator  
PO Box 4289, Farmington, NM 87499 (505) 326-9700

4. Location of Well, Footage, Sec., T, R, M  
1450' FNL, 1190' FWL, Sec.1, T-31-N, R-13-W, NMPM, San Juan County

API # (assigned by OCD)  
30-045-22533  
5. Lease Number  
Fee  
6. State Oil&Gas Lease #  
7. Lease Name/Unit Name  
Hancock Com  
8. Well No.  
1A  
9. Pool Name or Wildcat  
Blanco Mesaverde  
10. Elevation:

Type of Submission

☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment

Type of Action

☐ Abandonment ☐ Change of Plans  
☐ Recompletion ☐ New Construction  
☐ Plugging Back ☐ Non-Routine Fracturing  
☐ Casing Repair ☐ Water Shut off  
☐ Altering Casing ☐ Conversion to Injection  
☒ Other -Bradenhead repair

13. Describe Proposed or Completed Operations

It is intended to repair the bradenhead in the subject well according to the attached procedure.

SIGNATURE

*Johnny Bradfield* (LWD4) Regulatory Administrator December 11, 1995

(This space for State Use)

Approved by

*Johnny Robinson*

Title

DEPUTY OIL & GAS INSPECTOR, DIST. #1

Date

DEC 12 1995

RECEIVED  
DEC 12 1995  
OIL & GAS  
DIST. #1

## WORKOVER PROCEDURE - BRADENHEAD REPAIR

HANCOCK COM # 1A  
Mesaverde  
NW/4 Sec. 1, T31N, R13W  
San Juan Co., New Mexico  
DPNO 50012A

1. Comply to all NMOCD, BLM, and MOI regulations. Conduct daily safety meetings for all personnel on location.
2. Test location rig anchors and repair if necessary. Prepare blow pit. MOL and RU daylight pulling unit. Install a 400 bbl frac tank and an atmospheric blow tank. NU blooie line to blow pit, and relief line to atmospheric tank. Fill frac tank with 1% KCl water.
3. Blow down tubing (1 1/2" set at 4519') to atmospheric tank. Control well with 1% KCl water as needed. ND wellhead and NU BOP's. Test and record operation of BOP's. Send wellhead to A-1 Machine or WSI for inspection.
4. PU on tubing and strap out of hole. Visually inspect tubing, and replace joints that are in bad condition. Note any buildup of scale, and notify Operations Engineer.
5. PU 3 7/8" bit, casing scraper (4 1/2", 10.5 ppf), 2 3/8" workstring, and CO to PBTD of 4709'. POOH and PU 4 1/2" RBP. TIH and set RBP at 4300'. Pressure test casing to 1000 psig. Spot one sack of sand on top of RBP. POOH.
6. RU wireline unit. Run CBL (with 1000 psig pressure) from DV tool at 2167' to surface. Contact Operations Engineer for design of squeeze cement.
7. Perforate 4 squeeze holes as per results of cased hole logs. TIH with 4 1/2" fullbore packer and set 250' above perforations. Pressure up casing/tubing annulus to 500 psig. Establish rate into perforations with bradenhead valve open. Max pressure 1000 psig.
8. Mix and pump cement (if circulation has been established to surface, pump with turbulent flow behind pipe). Displace cement to packer. Squeeze cement into perforations. Maintain squeeze pressure and WOC 12 hours (overnite).
9. Release packer and POOH. TIH with 3 7/8" bit and drill out cement. Pressure test casing to 1000 psig. Test bradenhead valve for flow. Re-squeeze as necessary to hold pressure, or to stop fluid flow at surface.
10. TIH with retrieving tool and retrieve RBP. POOH laying down 2 3/8" workstring and RBP.
11. TIH with production tubing (seating nipple one joint off bottom, and an expendable check on bottom). Tag PBTD, blow well clean, and land tubing at +/- 4648'.

12. ND BOP's and NU wellhead. Pump check from tubing. Obtain final gauge.
13. Release rig.

Recommend: \_\_\_\_\_  
Operations Engineer

Approve: *J. Chappin* 12/6/95  
Drilling Superintendent

<b>Contacts:</b>	Cement	Cementers Inc	632-3683
	Wireline	Petro	326-6669
	Operations Engineer	Larry Dillon	326-9714