Form 3160-5 (August 1999)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB NO. 1004-0135 Expires: November 30, 2000

al No.

DEPARTMENT OF THE INTERIOR				Ex	ΧJ
BUREAU OF LAND MANAGEMENT	三、《高等》。1975年	5.	Lease	e Ser	ia
JNDRY NOTICES AND REPORTS ON WEL	AS STATE OF		NMS	3F0	7
t use this form for proposals to drill or to re-e		١.	T.C.T.		_

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.			NMSF078096 6. If Indian, Allottee or Tribe Name	
	PLICATE - Other instructions on re	MAY	If Unit or CA/Agreement, Name and/or No.	
Type of Well Oil Well	ег		8. Well Name and No. MUDGE /B/ 10A	
Name of Operator AMOCO PRODUCTION COM	Contact: (None Spec	cified)	9. API Well No. 30-045-22733-00-S1	
3a. Address P. O. BOX 3092 HOUSTON, TX 77253	3b. Phone N Ph: 281.3	No. (include area code) 166.4491	10. Field and Pool, or Exploratory BLANCO	
4. Location of Well (Footage, Sec., T., R., M., or Survey Description)			11. County or Parish, and State	
Sec 9 T31N R11W Mer NWSE 36.90958 N Lat, 107.99236 W			SAN JUAN COUNTY, NM	
12. CHECK APPE	OPRIATE BOX(ES) TO INDICAT	E NATURE OF NOTICE, RE	EPORT, OR OTHER DATA	
TYPE OF SUBMISSION	TYPE OF ACTION			

□ Production (Start/Resume) ■ Water Shut-Off □ Acidize Deepen Notice of Intent ☐ Well Integrity ☐ Alter Casing □ Fracture Treat □ Reclamation ■ Subsequent Report ☑ WRK Casing Repair ■ New Construction □ Recomplete ☐ Final Abandonment Notice □ Change Plans □ Plug and Abandon ☐ Temporarily Abandon ■ Water Disposal □ Convert to Injection ☐ Plug Back 13. Describe Proposed or Completed Operation (clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports shall be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 shall be filed once testing has been completed. Final Abandonment Notices shall be filed only after all requirements, including reclamation, have been completed, and the operator has

determined that the site is ready for final inspection.) Amoco Production Company request permission to Squeeze off the Cliffhouse perforations and return well to production through tubing as per the attached procedure.

14. I hereby certify that the foregoing is true and correct. Electronic Submission #4166 verified For AMOCO PRODUCTION COI Committed to AFMSS for processing by Mau	MPANY, sent to the Farmington
Name (Printed/Typed) (None Specified)	Title
Signature	Date 05/10/2001
THIS SPACE FOR FEDERA	L OR STATE OFFICE USE
_Approved By _ /S/ Jim Lovato	TitleDate
Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon	Office

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

Mudge B 10 A Well Work Procedure

ACTION: Squeeze Cliffhouse perforations, return well to production through tubing.

- Check anchors. Check and record tubing, casing, and Bradenhead pressures. Tag and flag valves and bleed flow line pressure to zero. MIRU workover rig.
- 2. Blow down wellhead. If necessary, kill with 2% KCl water.
- 3. ND Christmas tree & NU rig BOP's w/ pipe & blind rams. Pressure test to 500 psi.
- 4. TOH with tubing (2- 3/8", 4.7#, J-55, @ 5265').
- 5. Set cast iron bridge plug @ 4597' between bottom of Cliffhouse perfs (4547') and top of Point Lookout perfs (4929').
- 6. TIH with work string and packer @ 4276' (Top of Cliffhouse @ 4306').
- 7. Squeeze Cliffhouse perforations (198 shots; 2 jspf; 4306-4336, 4357-4360, 4412-4449, 4455-4462, 4470-4478, 4489-4491, 4500-4503, 4530-4532, 4540-4547) as per Schlumberger design.
- 8. TIH with bit and drill out cement to 4572'. Pressure test casing to 500 psi.
- 9. Drill out remaining cement and CIBP.
- 10. Cleanout to PBTD @ 5363'.
- 11. TIH with 2-3/8" production tubing and land tubing at +/- 5265'. Rabbit and RIH with tubing with an F-nipple and plug on bottom. Fill tubing while RIH and periodically pressure test to 500 psi. Replace any tubing joints that fail to pressure test. Swab water from the tubing using the sandline on the rig. RU slickline and run gauge ring to ensure the tubing drifts. Pull plug with slickline. Clean out to PBTD. Flow to cleanup tank.
- 12. Clean out to PBTD. Flow to cleanup tank.
- 13. ND BOP's. NU WH. Notify pumper that well is ready to be returned to production. Swab in well with sand line and flow back for a few hours on a

choke to ensure well is ready to produce and unloaded before turning well over to pumper to return to production.

