7	State of New Y, Minerals and Natura		Dartment
Inergy	y, Minerals and Natura Oil Conservatio		
	Sundry Notices and R	eports on Wells	5
		API	# (assigned by OCD) 30-045-23048
1. Type of Well GAS		5.	Lease Number
		ć.	State Oil&Gas Lease # E-3150-11
2. Name of Operator		7.	Lease Name/Unit Name
MERIDIAN OIL		8.	Beaver Lodge Com Well No.
3. Address & Phone No. of Operato: PO Box 4289, Farmington, NM		Ģ.	2A Pool Name or Wildcat Blanco Mesaverde
4. Location of Well, Footage, Sec 790'FNL, 1470'FWL, Sec.36, T-3	., T, R, M 1-N, R-11-W, NMPM, San		Elevation: 5885 GR
Type of Submission _XNotice of Intent	Type of Act Abandonment Recompletion	Change of Pl. New Construct	tion
Subsequent Report Final Abandonment	Plugging Back Casing Repair Altering Casing X Other - Tubing rep	Water Shut o Conversion t	ff o Injection

Describe Proposed or Completed Operations 13.

Approvedby

MMA O

It is intended to repair the tubing in the subject well according to the attached procedure and wellbore diagram.

DECENVED Mahuld (VGW5) Regulatory Administrator September 27, 1995____ SIGNATURE DEPUTY OIL & GAS INSPECTOR, DIST. #3 SEP 2 9 1995 (This space for State Use)

WORKOVER PROCEDURE - TUBING REPAIR

Beaver Lodge Com 2A DPNO 48711A Blanco Mesaverde Section 36, T31N, R11W San Juan County, New Mexico

WARNING: H2S Level 25-30 ppm

- 1. MOL and RU H2S safety equipment. Conduct H2S safety meeting for all personnel on location.
- 2. Install and test location rig anchors. Prepare blow pit. Comply to all NMOCD, BLM, and MOI safety regulations.
- 3. MOL and RU. Conduct safety meeting for all personnel on location. NU relief line. Blow down well and kill with 1% KCI water as necessary. ND wellhead and NU BOP. Test BOP.
- POH 2 3/8" tbg (169 jts). Inspect tubing and replace all bad joints. (Note any buildup of scale, and notify Operations Engineer. If tubing is excessively scaled, acid wash may be run in perforations.) PU and RIH with 3 7/8" bit and 4 1/2" 10.5# casing scraper to PBTD (5172'). CO and POH.
- 5. PU 4 1/2" RBP and RIH. Set @ 3920'. Load hole w/1% KCI water. Pressure test casing to 750#. (If casing does not test, notify Operations Engineer. Isolate failure and repair.) Release packer and POH.
- 6. RIH with open-ended 2 3/8" 4.7# tbg, SN one joint off bottom. (Rabbit tubing in derrick before running in hole.) Land @ 5088'.
- 7. ND BOP, NU wellhead, rig down, move off location, and restore location.

Recommended: perations Engineer

Approval:

Production Superintendent

Contacts: Operations Engineer

Gaye White

326-9875

VGW

Beaver Lodge Com #2A

Current -- 9/15/95

Blanco Mesaverde DPNO: 48711A

790' FNL, 1470' FWL Sec. 36, T31N, R11W, San Juan Co., NM Longitude/Latitude : 107.945862/36.860245



Spud: 11-15-78 Completed : 01-08-79 Elev. GL: 5885' KB: 5895'