DEPARTMEN	TED STATES IT OF THE INTERIOR OF LAND MANAGEMENT	/	
Sundry Noti	ces and Reports on Wells 7:55		
		5.	Lease Number SF-080376A
1. Type of Well GAS	OTO LESS STATISTICS MAL NM	6.	If Indian, All. or Tribe Name
2. Name of Operator		7.	Unit Agreement Name
		8.	Well Name & Number
3. Address & Phone No. of Operat PO Box 4289, Farmington, NM		9.	Sheets #1A API Well No. 30-045-23124
4. Location of Well, Footage, Sec., T, R, M 1840'FSL, 800'FEL, Sec.28, T-31-N, R-9-W, NMPM		10.	Field and Pool Blanco Mesaverde
		11.	County and State San Juan Co, NM
12. CHECK APPROPRIATE BOX TO INC	DICATE NATURE OF NOTICE, REPORT,	OTHER	DATA
Type of Submission	Type of Action		
X_ Notice of Intent		of Pla	
Subsequent Report			
Final Abandonment	Altering CasingConver _XOther - Bradenhead repair	sion to	D Injection

13. Describe Proposed or Completed Operations

It is intended to repair the bradenhead on the subject well according to the attached procedure and wellbore diagram.

Provide the second s

		OFFEB - 5 1996 OFFE CON DIV DIMESS
Signed Liggy Stall		
(This space for Federal APPROVED BY CONDITION OF APPROVAL, i	Title	Date APPROVED
		JAN 2 6 1996 DISTRICT MANAGER

WORKOVER PROCEDURE - BRADENHEAD REPAIR

SHEETS #1A Blanco Mesaverde SE/4 Sec. 28, T31N, R9W San Juan Co., New Mexico DPNO 47940A

- 1. Comply to all NMOCD, BLM, and MOI regulations. Conduct daily safety meetings for all personnel on location.
- 2. Test location rig anchors and repair if necessary. Prepare blow pit. MOL and RU daylight pulling unit. Install a 400 bbl frac tank and an atmospheric blow tank. NU blooie line to blow pit, and relief line to atmospheric tank. Fill frac tank with 1% KCl water.
- 3. Rig-up wireline and check tubing for obstructions or plunger lift equipment. Blow down tubing (175 jts. of 2 3/8", 4.7 #, set at 5516') to atmospheric tank. Control well with 1% KCl water as needed. ND wellhead and NU BOP's. Test and record operation of BOP's. Send wellhead to A-1 Machine for inspection.
- 4. TIH with 2 3/8" tubing and tag bottom. Record depth and TOOH. Visually inspect tubing (on trip), and replace joints that are in bad condition. Note any buildup of scale, and notify Operations Engineer.
- 5. PU 3 7/8" bit and casing scraper (4 1/2", 10.5 ppf), and TIH to below perfs or fill tagged above. TOOH. PU 4 1/2" RBP and TIH. Set RBP at 4350'. Pressure test casing to 1000 psig. Spot one sack of sand on top of RBP. TOOH with tubing. TIH with 6 1/4" bit and casing scraper (7", 20 ppf) to 3200'. TOOH.
- 6. RU wireline unit. Run CBL (with 1000 psig pressure) to determine TOC behind 7" casing. Estimated TOC is 1400' per temperature survey. Contact Operations Engineer for design of squeeze cement.
- 7. Perforate 4 squeeze holes 20' above TOC. TIH with 7" fullbore packer and set 150' above perforations. Pressure up casing/tubing annulus to 500 psig. Establish rate into perforations with bradenhead valve open. Max pressure 1000 psig.
- 8. Mix and pump cement. (If circulation has been established to surface, pump with turbulent flow behind pipe.) Displace cement to packer. Close bradenhead valve and squeeze cement into perforations. Maintain squeeze pressure and WOC 12 hours (overnite).
- 9. TIH with 6 1/4" bit and drill out cement. Pressure test casing to 1000 psig. Test bradenhead value for flow. Re-squeeze as necessary to hold pressure, or to stop bradenhead flow.
- 10. TIH with retrieving tool and retrieve RBP from 4 1/2" liner. TOOH and LD RBP. TIH with 3 7/8" bit and CO to PBTD @ 5645' with air. Blow well clean and gauge production. TOOH.
- 11. RIH open ended with 2 3/8" tubing, SN with pump out plug one joint off bottom. Rabbit tubing in derrick before running in hole. Land tubing at 5586'.
- 12. ND BOP's and NU wellhead. Pump plug from tubing. Obtain final gauge.
- 13. Release rig.

Recommend:

Operations Engineer

Approve:

Drilling Superintendent

Contacts:

Operations Engineer

Gaye White

326-9875

