FontStudes (June 1990) DEPARTMENT OF THE BUREAU OF LAND MAN	INTERIOR		FORM APPROVED Budget Bureau No. 1004-0135 Expires: March 31, 1993
SUNDRY NOTICES AND REP Do not use this form for proposals to drill or to deepen Use "APPLICATION FOR PERMIT - "	or reentry to a differen	nt reservoir.	5. Lease Designation and Sarial No. SF-078095 6. If Indian, Allottee or Tribe Name
		50 CCT 14 F112: 4	
		070 691	7. If Unit or CA, Agreement Designation
1. Type of Well Oit Well Well Other		······································	8. Well Name and No.
2. Name of Operator AMOCO PRODUCTION COMPANY	Attention: Gail M.	Jefferson	Case B #3A
3. Address and Telephone No.		(000) 000 0155	3004523175
P.O. BOX 800 DENVER, COLORADO 80201		(303) 830-6157	10. Field and Pool, or Exploratory Area
4. Location of Well (Footage, Soc., T., R., M., or Survey Description) 1790' FNL 1180' FWL Sec. 1	7 T 31N R	11W UNIT E	Blanco Mesaverde
12. CHECK APPROPRIATE BOX(s) TO I	NDICATE NA		SAN JUAN NEW MEXICO
TYPE OF SUBMISSION		TYPE OF ACTION	
Notice of Intent Subsequent Report Final Abandonment Notice 13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, immarkers and zones pertinent to this work.)* Amoco Production Company requests permission If you have any technical questions please contact	to perf and frac	(Note: Repor	I per the attached procedures.
<b>۴</b> ۰	DEC N OCT	EIVE()) 2 1 1998	
14. I hareby certify that the foregoing is true, and correct Signed	OUL CO D	0056 (1).116 1976 3 Sr. Admin. Stat	f Asst. Date 10-09-1998
(This space for Federal or State office use)			
Approved by /S/ Duane W. Spencer	Title	· · · · · · · · · · · · · · · · · · ·	Date 0CT 1 9 1998
Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any departmen	nt or agency of the United State	es any felse, ficticious, or freudulent statements or	representations as to any matter within its jurisdiction.
	* See Instruction	ns on Reverse Side	· · · · · · · · · · · · · · · · · · ·
E	NMOCE		J

NMOCD

Case B #3A TD = 5528' PBTD = 5511' Page 2 of 2

- 1. Check anchors. MIRUSU.
- 2. Check and record tubing, casing and bradenhead pressures.
- 3. Blow down wellhead, kill if necessary.
- 4. Nipple down wellhead, nipple up and pressure test BOP.
- 5. Tag and Tally OH with 2.375" tubing.
- 6. RU wireline unit and packoff.
- Perforate one shot at each of the following depths. Correlate with density log dated 6/20/79 (20 total holes):

4354 4377 4435, 4442 4450, 4456 4484, 4488 4500, 4504, 4508 4615, 4628 4644, 4648, 4652, 4658 4744, 4746 4785

- 8. Set a composite bridge plug @ 4825'.
- 9. TIH with 2 7/8" frac string and PIP.
- 10. Break down each interval (10 total) with 7 1/2% HCL (1/2 BBL per perforation, approximately 420 gallons total).
- 11. TOH with 2 7/8" frac string and PIP.
- 12. TIH with 2 7/8" frac string and packer.
- 13. Pressure test composite bridge plug.
- 14. Set packer at +/- 4275'
- 15. Fracture stimulate down 2 7/8" tubing according to frac schedule.
- 16. TOH with Frac String.
- 17. TIH with tubing and bit to PBTD and circulate clean.
- 18. Raise bit to +/- 5450 and reverse circulate until gas production returns.
- 19. If night shutdown is necesary, raise bit above 4300'.
- 20. Once gas production returns/sand production ceases, double check PBTD and TOH with tubing and bit.
- 21. TIH with 2 3/8" tubing with SN and land at 5410'.

Case B #3A TD = 5528' PBTD = 5511' Page 3 of 2

-

22. Put well back on production.

