Form 3160-5 (November 1983) (Formerly 9-331) DFPART	UNITED STATES MENT OF THE INTER	SUBMIT IN TRIPLICA	re Expires August 31, 1985
	AU OF LAND MANAGEMEN	IOR verse side)	5. LEASE DESIGNATION AND BERIAL NO. SF-078707
(Do not use this form for prop Use "APPLIC	6. IF INDIAN, ALLOTTEE OR TRIBE NAME / N/A		
1. OIL GABXX OTHER	7. UNIT AGREEMENT NAME N/A		
2. NAME OF OPERATOR Snyder Oil Corporation (505) 632-8056			8. PARM OR LEASE NAME DUKE 1M
3. ADDRESS OF OPERATOR P.O. 2038 Farmington, NM 87499			9. WBLL NO. 2364800
 LOCATION OF WELL (Report location See also space 17 below.) At surface 	10. FIELD AND FOOL OF WILDCAT MV Basin DK/Blanco MV		
1640' FSL & 790' FWL, Sec 13, T31N, R13W, NMPM			11. BEC., T., B., M., OR BLE. AND SURVEY OR AREA
14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)			12. COUNTY OF PARISH 13. STATE San Juan NM
10. Check A	ppropriate Box To Indicate N		
		SUB	SEQUENT REPORT OF:
TEST WATER SHUT-OFF	PULL OR ALTER CASING	WATER SHUT-OFF	REPAIRING WELL
SHOUT OR ACIDIZE	MULTIPLE COMPLETE	FRACTURE TREATMENT	ALTEBING CABING
REFAIR WELL	CHANGE PLANS	SHOOTING OR ACIDIZING	ABANDONMENT [®]
(Other)		(Other)	ults of multiple completion on Well
nent to this work.) *		t details, and give pertinent da lions and measured and true ver	mapletion Report and Log form.) tes, including estimated date of starting any rtical depths for all markers and zones perti-
Subjec	ct: This well was on March 21,	Plugged & Abano 1994	loned
Per at	ttached report.		
		DECEIVE)] 12
		OIL CON. DIV Dist. 3	
	Approved as to plug Liability under bond surface restoration i	ging of the well bore. Is retained until Completed.	
Mary 10			
18. I hereby certify that the foregoing i			02/21/04
Wayne Conv	TITLE	Engineer	03/31/94
(This space for Federal or State off	lce usc)		
APPROVED BY CONDITIONS OF APPROVAL, IF A	TITLE		
	•		APPROVED
	*San Instructure	on Reverse Side	APR 1 3 1994
	NMOCD	SH REFEISE JILLE	CIETRICT MANAGER

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations are transmission to average the statement of agency of the

1

1

na geografia geografia (* 1840). Na geografia geografia (* 1840). Na geografia

Page 1 of 2

March 23, 1994

Snyder Oil Corporation **Duke #1M** (MV/Dk) 1640' FSL, 790' FWL Sec. 13, T31N, R13W San Juan County, NM SF 078707

PLUG AND ABANDONMENT REPORT

Cementing Summary:

- Plug #1 from 6890' to 6620' inside 5-1/2" casing over Dk perfs with 35 sxs Class B cement, displace to 5900' then pressured up to 900#.
- Plug #2 from 5450' to 5300' with 17 sxs Class B cement.
- Plug #3 from 4805' to 3040' with 200 sxs Class B cement over Mesaverde perfs.
- Plug #4 with retainer at 2774', pump 10 sxs Class B cement on top of CR inside casing to 2686'.
- Plug #5 with retainer at 2097', pump 152 sxs Class B cement, squeeze 137 sxs below retainer from 2161' to 1705' outside casing; pressured up to 1,000#; spot 15 sxs above retainer to 1965'.
- Plug #6 from 1806' to 1656' with 17 sxs Class B cement inside casing.

Plugging Summary:

3-17-94 Safety meeting. Drive rig and equipment to location. Rig up. Rig up relief lines and blow well down. Check well for H2S; none. Kill both strings of tubing and 5-1/2" casing with 180 bbl water. Continue pumping water down casing to keep casing dead. ND wellhead. PU on MV side, found 1-1/4" tubing stuck. Attempt to work 1-1/4" tubing free. By pulling 30,000# (19,000# over string weight) made 38' up hole; then tubing parted. POH and LD Mesaverde 1-1/4" tubing (88 jts, 2848'). Tubing was parted in half on the 88th jt. Shut in well.

March 23, 1994

Page 2 of 2

Snyder Oil Corporation **Duke #1M** (MV/Dk) 1640' FSL, 790' FWL Sec. 13, T31N, R13W San Juan County, NM SF 078707

PLUG AND ABANDONMENT REPORT

Plugging Summary (contd):

- 3-18-94 Safety meeting. Open up well. Pressure 200# on casing, no pressure on Dk tubing. Blow down casing. Attempt to work 1-1/2" Dk tubing free, pull up to 35,000# (16,000# over string weight); tubing stuck. Establish rate down 1-1/2" Dk tubing of 1-1/2 bpm 400#. Procedure change approved by W. Townsend with BLM. Plug #1 from 6890' to 6620' inside 5-1/2" casing over Dk perfs with 35 sxs Class B cement, displace to 5900' then pressured up to 900#. Shut in tubing and WOC. Open up well. RIH with wireline and tag TOC at 5490'. POH with wireline. Pressure test tubing to 750#, bleed off to 500# in 1-1/2 minutes. Rig up wireline with 1.390" tubing cutter. TIH with wireline and jet cut 1-1/2" tubing at 5450'. POH with wireline. Attempt to work tubing free; pull up to 12,000# over string weight, tubing stuck. Establish circulation down tubing. Plug #2 from 5450' to 5300' with 17 sxs Class B cement. Rig up wireline with 1.390" tubing cutter. RIH with wireline and jet cut tubing at 4805'. POH with wireline. Attempt to work tubing free; pull up to 11,000# over string weight, tubing stuck. Plug #3 from 4805' to 3040' with 200 sxs Class B cement over Mesaverde perfs. Rig up wireline with 1.390" tubing cutter. RIH with wireline and jet cut tubing at 2833'. POH with wireline. Work tubing free. POH with tubing above cement. Shut in well. SDFN.
- 3-21-94 Safety meeting. Open up well. POH and tally 86 jts 1-1/2" tubing. PU 5-1/2" cement retainer and RIH; set at 2774'. Sting out of CR. Load well with 17 bbl water. Sting into CR. Attempt to pump below cement retainer; pressured up to 800# with 3/4 bbl water. Sting out of CR. Plug #4 with retainer at 2774', pump 10 sxs Class B cement on top of CR inside casing to 2686'. POH to 2097'. Perforate 4 holes at 2161'. POH with wireline. PU 5-1/2" cement retainer and RIH; set at 2097'. Establish rate into holes 1-1/4 bpm at 600#. Plug #5 with retainer at 2097', pump 152 sxs Class B cement, squeeze 137 sxs below retainer from 2161' to 1705' outside casing; pressured up to 1,000#; spot 15 sxs above retainer to 1965'. POH to 1806'. Pressure test casing to 500#, held OK. Plug #6 from 1806' to 1656' with 17 sxs Class B cement inside casing. POH to 323'. Plug #7 from 323' to surface with 48 sxs Class B cement, circulate good cement out 5-1/2" casing. POH and LD tubing and setting tool. ND BOP. Dig out and cut off wellhead. Install P&A marker with 20 sxs cement. Rig down and move off location.

Procedure change approved by W. Townsend with BLM. H. Lujan with BLM was on location.