.

ι.,

#### UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

Sundry Notice.	s and Reports on Wells		
		5.	Lease Number NM-33055
. Type of Well GAS	рана (1993) 1997 — Прилански Сери, 1993 1997 — Прилански Сери, 1993	6.	If Indian, All. or Tribe Name
		7.	Unit Agreement Name
. Name of Operator			
BURLINGTON RESOURCES OIL & G	GAS COMPANY		
		8.	Well Name & Number Trail Canyon #2
3. Address & Phone No. of Operator PO Box 4289, Farmington, NM 8	7499 (505) 326-9700	9.	API Well No. 30-045-24590
4. Location of Well, Footage, Sec., T, R, M 1560'FNL, 830'FEL, Sec.18, T-32-N, R-8-W, NMPM			Field and Pool Blanco Mesaverde/ Trail Canyon Gallu
		11.	County and State San Juan Co, NM
12. CHECK APPROPRIATE BOX TO INDIC		RT, OTHER	DATA
Type of Submission _X_ Notice of Intent		nge of Pla Construct	

_^_	NOULCE OF INCENC	Recompletion New Construction
	Subsequent Report	Plugging Back Non-Routine Fracturing Casing Repair Water Shut off
	Final Abandonment	Altering Casing Conversion to Injection XX Other - Commingle or P&A Gallup

## 13. Describe Proposed or Completed Operations

It is intended to retrieve the packer and commingle the subject well according to the attached procedure. If the packer will not come free, the Gallup formation will be plugged and abandoned.

14. I hereby certify that the for	regoing is	true and correct.	
signed Juggy Call	Title	Regulatory Supervisor	
(This space for Federal or State O APPROVED BY	office use) Title	Date	MAR 29 694
CONDITION OF APPROVAL, if any: Title 18 U.S.C. Section 1001, makes it a crime for any pe United States any false, fictitious or fraudulent stateme	ents or representa	d willfully to make to any departme tions as to any matter within its j	nt or agency of the urisdiction.

# **TRAIL CANYON 2**

Blanco Mesaverde/Gallup AIN: 151001/151002 1560' FNL & 830' FEL Unit H, Sec. 18, T32N, R08W Latitude 36° 59.231' / Longitude 107° 42.561' **Recommended Commingle Procedure** 

### Project Summary:

The Trail Canyon 2 was drilled in 1981, and completed open-hole in the Gallup formation. An attempt was made in 1983 to commingle this well during a recompletion to the Mesaverde formation. A Baker model "A-3" Lok-set packer with model "FWG" bypass blanking plug was set at 7500'. Attempts to latch onto the packer with the on/off tool were unsuccessful and efforts were abandoned after two days. Bixco did not attempt to retrieve and replace the packer. Therefore the Gallup was ignored, leaving 40-50 MCFD below the packer. Current Mesaverde production is 40 MCF/D.

The OCD requires us to either properly P&A the Gallup zone, or remove the packer and continue producing the Gallup zone. It is proposed to try and retrieve the packer, and commingle the Gallup and Mesaverde with a single string of 2 3/8" tubing. Uplift is estimated at 40-50 MCFD. If the Gallup will not produce or we cannot economically retrieve the packer, the Gallup will be P&A'd, and the well returned to a single Mesaverde completion.

### Commingle Procedure:

- Comply with all NMOCD, BLM and Burlington safety and environmental regulations. Test rig anchors and build 1 blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Cole 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
- MOL and RU workover rig. Conduct safety meeting for all personnel on location. NU relief line. Blow down 2. well and kill with 2% KCL water as necessary. ND wellhead and NU BOP. Test and record operation of BOP rams. Test secondary seal and replace/install as necessary.
- TOOH standing up the 2-3/8" Mesaverde tubing (set at 5983'). 3.
- Pick up 2-3/8" N-80 work-string. TIH w/ 3-7/8" rotary shoe with Kutrite on leading edge only (smooth ID, smooth 4. OD, with brass tattle tale), 6 3-1/8" drill collars, and 2-3/8" work-string. Clean out w/ air/mist down to packer, and then wash-over Baker Lock-Set on/off tool (w/ FWG plug) with air/mist. Packer is set at 7500'. Note: when using air/mist, the minimum mist rate is 12 bph. Try to maintain air rate at 1,400 cfm.
- Round trip work-string replacing rotary shoe with retrieving tool and attempt to retrieve Baker Lok-Set packer. 5.
- If packer will not come free, round trip work-string replacing retrieving tool with short catch overshot, bumper sub, 6. hydraulic jars, 6 drill collars, intensifier, and tubing. Attempt to latch onto on/off tool. If successful, pull at least 3000# over string weight and rotate tubing to the right eight to ten turns at the tool. TOOH and lay down fishing, tools, and packer.
- If packer has not come free in 2 days (consult with engineer), the Gallup will be P&A'd by placing 100ft of 7. cement on top of the packer. The well will be returned to its prior configuration as a Mesaverde well.
- If the packer has come free, TIH w/ work-string (which should still be in the derrick) with 3-7/8" bit, 6 dirll 8. collars, and 2-3/8" work-string. Clean out to PBTD at 7597'. TOOH laying down work-string.
- TIH with seating nipple and expendable check (if necessary) on bottom of 2-3/8" tubing. Place a 2' pup joint one 9.

joint off bottom to serve as a marker joint. Broach all tubing and land at approximately 7530'. ND BOP and NU wellhead. Pump off expendable check and blow well in.

10. During cleanout operations the reservoir may be charged with air. As a result of excess oxygen levels that may be in the reservoir and/or wellbore, contact the Lease Operator to discuss the need for determining oxygen levels prior to returning the well or production. RD and MOL. Return well to production.

Bruce W. Bough 1.12.01 Drilling Superintenden Approved: Recommended; Operations Engineer Required: Yes X No \_\_\_\_ 1001 Regulatory Approv Kevin W Book **Operations Engineer:** BR Office - 326-9530 Pager - 326-8848 Home - 326-6236 Cell: 320-2532 Pager: 326-8418 Mark Glover Lease Operator: Cell: 320-0436 Pager: 324-2468 Wayne Ritter Office: 326-9818 Specialist/Foreman: