State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

Sundry Notices and Reports on Wells

	API # (assigned by OCD) 30-045-24675
L. Type of Well	5. Lease Number
GAS	FEE
	6. State Oil&Gas Lease #
2. Name of Operator	7. Lease Name/Unit Name
BURLINGTON RESOURCES OTL & GAS COMPANY	
RESOURCES OIL & GAS COMPANY	Harper 8. Well No.
3. Address & Phone No. of Operator	8. Well No. #3
PO Box 4289, Farmington, NM 87499 (505) 326-9700	· · · · · · · · · · · · · · · · · · ·
	Aztec PC/Basin Frt Coa
4. Location of Well, Footage, Sec., T, R, M	10. Elevation: Glades FYT S
970' FSL, 1090' FEL, Sec.14, T-31-N, R-12-W, NMPN	4, San Juan County, NM
Type of Submission Type of J	
X Notice of Intent _X_ Abandonment	Change of Plans New Construction
Subsequent Report Plugging Back	Non-Routine Fracturing
Subsequent Report fragging Such	Water Shut off
Final Abandonment Altering Casing	Conversion to Injection
Other	
It is intended to plug and abandon the subject	well according to the attached
It is intended to plug and abandon the subject procedure and wellbore diagram.	well according to the attached
	well according to the attached
	well according to the attached
	well according to the attached DECENDED MAR 1 6 1993
	DEGEIVED Mar 1 6 1993
	DEGEIVED MAR 1 6 1993 OIL CON. DIV.
	REGEIVED MAR 1 6 1993
	DEGEIVED MAR 1 6 1993 OIL CON. DIV.
procedure and wellbore diagram.	DECEIVED MAR 1 6 1993 OIL CON. DIV. DIST. 3
procedure and wellbore diagram.	DECEIVED MAR 1 6 1993 OIL CON. DIV. DIST. 3
SIGNATORE AGAIN Statucer Regulatory Ad	DECEIVED MAR 1 6 1993 OIL CON. DIV. DIST. 3
SIGNATORE USE)	DECEIVED MAR 1 6 1993 ONL CON. DOV. DIST. 3 ministrator_March 12, 1998 VKH
SIGNATORE John State Use)	DECEIVED MAR 1 6 1993 ONL CON. DOV. DIST. 3 ministrator_March 12, 1998 VKH
SIGNATORE AND State Use) Approved by Johnny Robinson Title	DECEIVED MAR 1 6 1993 ONL CON. DOV. DIST. 3 ministrator_March 12, 1998 VKH
SIGNATORE AM Statuer Regulatory Ad	DECEIVED MAR 1 6 1993 OIL CON. DIV. DIST. 3 ministrator_March 12, 1998 VKH

PLUG AND ABANDONMENT PROCEDURE

Harper #3 Blanco Pictured Cliffs / Fruitland Coal 970' FSL and 1090 FEL / SE, Sec. 14, T31N, R12W San Juan County, New Mexico

- Note: All cement volumes use 100% excess outside pipe and 50' excess inside pipe. The stabilizing wellbore fluid will be 8.3 ppg, sufficient to balance all exposed formation pressures.
- 1. Install and test rig anchors. Prepare blow pit. Comply with all NMOCD, BLM and Burlington safety rules and regulations.
- 2. MOL and RU daylight pulling unit. Conduct safety meeting for all personnel on location. NU relief line to blow well down; kill with water as necessary. ND wellhead and NU BOP and stripping head; test BOP.
- 3. Open bradenhead valve. Establish rate down the Fruitland 2-7/8" casing with 20 bbls water, record pump rate and pressure. Monitor bradenhead for flow. If no flow or blow then pump 4 frac balls in additional water and monitor pressure, rate and volumes pumped, to confirm perforations taking water and there is not a casing leak. If bradenhead flows water or there are other indications of a casing leak, then use 1-1/4" tubing to plug well. Repeat pump in procedure for the Pictured Cliffs 2-7/8" casing; monitor bradenhead. If either casing string has a leak, then spot or tag subsequent plugs as appropriate.
- 4. Plug #1 (Pictured Cliffs perforations and Fruitland top, 2810' 2162'): With the Pictured Cliffs' casing, establish rate into Pictured Cliffs perforations with water. Mix and pump 50 sxs. Class B cement down 2-7/8" casing (20% excess), displace to 1300'. Shut in well and WOC. Rig up wireline and RIH and tag cement.
- 5. Plug #2 (Fruitland perforations to surface, 2550' Surface): With the Fruitland's casing, establish rate into Fruitland Coal perforations with water. Mix and pump 84 sxs. Class B cement down 2-7/8" casing (20% excess); do not displace. Shut in well and WOC. Tag cement, fill as necessary.
- 6. Plug #3 (Kirtland and Ojo Alamo tops, 1075' 855'): With the Pictured Cliffs' casing, pressure test to 500#. Perforate 2 squeeze holes at 1075'. Establish rate into squeeze holes. Mix 138 sxs. Class B cement and squeeze 122 sxs. outside 2-7/8" casing and leave 16 sxs. inside, displace to 500', to cover Kirtland and Ojo Alamo tops. $\frac{4}{5}$ Tat compatible 5.5'
- 7. Plug #4 (Surface Casing at 139'): With the Pictured Cliffs' casing, pressure test to 500#. Perforate 2 squeeze holes at 189'. Establish rate out bradenhead. Mix and pump approximately 61 sxs. Class cement inside casing from 189' to surface, circulate good cement out bradenhead. Shut well in and WOC.
- 8. ND BOP and cut off wellhead below surface casing flange. Install P&A marker with cement to comply with regulations. RD, MOL, cut off anchors and restore location.

Recommended: <u>M.E. Sixtu</u> Operations Engineer

Approval:





TD 2920'