## State of New Mexico / Energy, Minerals and Natural Resources Department Oil Conservation Division

|                         |   | Sundry Notice                               | es and Reports on W   | ells  |
|-------------------------|---|---|---|---|
| 1. Type of GAS          | Well  |   | Section to the second section of the second section of the second section of the second section of the second | API # (assigned by OCD) 30-045-25812 5. Lease Number Fee 6. State Oil&Gas Lease |
| 2. Name of RES          | LINGTON   | GAS COMPANY                                 | DECEIVE<br>FEB 1 2 1999   | Lease Name/Unit Name  |
|                         | & Phone No. of Operat<br>4289, Farmington, NM                               |   | 011 CON. DI   | 8. Well No.  22A  Pool Name or Wildcat  Blanco Mesaverde                        |
| 4. Location<br>1470'FNL | of Well, Footage, Se<br>1850'FWL, Sec.25, T-                                | c., T, R, M<br>32-N, R-7-W, NM              | IPM, San Juan Count   | 10. Elevation:  |
| _x_                     | Submission Notice of Intent Subsequent Report Final Abandonment             | Abandonmen Recompleti Plugging B Casing Rep | on New Constack Non-Rout:   | cruction<br>ine Fracturing<br>ut off  |
|                         | <pre>ibe Proposed or Compl intended to repair t   attached procedure.</pre> | he tubing on th                             |   | ording to the   |
| SIGNATURE               | Stad he   | (MEL6) Regu                                 | latory Administrato   | orFebruary 10, 1999<br>   |
|                         | for State Use)  | .penow <b>DEPUT</b>                         | ' OIL & GAS INSPECTOR, DIS  | T. 43 FEB 12 1999   |

## Allison Unit #22A

## Mesaverde 1470'FNL, 1850' FWL

Unit F, Section 25, T-32-N, R-7-W

Latitude / Longitude: 36° 57.258' / 107° 31.2148' DPNO: 5265001

**Tubing Repair Procedure** 

- Hold safety meeting. Comply with all NMOCD, BLM and Burlington safety and environmental 1. regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
- MOL and RU workover rig. Obtain and record all wellhead pressures. NU relief line. Blow 2. well down and kill with 2% KCL water if necessary. ND WH and NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. Test secondary seal and replace/install as necessary.
- Mesaverde, 2-3/8", 4.7# J-55 tubing is set at 6128'. Release donut, pick straight up on 2-3/8" 3. tubing to release the Baker Model "R" packer (@ 4891'). PU additional joints of tubing and tag bottom. (Record depth). PBTD should be at +/- 6222'. TOOH with tubing. Visually inspect tubing for corrosion and replace any bad joints. Check tubing for scale build up and notify Operations Engineer.
- If fill is encountered, TIH with 3-7/8" bit, bit sub and watermelon mill on 2-3/8" tubing and 4. round trip to below perforations, cleaning out with air/mist. NOTE: When using air/mist, minimum mist rate is 12 bph. If scale is present, contact Operations Engineer to determine methodology for removing scale from casing and perforations.
- TIH with one joint of 2-3/8" tubing with an expendable check on bottom and a seating nipple one 5. joint off bottom then ½ of the 2-3/8" production tubing. Run a broach on sandline to insure that the tubing is clear. TIH with remaining 2-3/8" tubing and then broach this tubing. Replace any bad joints. CO to PBTD with air/mist. PU above the perforations and flow the well naturally, making short trips for clean up when necessary.
- Land tubing at ±6058'. ND BOP and NU WH. Pump off expendable check. Connect to casing 6. and circulate air to assure that expendable check has pumped off. Obtain pitot gauge up the tubing. If well will not flow up the tubing, make swab run to SN. RD and MOL. Return well to production.

Recommended: ME Autua Operations Engineer

Approved: Bruce D. Bowy 1. 27-99
Drilling Superintendent

Operations Engineer: Mary Ellen Lutey

> Office - (599-4052) Home - (325-9387) Pager - (324-2671)