## State of New Mexico Energy, Minerals and Natural Resources Department Oil Conservation Division

	Sundry Notices and Reports	on Wells	
		API	# (assigned by OCD)
			45-60066
1. Type of Well		5.	Lease Number
GAS			Fee
		6.	State Oil&Gas Lease #
2. Name of Operator		7.	Lease Name/Unit Name
BURLINGTON RESOURCES OTL			
RESOURCES OIL	& GAS COMPANY		Culpepper Martin
		8.	
3. Address & Phone No. of Opera			#8
PO Box 4289, Farmington, NM	87499 (505) 326-9700	9.	Pool Name or Wildcat Blanco Mesaverde
4. Location of Well, Footage, S			Elevation:
990'FSL, 1650'FWL, Sec.19, T-32	-N, R-12-W, NMPM, San Juan Co	unty, NM	
Type of Submission	Type of Action		
_X_ Notice of Intent		nge of Pla	
	<del></del>	Construct	
Subsequent Report	<u> </u>		Fracturing
	~ ~	er Shut of	
Final Abandonment	Altering Casing Con	version to	o Injection
	_X_ Other - Tubing Repair		
It is intended to repair procedure.		1 5 1999 0 NJ. DIV	
(This space for State Use)	Regulatory Administra	t	rc
	Title		Date
Approved by	11616		

## Culpepper Martin #8

Mesaverde 990'FSL, 1650' FWL

Unit N, Section 19, T-32-N, R-12-W

Latitude / Longitude: 36° 58.0444' / 108° 8.3542'

DPNO: 1067401 MV **Tubing Repair Procedure** 

- Hold safety meeting. Comply with all NMOCD, BLM and Burlington safety and environmental 1. regulations. Test rig anchors and build blow pit prior to moving in rig. Notify BROG Regulatory (Peggy Bradfield 326-9727) and the appropriate Regulatory Agency prior to pumping any cement job. If an unplanned cement job is required, approval is required before the job can be pumped. If verbal approval is obtained, document approval in DIMS/WIMS. Allow as much time as possible prior to pump time in case the Agency decides to witness the cement job.
- MOL and RU workover rig. Obtain and record all wellhead pressures. NU relief line. Blow 2. well down and kill with 2% KCL water if necessary. ND WH and NU BOP with stripping head. Test and record operation of BOP rams. Have wellhead and valves serviced as necessary. Test secondary seal and replace/install as necessary.
- Mesaverde, 2-3/8", 4.7# tubing is set at 4691'. Release donut, pick up additional joints of tubing 3. and tag bottom. (Record depth.) PBTD should be at +/-4856'. TOOH with tubing. Visually inspect tubing for corrosion and replace any bad joints. Check tubing for scale build up and notify Operations Engineer.
- If fill is encountered, TIH with 4-3/4" bit, bit sub and watermelon mill on 2-3/8" tubing and 4. round trip to below perforations, cleaning out with air/mist. NOTE: When using air/mist, minimum mist rate is 12 bph. If scale is present, contact Operations Engineer to determine methodology for removing scale from casing and perforations.
- TIH with one joint of 2-3/8" tubing with an expendable check on bottom and a seating nipple one 5. joint off bottom then ½ of the 2-3/8" production tubing. Run a broach on sandline to insure that the tubing is clear. TIH with remaining 2-3/8" tubing and then broach this tubing. Replace any bad joints. CO to PBTD with air/mist. PU above the perforations and flow the well naturally, making short trips for clean up when necessary.
- Land tubing at ±4680'. ND BOP and NU WH. Pump off expendable check. Connect to casing 6. and circulate air to assure that expendable check has pumped off. Obtain pitot gauge up the tubing. If well will not flow up the tubing, make swab run to SN. RD and MOL. Return well to

Recommended: 11. E Sutary
Operations Engineer

Approved:

Bruce D. Bory 6.4.99
Drilling Superintendent

的法 通识

Operations Engineer:

Mary Ellen Lutey

Office - (599-4052) Home - (325-9387) Pager - (324-2671)

MEL/klg

