Submit 3 Copies To Appropriate District Office	Office			Form C-103 October 13, 2009
District I 1625 N. French Dr., Hobbs, NM 8240 District II 1301 W. Grand Ave, Artesia, NN 88210 District III 1301 Strict III 1301 W. Grand Ave, Artesia, NN 88210 District III 1220 South St. Francis Dr			WELL API NO.	
District II			30-025-08009	
1301 W. Grand Ave, Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of Lease	_ /	
1000 Big Brange Bd. Artes NM974 INN 9 0 2044			EE	
District IV 1220 S. St. Francis Dr., Santa Fe, NM			6. State Oil & Gas Lease N	lo.
87505 SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			7. Lease Name or Unit Age State BB NCT-1	reement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			8. Well Number 2 SWD	
1. Type of Well: Oil Well 🛛 Gas Well 🗌 Other				
2. Name of Operator PALADIN ENERGY CORP.			9. OGRID Number 164070	
 Address of Operator 10290 Monroe Drive, Suite 301, Dallas, Texas 75229 			10. Pool name or Wildcat Caprock:Devonian, East (8930)	
4. Well Location				
Unit Letter N: 660 feet from the North line and 1984 feet from the West line				
Section 11		ange 32E		County
	L. Elevation (Show whether DR, 4367' GR	<i>KKB</i> , <i>K</i> 1, <i>GK</i> , <i>etc.)</i>		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data				
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:				
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK				
TEMPORARILY ABANDON 🔲 CHANGE PLANS 🔲 COMMENCE DRI				· 🗌
PULL OR ALTER CASING 🔲 MULTIPLE COMPL 🔲 CASING/CEMEN			ГЈОВ 🗌	
DOWNHOLE COMMINGLE				
OTHER:		OTHER:		
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.				
 MIRU, GIH with 2-7/8" tubing and packer, set packer at 3,850' (+,-). R/U pumping unit and establish injection rate. Pump 880 sacks of class H cement and plug 5-1/2" casing from 3,900' to TD at 11,226'. Release packer, POOH. 				
WOC. Tag cement.				
2.)ACut 5-1/2" casing at 3,900' or deepest free point and pull. GIH w/ 2-7/8" tubing and set 200' cement stub plug (in and				
 <u>out of 5-1/2 " casing) from 4,000' to 3,800' with 35 sacks class H cement. WOC. Tag plug at 3,800'.</u> <u>So securt</u> <u>3.) Perforate 8-5/8" casing at 1,850' for squeeze. GBIH with tubing and packer, squeeze perfs and set 100' cement plug with 35 sacks Class H cement from 1,850' to 1,750' in <i>So for squeeze</i>.</u> 				
Cement.				
4.) Perforate 8-5/8" casing at 400' for circulation. GBIH with tubing and packer and circulate cement to surface and fill casing to surface with class H cement. WOC. Tag plug.				
5.) Cut all casing 3' below mud line. Backfill, set P&A marker, clear location.				
Spud Date:	Rig Release Da	ite:		
	· · · · · · · · · · · · · · · · · · ·		11.1.6	
I hereby certify that the information above is true and complete to the best of my knowledge and belief.				
SIGNATURE David Plaisance	V.P	. Exploration & Pro	DATE	4/2011
Type or print name E-mail address: PHONE:				
For State Use Only				
APPROVED BY:	TITLE J	DII MG	DATE //	7-2011
\bigcirc				

State BB NCT-1 Well #1



PROPOSED P&A