Submit 1 Copy To Appropriate District Office State of New Mexico District I - (575) 393-6161 Energy, Minerals and Natural Resources 1625 N French Dr, Hobbs, Nuccess OCD District II - (575) 748-1283 OCD District III - (575) 748-1283 OIL CONSERVATION DIVISION 111 S. First St, Artesia, NM 88210 OIL CONSERVATION DIVISION District III - (505) 334-6178 9 2012 1000 Rio Brazos Rd, Aztec, NAUGU 9 2012 OIL CONSERVATION DIVISION 1220 S outh St, Francis Dr, Santa Fe, NM Santa Fe, NM 87505 1220 S St. Francis Dr, Santa Fe, NM Santa Fe, NM 87505 SUNDRY NOTICES AND REPORTS ON WELLS ON NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) I. Type of Well: Oil Well Gas Well 1. Type of Well: Oil Well Gas Well Other Injector 2. Name of Operator Chevron U. S. A. Inc. 3. Address of Operator	Form C-103 Revised August 1, 2011 WELL API NO. 30-025-32771 5. Indicate Type of Lease STATE FEE 6. State Oil & Gas Lease No. 7. Lease Name or Unit Agreement Name West Dollarhide Drinkard Unit 8. Well Number 152 9. OGRID Number 4323 10. Pool name or Wildcat
15 Smith Rd. Midland, TX 79705 4. Well Location	Dollarhide Tubb Drinkard
Unit Letter M : 600_feet from the South line and Section 29 Township 24S Range 38E 11. Elevation (Show whether DR, RKB, RT, GR, etc., 3173'GR 3173'GR	NMPM County Lea
12. Check Appropriate Box to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO: SUB PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMENT DOWNHOLE COMMINGLE CASING/CEMENT	
OTHER: Sqz casing C/O & Acidize OTHPer Underg	round Injection Control Program Manual
13. Describe proposed or completed operations. (Clearly state all pertinent details an of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Comproposed completion or recompletion.	e uppermost injection perfs or open hole.
The Oil Conservation Division	Condition of Approval: notify OCD Hobbs office 24 hours rior of running MIT Test & Chart
MUST BE NOTIFIED 24 Hours Spud Date Rig Release Date:	
I hereby certify that the information above is true and complete to the best of my knowledg	e and belief.
SIGNATURE SEATH GND	DATE08/07/2012
Type or print nameScott HaynesE-mail address:toxo@chevro	n.com PHONE: 432-687-7198
APPROVED BY Conditions of Approval (if any):	DATE <u>8-10-2012</u>
	AUG 1 3 2012

PROCEDURE:

- 1. Notify NMOCD 48 hours prior to MIRU. Notify Baker Gel supervisor (432-59-3955) to test compatibility of the MARA-SEAL treatment with the source fresh water.
- 2. Ensure location is in appropriate condition, anchors have been tested within the last 24 months and power line distance has been verified to determine if variance is needed.
- 3. Check and record SITP and SICP on wellview. Determine kill fluid weight. RU slickline and attempt to set blanking plug. Bleed off pressure.
- 4. MIRU.
- Caliper elevators and tubular EACH DAY prior to handling tubing/tools. Note in JSA when and what items are callipered within the task step that includes that work.
- 5. ND WH. NU 5K BOP with blinds in bottom and 2-3/8" pipe rams in top.
- 6. Release on/off tool. LD 2 top joints. PU/RIH packer and set it ~ 25'. Test BOP pipe rams to 250 psi/1000 psi. Release and LD packer. PU/RIH 2 top joints back in the hole. POOH scanning all 2-3/8" injection tubing. Plan to replace on/off tool and injection packer. LD any bad joints (green and red). Do not release injection packer with injection string to avoid damaging IPC.
- Caliper elevators and tubular EACH DAY prior to handling tubing/tools. Note in JSA when and what items are callipered within the task step that includes that work.
- 7. PU/RIH with on/off tool overshot on 2-7/8" 6.5# L80 WS. Latch and release packer. POOH and LD injection packer.
- PU/RIH with 4-3/4" MT bit, 3-1/2" DC's on 2-7/8" 6.5# L80 WS. RIH and tag for fill (note fill depth on report). PU power swivel and C/O to PBTD (7030') and circulate well clean.

Note: Inspect returns and turn samples to Baker Chem Rep & ALCR for analysis and treatment recommendation. If there is evidence of sulfate scale, scale converter will be spotted prior to the acid job stage. Pump scale converter per Baker recommendations.

- 9. POOH and LD bit.
- 10. Isolate casing leak interval(s) by dumping sand in wellbore to plug back current perforations to \pm 6460'. Tag to verify sand top is within desired depth. Dump and bail 10' of cement on top leaving TOC ~ 6450'.
- 11. PU/RIH with 5-1/2" treating packer on 2-7/8" 6.5# L80 WS and set it 6210' (10' above previous packer depth). Hydrotest WS in the hole to 6000 psi.
- 12. Load and test casing to 500 psi. Monitor backside for communication. Perform pump-in test prior to treatment communicate results to Remedial Engineer and Baker Gel

supervisor (432-59-3955) for a squeeze recommendation. Do not plan to shoot squeeze perforations prior to test.

- 13. Follow attached treatment recommendation from Baker Hughes for squeezing casing leaks with MARA-SEAL gel. Shut-in well for 2 days or as recommended by Baker Hughes.
- 14. Release packer and POOH.
- 15. PU/RIH with 4-3/4" MT bit, 3-1/2" DC's on 2-7/8" 6.5# L80 WS. RIH and tag for gel (note depth on report). PU power swivel and C/O to PBTD (7030') and circulate well clean. POOH.
- 16. PU/RIH with 8 joints tailpipe, 5-1/2" treating packer on 2-7/8" 6.5# L80 WS. Set packer at 6210' leaving EOT ~ 6460'. Load and test casing to 500 psi.
- 17. MIRU acid contractor. Monitor casing pressure throughout acid job. Bleed off if pressure exceeds 500 psi during acid job. RU choke manifold to flowback tank. Acidize perforations (6464-7010') with 12,000 gals NEFe 15% HCl in 5 stages dropping graded rock salt (GRS) between stages to divert at 1-2 PPG. Flush to bottom perf @ 7010'. Maximum pumping pressure is 5000 psi. Set pop-off in pump to less than 5500 psi.
- 18. Record ISIP, 5, 10, & 15 minute SIP's. Allow acid to spend 2 hours. Flow well back on a choke.
- 19. Flow or swab back to recover acid volume. Kill tubing with 10 ppg brine if necessary. Report acid volumes and pressures on morning wellview report. Release packer. POOH and LD packer.
- 20. PU and RIH with notched collar and C/O to PBTD flushing remaining salt with fresh water. POOH and LD WS.

Caliper elevators and tubular EACH DAY prior to handling tubing/tools. Note in JSA when and what items are callipered within the task step that includes that work.

- 21. PU and RIH with new 5-1/2" AS-1X nickel-coated IPC as injection packer, with pumpout plug (rated 1500#), on/off tool with 1.81" 'F' stainless-steel profile nipple on 2-3/8"
 4.7# J-55 IPC injection tubing. RIH hydrotesting all tubing to 6500 psi. Set injection packer above all bad casing at ~ 6210'. Test casing to 500 psi for 5 minutes.
- 22. Load tubing. Disengage on/off tool, reverse circulate packer fluid. Engage back on/off tool. Perform preliminary MIT testing to 500 psi for 30 minutes.
- 23. ND BOP, NU WH.
- 24. Pump down tubing to shear-off pump-out plug.
- 25. Conduct MIT (mechanical integrity test). Pressure test casing to 500 psi and record chart for 30 minutes. Notify NMOCD of MIT with 4 hours advance notice with rig on well.
- 26. RDMO. Turn over well to operations (contacts in front page).

WELLBORE DIAGRAM CURRENT WDDU 152

FIELD: West Dollarhide Drinkard	l Unit	Well No: 152	FORMATION: DRKD
LOC: 600' FNL & 760' FEL	Sec: 29	GR. 3166'	CURRENT STATUS Injector
TOWNSHIP: 24S	Cnty: Lea	KB 3187'	API NO 30-025-32771
RANGE: 38E	State: NM	DF '	Chevno BC1105

