Submit 1 Copy To Appropriate District MOBBS OCD Office				Form C-103
Enargy Minorals and Notural Recourses			WELL API NO.	Revised August 1, 2011
District I – (575) 393-6161 1625 N French Dr., Hobbs, NM 88240 SEP 1 8 2012 District II – (575) 748-1283 811 S Eirst St. Artesia NM 88210 OIL CONSERVATION DIVISION			30-025-03198	
811 S First St., Artesia, NM 88210 Off. CONSERVATION DIVISION District III - (505) 334-6178 1220 South St. Francis Dr.			5. Indicate Type of Le	ś
1000 R to Brazos Rd., Aztec, NM 87410 District IV – (505) 476-3460 RECEIVED Santa Fc, NM 87505			STATE 🖂 6. State Oil & Gas Le	FEE
1220 S St Francis Dr., Santa Fe, NM 87505			0. Shate On the Gus De	
SUNDRY NOTICES AND RE	PORTS ON WELLS		7. Lease Name or Uni	1 Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL DIFFERENT RESERVOIR. USE "APPLICATION FOR PEI				
PROPOSALS.)			Northeast Pearl Queer 8. Well Number 01	
	Other Injection W	Vell		· _
2. Name of Operator Quantum Resources Management, LLC			9. OGRID Number 243874	
3. Address of Operator			10. Pool name or Wild	dcat
1401 McKinney St., Suite 2400, Houston, TX 770)10		Pearl; Queen	
4. Well Location				
	t from the <u>Nort</u>		<u>2310</u> feet from the	
	Fownship 19S 1 (Show whether DR,	Range 35E		County Lea
3787' RKB,		KKD, KT, CK, etc.)	185	
		<u> </u>		2
12. Check Appropriate I	Box to Indicate N	ature of Notice, 1	Report or Other Dat	a
NOTICE OF INTENTION	۲O	SUBS	SEQUENT REPO	
PERFORM REMEDIAL WORK D PLUG AND A		REMEDIAL WORK		
TEMPORARILY ABANDON		COMMENCE DRIL		ND A
		CASING/CEMENT	JOB 🗌	
OTHER.		OTHER:		
 Describe proposed or completed operation of starting any proposed work). SEE RUL proposed completion or recompletion. 				
Quantum Resources Management, LLC proposes to Mr. D. Bulman, Quantum, consulted w/Mr. M. M				::
-Sct packer at least 100' above top of fish @ 3933', 25sxs Class "C" cement to fill the tubing from 100' -Wait on cement 4 hours, tag. Top of cement must -If successful, perforate @ 3200' and squeeze benea -Perforate @ 1795', squeeze with 50sxs cement, wa -Perforate 50' below the surface casing shoe, shoe a -Cut off all casings and weld on ½" steel plate -Erect P&A marker -Commence surface restoration operations	above top of fish to be a minimum of 100 ath a packer with 50s it on cement 4 hours	the top perforation. D' above top of fish. xs cement, wait on o , tag top of cement.		
NMOCD Hobbs field office will be notified prior to	commencing pluggi	ng operations.		
		Γ		
Spud Date:	Rig Release Da	te:		
I hereby certify that the information above is true an	d complete to the be	st of my knowledge	and belief.	
1				
SIGNATURE_ Cullete A. Dale	TITLE_ <u>Sr. Re</u> g	ulatory Analyst	DATE_0	9/17/12
Type or print name <u>Celeste G. Dale</u> For State Use Only	E-mail address:	cdale@qracq.c	om PHONE:	432-683-1500
APPROVED BY: Wach Whitah	TITLEO	mptioner O.	ficor DATE	7-18-2012
Conditions of Approval (if any):				
24 hours pr	tion Division - Hobbs ior to the beginning of	office Must be No Plugging Operations	tified s begin	SEP 1 8 201

SEP 1 8 2012



Plugging Procedure

Objective Field/Zone	NEPQ #14 Plug and Abandon Wellbore Northeast Pearl Queen, Artesia Lea County, NM
Goal	Permanently plug and abandon wellbore
Casing Tubing Perfs Last Test: PBTD Notes:	3787' 2 7/8" to ~5100' 2 1/16" IJ IPC injection tbg 4956'-62', 67'-70', 74'-80', 91'-93', 5010'-14', 44'-5052' ~5100' 2 1/16" Arrowset AS1X Packer initially set @ 4932', TOF @ 3933' 2 7/8" 6.5# csg = 0.00578 bbls/ft

- 1. MIRU ND wellhead. NU BOP.
- 2. RIH with pkr on WS and set at approximately 3633'. Establish inj rate and pump minimum of 25 sxs Class C cmt to fill tbg above TOF to top perf.
- 3. PU 3 stands, reverse out, WOC 4 hrs, Tag TOC, Must be minimum 100' above TOF. POOH with WS.
- 4. RIH with Wireline and perf at 3200'. POOH with Wireline.
- 5. RIH with pkr on WS and set at approximately 3000'. Squeeze 50 sx of cement. PU 3 stands, reverse out, WOC 4 hrs, tag TOC. POOH with WS.
- 6. RIH with Wireline and perf at 1795'. POOH with Wireline.
- 7. RIH with pkr on WS and set at approximately 1595'. Squeeze 50 sx of cement. PU 3 stands, reverse out, WOC 4 hrs, tag TOC. POOH with WS.
- 8. RIH w/ Wireline and perf at 265'. POOH w/ Wireline. RU cmt and Circulate cement to surface. If well will not circulate sqz 50 sx cmt. Set surface plug.
- 9. RDMO cementers. Cut surface and production casing off below GL. Weld on top plate as per NMOCD regulations. Back fill hole.
- 10. RDMO.



Current WBD

WELL DIAGRAM

Unit Letter - G



7/1962: Perforated: 4967'-69', 4973'-77', 4978'-80', 5046'-50'. Treated w/500 gals of spearhead acid, 37,800 gals of lease oil, 70,600# of sand and 1,000# adomite using 20 ball sealers. (22.7 BPM). Swabbed 60 bo & 15 bw in 24 hrs.

12/1969: Convert to Water Injector.

2/2007: (Repaired casing leak). Perforated: 4956'-5052' (70 holes). Acidized well w/1500 gals 15% NEFE. Began to inject water.



PBTD: 5100'