Form 3160-5 .. (August 2007)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

	100000 AC	n
OCD	HOBBS OC	-

FORM APPROVED OMB No 1004-0137

Expires July 31, 2010 Lease Serial No

JUN 1-8 2004 Indian, Allottee or Tribe Name SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals. 7 If Unit of CA/Agreement, Name and/or No. SUBMIT IN TRIPLICATE - Other instructions on page 2. Cooper Jal Unit- NM 70926X 1 Type of Well 8 Well Name and No Cooper Jal Unit #133 Oil Well Other Injector Gas Well 9 API Well No 30-025-11161 2 Name of Operator Resaca Operating Company 3a Address 3b Phone No (include area code) 10 Field and Pool or Exploratory Area Jalmat; T-Y-7R/ Langlie Mattix; 7R-Q-G 1331 Lamar Street, Suite 1450 Houston, TX 77010 (432) 580-8500 4. Location of Well (Footage, Sec., T., R, M, or Survey Description) 11 Country or Parish, State Lea County, NM 1980' FSL & 1916' FWL, Sec 19, T-24S, R-37E, Unit Letter K 12 CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA TYPE OF SUBMISSION TYPE OF ACTION Production (Start/Resume) ☐ Acidize ___ Deepen Water Shut-Off Notice of Intent Alter Casing Fracture Treat Reclamation Well Integrity Other Test casing & run Casing Repair New Construction Recomplete ✓ Subsequent Report MIT Change Plans Plug and Abandon Temporarily Abandon Final Abandonment Notice Convert to Injection Plug Back Water Disposal 13 Describe Proposed or Completed Operation Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection)

5/17- MIRU PU Rig stuck, broke down

5/22- Speared broken tbg. NDWH, released packer. NU BOP, POOH w/ tbg. & pkr. RIH w/ 4 3/4" Bit & tubing, tagged @ 3126'. POOH w/ tubing & Bit. RIH w/ 5 1/2" AD-1 Packer. RU tbg. tester & hydro-tested tubing in hole, no leaks.

5/23- Racked work string, MI reverse unit

5/24- Set 5 1/2" Arrow Set Packer @ 2930'. Tried to run MIT, lost pressure. Pulled 1 jt., set packer, Tried to run MIT, lost pressure. POOH w/ tbg. & pkr.

RIH w/ 4 3/4" Bit, drill collars & tubing, tagged @ 3110'. PU Swivel & cleaned to 3165', circulated clean.

5/25- RIH w/ tbg., tagged @ 3165'. PU Swivel & cleaned to 3670', circulated clean. LD Swivel.

5/29- RIH w/ tbg., tagged @ 3610'. PU Swivel, croke circulation bridge at 3610', cleaned to 3670'. POOH w/ tbg. & D.C.'s. RIH w/ plug & pkr. Tested tubing in hole, good. Set Plug @ 2940', tested plug, okay. POOH to 1800', tested casing, test good.

5/30- POOH, LD work string, pkr., & plug. PU 5 1/2" AD-1 Pkr, Tested 2 3/8" IPC tbg., test good. Tried to run MIT Twice, wouldn't hole pressure.

5/31- RIH w/ 5 1/2" Arrow Set Packer & 2 3/8" IPC tubing, set Pkr @ 2930'. Tried to run MIT twice, lost pressure. RIH w/ 5 1/2" Plug & pkr. PU w/ 2 7/8" work string & set plug @ 2948'; tested plug, test good. POOH to 2000', tested casing to 600 psi, test good. Released packer & tested all casing f/ surface to 2948' to 600 psi, test good.

6/1- Tried to run MIT three times, unsuccessful.

6/2- Standby

6/3- RDMO PU, cleaned location,

* Filing Form 3160-5 Notice of Intent to run & cement liner.

fictitious or fraudulent statements or representations as to any matter within its jurisdiction

accept for 0.6/13/2012	recos d
------------------------	---------

14 I hereby certify that the foregoing is true and correct Name (Printed/Typed) Melanie Reyes	Title Engineer Assistant	
Signature MM	Date 06/06/2012	
THIS SPACE FOR FEDE	RAL OR STATE OFFICE	USE
Approved by		
	Title	Date
Conditions of approval, if any, are attached Approval of this notice does not warrant or c	and G	

(Instructions on page 2)

Submit 1 Copy To Appropriate District	State of	New Mexico			Form C	
Office <u>District I</u> – (575) 393-6161	Energy, Minerals	and Natural Reso	ources		Revised August 1	, 2011
1625 N. French Dr , Hobbs, NM 88240			,	VELL API NO.		1
' <u>District II</u> – (575) 748-1283 811 S. First St., Artesia, NM 88210	OIL CONSERVATION DIVISION		H 11X1	0-025-11161		
<u>District III</u> – (505) 334-6178	1220 South St. Francis Dr.		3	. Indicate Type of L STATE	FEE 🗌	FED
1000 Rio Brazos Rd., Aztec, NM 87410 <u>District IV</u> – (505) 476-3460	Santa Fe	Santa Fe, NM 87505		State Oil & Gas Le		TED
1220 S St Francis Dr , Santa Fe, NM				306444		
87505	TIOPS AND DEPONTS OF	NAMELLO		I NI I I	is A annument Nie	
(DO NOT USE THIS FORM FOR PROI	TICES AND REPORTS OF		t t	. Lease Name or Un Cooper Jal Unit	it Agreement Na	ime
DIFFERENT RESERVOIR. USE "APP			ion C	ooper Jai Onn		
PROPOSALS)	6 W 11 M 64 Y	• .	8	. Well Number 133		
1. Type of Well: Oil Well	Gas Well Other In	jector				
2. Name of Operator	aca Operating Company		I .	. OGRID Number 63848		
3. Address of Operator	aca Operating Company			0. Pool name or Wil	dcat	
1331 Lamar Street, Suite 1450	Houston, TX 77010			almat; T-Y-7R/ Lang		-G
4. Well Location					<u></u>	
Unit Letter K:	1980 feet from the	South line	and <u>1916</u>	feet from the	West lin	ne
Section 19	Township	24S Range	37E	NMPM Les	a County	ALESSANCE P
	11. Elevation (Show wh	neiner DR, RKB, R. 6' GL	I, GK, etc.)			
	320	O OL			(1) · X · S · X · X · X · X · X · X · X · X	
12 Charle	. A	J: 4 - NT- 4 4	CNT-4: D.			
12. Check	Appropriate Box to In	dicate Nature of	Notice, Re	port or Other Da	ia	
NOTICE OF I	NTENTION TO:		SUBSE	QUENT REPO	RT OF:	
PERFORM REMEDIAL WORK		REME	DIAL WORK		TERING CASING	зΠ
TEMPORARILY ABANDON	-		ENCE DRILLI		ND A	
PULL OR ALTER CASING [G/CEMENT JO			
]					
DOMINIOLE COMMININGLE L						
DOWNHOLE COMMININGLE	_					
OTHER:		☐ OTHER		asing & Run MIT		\boxtimes
OTHER: 13. Describe proposed or con	apleted operations. (Clearly	state all pertinent	details, and gi	ve pertinent dates, in		⊠ ed date
OTHER: 13. Describe proposed or con of starting any proposed or con or	npleted operations. (Clearly work). SEE RULE 19.15.7.	state all pertinent	details, and gi	ve pertinent dates, in		⊠ ed date
OTHER: 13. Describe proposed or con of starting any proposed or proposed completion or r	npleted operations. (Clearly work). SEE RULE 19.15.7. ecompletion.	y state all pertinent 14 NMAC. For M	details, and gi ultiple Compl	ve pertinent dates, in etions: Attach wellt	ore diagram of	
OTHER: 13. Describe proposed or con of starting any proposed proposed completion or r 1) MIRU PU. Rig stuck, bro.	npleted operations. (Clearly work). SEE RULE 19.15.7. ecompletion. ke down; Speared broken the	y state all pertinent 14 NMAC. For M og. NDWH, release	details, and gi ultiple Compl d packer. NU	ve pertinent dates, in etions: Attach wellb BOP, POOH w/ tbg	oore diagram of . & pkr. RIH w	/ 4 3/4"
OTHER: 13. Describe proposed or con of starting any proposed proposed completion or r 1) MIRU PU. Rig stuck, bro. Bit & tubing, tagged @ 3	npleted operations. (Clearly work). SEE RULE 19.15.7. ecompletion.	y state all pertinent 14 NMAC. For M og. NDWH, release	details, and gi ultiple Compl d packer. NU	ve pertinent dates, in etions: Attach wellb BOP, POOH w/ tbg	oore diagram of . & pkr. RIH w	/ 4 3/4"
OTHER: 13. Describe proposed or con of starting any proposed or proposed completion or r 1) MIRU PU. Rig stuck, bro. Bit & tubing, tagged @ 3 hole, no leaks. 5/17-5/22	npleted operations. (Clearly work). SEE RULE 19.15.7. ecompletion. ke down; Speared broken to 126'. POOH w/ tubing & B	y state all pertinent 14 NMAC. For M og. NDWH, release it. RIH w/ 5 1/2" A	details, and gi ultiple Compl d packer. NU AD-1 Packer.	ve pertinent dates, it etions: Attach wellb BOP, POOH w/ tbg RU tbg. tester & hy	oore diagram of . & pkr. RIH warder tubing	/ 4 3/4" g in
OTHER: 13. Describe proposed or composed of starting any proposed oproposed completion or r 1) MIRU PU. Rig stuck, brown Bit & tubing, tagged @ 3 hole, no leaks. 5/17-5/22 2) Racked work string, MI re	npleted operations. (Clearly work). SEE RULE 19.15.7. ecompletion. ke down; Speared broken the 126'. POOH w/ tubing & B werse unit. Set 5 1/2" Arrow	y state all pertinent 14 NMAC. For M og. NDWH, release hit. RIH w/ 5 1/2" / y Set Packer @ 293	details, and gi ultiple Compl d packer. NU AD-1 Packer. 0'. Tried to ru	ve pertinent dates, it etions: Attach wellb BOP, POOH w/ tbg RU tbg. tester & hy in MIT twice, lost pr	oore diagram of . & pkr. RIH w dro-tested tubing essure. POOH v	/ 4 3/4" g in w/ tbg.
OTHER: 13. Describe proposed or comof starting any proposed or proposed completion or r 1) MIRU PU. Rig stuck, brown Bit & tubing, tagged @ 3 hole, no leaks. 5/17-5/22 2) Racked work string, MI re & pkr. RIH w/ 4 3/4" Bit	npleted operations. (Clearly work). SEE RULE 19.15.7. ecompletion. ke down; Speared broken to 126'. POOH w/ tubing & B werse unit. Set 5 1/2" Arrow, drill collars & tubing, tagg	y state all pertinent 14 NMAC. For M og. NDWH, release bit. RIH w/ 5 1/2" A Set Packer @ 293 ged @ 3110'. PU S	details, and gi ultiple Compl d packer. NU AD-1 Packer. 0'. Tried to ru wivel & clean	ve pertinent dates, it etions: Attach wellt BOP, POOH w/ tbg RU tbg. tester & hy an MIT twice, lost pred to 3165', circulate	oore diagram of . & pkr. RIH wadro-tested tubing essure. POOH ved clean. 5/23-5/	/ 4 3/4" g in w/ tbg. /24
OTHER: 13. Describe proposed or comof starting any proposed or proposed completion or r 1) MIRU PU. Rig stuck, brown Bit & tubing, tagged @ 3 hole, no leaks. 5/17-5/22 2) Racked work string, MI re & pkr. RIH w/ 4 3/4" Bit 3) RIH w/ tbg., tagged @ 316	npleted operations. (Clearly work). SEE RULE 19.15.7. ecompletion. ke down; Speared broken to 126'. POOH w/ tubing & B werse unit. Set 5 1/2" Arrow, drill collars & tubing, tagg 55'. PU Swivel & cleaned to	y state all pertinent .14 NMAC. For M og. NDWH, release bit. RIH w/ 5 1/2" A y Set Packer @ 293 ged @ 3110'. PU S o 3670', circulated of	details, and gi ultiple Compl d packer. NU AD-1 Packer. 0'. Tried to ru wivel & clean clean. LD Sw	ve pertinent dates, it etions: Attach wellt BOP, POOH w/ tbg RU tbg. tester & hy in MIT twice, lost pr ed to 3165', circulate ivel.RIH w/ tbg., tag	oore diagram of . & pkr. RIH wardro-tested tubing essure. POOH ved clean. 5/23-5/ ged @ 3610'. P	/ 4 3/4" g in w/ tbg. /24 U
OTHER: 13. Describe proposed or con of starting any proposed or proposed completion or r 1) MIRU PU. Rig stuck, bro. Bit & tubing, tagged @ 3 hole, no leaks. 5/17-5/22 2) Racked work string, MI re & pkr. RIH w/ 4 3/4" Bit 3) RIH w/ tbg., tagged @ 316 Swivel, croke circulation	npleted operations. (Clearly work). SEE RULE 19.15.7 ecompletion. ke down; Speared broken the 126'. POOH w/ tubing & Bourse unit. Set 5 1/2" Arrow, drill collars & tubing, tagg 55'. PU Swivel & cleaned to bridge at 3610', cleaned to 5	y state all pertinent .14 NMAC. For M og. NDWH, release bit. RIH w/ 5 1/2" A y Set Packer @ 293 ged @ 3110'. PU S o 3670', circulated of 3670'. POOH w/ th	details, and gi ultiple Compl d packer. NU AD-1 Packer. 0'. Tried to ru wivel & clean clean. LD Sw og. & D.C.'s.	ve pertinent dates, in etions: Attach wellt BOP, POOH w/ tbg RU tbg. tester & hy in MIT twice, lost pred to 3165', circulate ivel.RIH w/ tbg., tag RIH w/ plug & pkr.	oore diagram of . & pkr. RIH wardro-tested tubing essure. POOH ved clean. 5/23-5/ ged @ 3610'. P	/ 4 3/4" g in w/ tbg. /24 U
OTHER: 13. Describe proposed or con of starting any proposed or proposed completion or r 1) MIRU PU. Rig stuck, brown Bit & tubing, tagged @ 3 hole, no leaks. 5/17-5/22 2) Racked work string, MI re & pkr. RIH w/ 4 3/4" Bit 3) RIH w/ tbg., tagged @ 316 Swivel, croke circulation good. Set Plug @ 2940', 4) POOH, LD work string, pk	npleted operations. (Clearly work). SEE RULE 19.15.7. ecompletion. ke down; Speared broken the 126'. POOH w/ tubing & Boverse unit. Set 5 1/2" Arrow, drill collars & tubing, tagg (5'). PU Swivel & cleaned to bridge at 3610', cleaned to stested plug, okay. POOH to tr., & plug. PU 5 1/2" AD-	y state all pertinent 14 NMAC. For M og. NDWH, release bit. RIH w/ 5 1/2" A y Set Packer @ 293 ged @ 3110'. PU S to 3670', circulated of 3670'. POOH w/ the to 1800', tested casin 1 Pkr, Tested 2 3/8'	details, and gi ultiple Compl d packer. NU AD-1 Packer. 0'. Tried to re wivel & clean clean. LD Sw og. & D.C.'s. ng, test good. ' IPC tbg., tes	ve pertinent dates, in etions: Attach wellt BOP, POOH w/ tbg RU tbg. tester & hy in MIT twice, lost pred to 3165', circulate ivel.RIH w/ tbg., tag RIH w/ plug & pkr. 5/25-5/29 t good. Tried to run	oore diagram of . & pkr. RIH wanter dro-tested tubing essure. POOH ved clean. 5/23-5/ ged @ 3610'. P Tested tubing in MIT Twice, won	/ 4 3/4" g in w/ tbg. // 24 U n hole, uldn't
OTHER: 13. Describe proposed or con of starting any proposed or proposed completion or r 1) MIRU PU. Rig stuck, brown Bit & tubing, tagged @ 3 hole, no leaks. 5/17-5/22 2) Racked work string, MI re & pkr. RIH w/ 4 3/4" Bit Swivel, croke circulation good. Set Plug @ 2940', 4) POOH, LD work string, pk hole pressure. RIH w/ 5 1	npleted operations. (Clearly work). SEE RULE 19.15.7. ecompletion. ke down; Speared broken to 126'. POOH w/ tubing & Boverse unit. Set 5 1/2" Arrow, drill collars & tubing, tagg 55'. PU Swivel & cleaned to 55'. PU Swivel & cle	y state all pertinent 14 NMAC. For M og. NDWH, released bit. RIH w/ 5 1/2" A y Set Packer @ 293 ged @ 3110'. PU S o 3670', circulated of 3670'. POOH w/ th o 1800', tested casin 1 Pkr, Tested 2 3/8' 1/8" IPC tubing, set	details, and giultiple Compled packer. NUAD-1 Packer. O'. Tried to ruwivel & clean clean. LD Swog. & D.C.'s. ng, test good. ' IPC tbg., test Pkr @ 2930'.	ve pertinent dates, in etions: Attach wellt BOP, POOH w/ tbg RU tbg. tester & hy in MIT twice, lost pred to 3165', circulate ivel.RIH w/ tbg., tag RIH w/ plug & pkr. 5/25-5/29 t good. Tried to run MIT to	ore diagram of . & pkr. RIH wants dro-tested tubing essure. POOH ved clean. 5/23-5/ ged @ 3610'. P Tested tubing in MIT Twice, wor vice, lost pressur	/ 4 3/4" g in w/ tbg. /24 U n hole, uldn't
OTHER: 13. Describe proposed or con of starting any proposed or proposed completion or r 1) MIRU PU. Rig stuck, bro. Bit & tubing, tagged @ 3 hole, no leaks. 5/17-5/22 2) Racked work string, MI re & pkr. RIH w/ 4 3/4" Bit Swivel, tagged @ 316 Swivel, croke circulation good. Set Plug @ 2940', 4) POOH, LD work string, pk hole pressure. RIH w/ 5 1 RIH w/ 5 1/2" Plug & pkr	npleted operations. (Clearly work). SEE RULE 19.15.7. ecompletion. ke down; Speared broken to 126'. POOH w/ tubing & Bourse unit. Set 5 1/2" Arrow, drill collars & tubing, tagg is. PU Swivel & cleaned to bridge at 3610', cleaned to tested plug, okay. POOH terr., & plug. PU 5 1/2" AD-/2" Arrow Set Packer & 2 3 puly. PU w/ 2 7/8" work string	y state all pertinent .14 NMAC. For M14 NMAC. For M14 NMAC. For M14 NMAC. For M15 NMAC. For M16 NMAC. For M17 NMAC. For M17 NMAC17 NMAC17 NMAC18 N	details, and giultiple Compled packer. NUAD-1 Packer. O'. Tried to rusivel & clean clean. LD Swog. & D.C.'s. ng, test good. ' IPC tbg., test Pkr @ 2930'. S'; tested plug,	ve pertinent dates, in etions: Attach wellt BOP, POOH w/ tbg RU tbg. tester & hy in MIT twice, lost pred to 3165', circulate ivel.RIH w/ tbg., tag RIH w/ plug & pkr. 5/25-5/29 t good. Tried to run MIT to test good. POOH to	ore diagram of . & pkr. RIH wanter dro-tested tubing essure. POOH ved clean. 5/23-5/ ged @ 3610'. P Tested tubing in MIT Twice, wor vice, lost pressur	/ 4 3/4" g in w/ tbg. /24 U n hole, uldn't
OTHER: 13. Describe proposed or comof starting any proposed oproposed completion or r 1) MIRU PU. Rig stuck, brown Bit & tubing, tagged @ 3 hole, no leaks. 5/17-5/22 2) Racked work string, MI rewighter & pkr. RIH w/ 4 3/4" Bit 3) RIH w/ tbg., tagged @ 316 Swivel, croke circulation good. Set Plug @ 2940', 4) POOH, LD work string, pk hole pressure. RIH w/ 5 1 RIH w/ 5 1/2" Plug & pkr 600 psi, test good. Release	npleted operations. (Clearly work). SEE RULE 19.15.7. ecompletion. ke down; Speared broken the 126'. POOH w/ tubing & Bourse unit. Set 5 1/2" Arrow, drill collars & tubing, tagg 15'. PU Swivel & cleaned to bridge at 3610', cleaned to stested plug, okay. POOH text., & plug. PU 5 1/2" AD-1/2" Arrow Set Packer & 2 3 2. PU w/ 2 7/8" work string sed packer & tested all casing the complete the string sed packer & tested all casing the complete the set of the set o	y state all pertinent .14 NMAC. For M14 NMAC. For M14 NMAC. For M14 NMAC. For M15 NMAC. For M16 NMAC. For M17 NMAC. For M17 NMAC17 NMAC17 NMAC18 N	details, and giultiple Compled packer. NUAD-1 Packer. O'. Tried to rusivel & clean clean. LD Swog. & D.C.'s. ng, test good. ' IPC tbg., test Pkr @ 2930'. S'; tested plug,	ve pertinent dates, in etions: Attach wellt BOP, POOH w/ tbg RU tbg. tester & hy in MIT twice, lost pred to 3165', circulate ivel.RIH w/ tbg., tag RIH w/ plug & pkr. 5/25-5/29 t good. Tried to run MIT to test good. POOH to	ore diagram of . & pkr. RIH wanter dro-tested tubing essure. POOH ved clean. 5/23-5/ ged @ 3610'. P Tested tubing in MIT Twice, wor vice, lost pressur	/ 4 3/4" g in w/ tbg. /24 U n hole, uldn't
OTHER: 13. Describe proposed or comof starting any proposed oproposed completion or r 1) MIRU PU. Rig stuck, brown Bit & tubing, tagged @ 3 hole, no leaks. 5/17-5/22 2) Racked work string, MI rewell & pkr. RIH w/ 4 3/4" Bit 3) RIH w/ tbg., tagged @ 316 Swivel, croke circulation good. Set Plug @ 2940', 4) POOH, LD work string, pkhole pressure. RIH w/ 5 1 RIH w/ 5 1/2" Plug & pkr 600 psi, test good. Release 5) Tried to run MIT three times.	ppleted operations. (Clearly work). SEE RULE 19.15.7. ecompletion. ke down; Speared broken the 126'. POOH w/ tubing & Boverse unit. Set 5 1/2" Arrow, drill collars & tubing, tagg 15'. PU Swivel & cleaned to bridge at 3610', cleaned to stested plug, okay. POOH to tr., & plug. PU 5 1/2" AD-1/2" Arrow Set Packer & 2 3 2. PU w/ 2 7/8" work string sed packer & tested all casines, unsuccessful.6/1	y state all pertinent .14 NMAC. For M14 NMAC. For M14 NMAC. For M14 NMAC. For M15 NMAC. For M16 NMAC. For M17 NMAC. For M17 NMAC17 NMAC17 NMAC18 N	details, and giultiple Compled packer. NUAD-1 Packer. O'. Tried to rusivel & clean clean. LD Swog. & D.C.'s. ng, test good. ' IPC tbg., test Pkr @ 2930'. S'; tested plug,	ve pertinent dates, in etions: Attach wellt BOP, POOH w/ tbg RU tbg. tester & hy in MIT twice, lost pred to 3165', circulate ivel.RIH w/ tbg., tag RIH w/ plug & pkr. 5/25-5/29 t good. Tried to run MIT to test good. POOH to	ore diagram of . & pkr. RIH wanter dro-tested tubing essure. POOH ved clean. 5/23-5/ ged @ 3610'. P Tested tubing in MIT Twice, wor vice, lost pressur	/ 4 3/4" g in w/ tbg. /24 U n hole, uldn't
OTHER: 13. Describe proposed or con of starting any proposed or proposed completion or r 1) MIRU PU. Rig stuck, bro. Bit & tubing, tagged @ 3 hole, no leaks. 5/17-5/22 2) Racked work string, MI re & pkr. RIH w/ 4 3/4" Bit 3) RIH w/ tbg., tagged @ 316 Swivel, croke circulation good. Set Plug @ 2940', 4) POOH, LD work string, pk hole pressure. RIH w/ 5 1 RIH w/ 5 1/2" Plug & pkr 600 psi, test good. Release 5) Tried to run MIT three tim 6) RDMO PU, cleaned location.	ppleted operations. (Clearly work). SEE RULE 19.15.7. ecompletion. ke down; Speared broken the 126'. POOH w/ tubing & Boverse unit. Set 5 1/2" Arrow, drill collars & tubing, tagg 55'. PU Swivel & cleaned to bridge at 3610', cleaned to bridge at 3610', cleaned to tested plug, okay. POOH to tr., & plug. PU 5 1/2" AD-7/2" Arrow Set Packer & 2 37. PU w/ 2 7/8" work string sed packer & tested all casines, unsuccessful.6/1 on. 6/3	y state all pertinent 14 NMAC. For M 14 NMAC. For M 15 NDWH, release 15 NDWH, release 16 NDWH, release 16 NDWH, release 17 NDWH, release 17 NDWH, release 18 NDWH, release 18 NDWH, rested 2 36 NDWH, rested 2 3/8 NDWH, release 10 NDWH, rested 2 3/8 NDWH, rested	details, and giultiple Compled packer. NUAD-1 Packer. O'. Tried to rusivel & clean clean. LD Swog. & D.C.'s. ng, test good. ' IPC tbg., test Pkr @ 2930'. S'; tested plug,	ve pertinent dates, in etions: Attach wellt BOP, POOH w/ tbg RU tbg. tester & hy in MIT twice, lost pred to 3165', circulate ivel.RIH w/ tbg., tag RIH w/ plug & pkr. 5/25-5/29 t good. Tried to run MIT to test good. POOH to	ore diagram of . & pkr. RIH wanter dro-tested tubing essure. POOH ved clean. 5/23-5/ ged @ 3610'. P Tested tubing in MIT Twice, wor vice, lost pressur	/ 4 3/4" g in w/ tbg. /24 U n hole, uldn't
OTHER: 13. Describe proposed or comof starting any proposed oproposed completion or r 1) MIRU PU. Rig stuck, brown Bit & tubing, tagged @ 3 hole, no leaks. 5/17-5/22 2) Racked work string, MI rewing & pkr. RIH w/ 4 3/4" Bit 3) RIH w/ tbg., tagged @ 316 Swivel, croke circulation good. Set Plug @ 2940', 4) POOH, LD work string, pkhole pressure. RIH w/ 5 1 RIH w/ 5 1/2" Plug & pkr 600 psi, test good. Release 5) Tried to run MIT three tim 6) RDMO PU, cleaned location.	npleted operations. (Clearly work). SEE RULE 19.15.7. ecompletion. ke down; Speared broken the 126'. POOH w/ tubing & Boverse unit. Set 5 1/2" Arrow, drill collars & tubing, tagg 15'. PU Swivel & cleaned to bridge at 3610', cleaned to stested plug, okay. POOH tear., & plug. PU 5 1/2" AD-1/2" Arrow Set Packer & 2 3 2. PU w/ 2 7/8" work string sed packer & tested all casines, unsuccessful.6/1 on. 6/3 of Intent to run & cement lines.	y state all pertinent 14 NMAC. For M 14 NMAC. For M 15 NDWH, release 15 NDWH, release 16 NDWH, release 16 NDWH, release 17 NDWH, release 17 NDWH, release 18 NDWH, release 18 NDWH, rested 2 36 NDWH, rested 2 3/8 NDWH, release 10 NDWH, rested 2 3/8 NDWH, rested	details, and giultiple Compled packer. NUAD-1 Packer. O'. Tried to rewivel & clean clean. LD Swog. & D.C.'s. ng, test good. ' IPC tbg., test Pkr @ 2930'. '; tested plug, 8' to 600 psi, 1	ve pertinent dates, in etions: Attach wells BOP, POOH w/ tbg RU tbg. tester & hy in MIT twice, lost pred to 3165', circulate ivel.RIH w/ tbg., tag RIH w/ plug & pkr. 5/25-5/29 t good. Tried to run Tried to run MIT to test good. 5/30-5/31	ore diagram of . & pkr. RIH wanter dro-tested tubing essure. POOH ved clean. 5/23-5/ ged @ 3610'. P Tested tubing in MIT Twice, wor vice, lost pressur	/ 4 3/4" g in w/ tbg. /24 U n hole, uldn't
OTHER: 13. Describe proposed or comof starting any proposed oproposed completion or r 1) MIRU PU. Rig stuck, brown Bit & tubing, tagged @ 3 hole, no leaks. 5/17-5/22 2) Racked work string, MI rewell & pkr. RIH w/ 4 3/4" Bit 3) RIH w/ tbg., tagged @ 316 Swivel, croke circulation good. Set Plug @ 2940', 4) POOH, LD work string, pk hole pressure. RIH w/ 5 1 RIH w/ 5 1/2" Plug & pkr 600 psi, test good. Release 5) Tried to run MIT three tim 6) RDMO PU, cleaned location. * Filing Form 3160-5 Notice of the proposed of the p	ppleted operations. (Clearly work). SEE RULE 19.15.7. ecompletion. ke down; Speared broken to 126'. POOH w/ tubing & B verse unit. Set 5 1/2" Arrow, drill collars & tubing, tagg 55'. PU Swivel & cleaned to bridge at 3610', cleaned to tested plug, okay. POOH to tr., & plug. PU 5 1/2" AD-/2" Arrow Set Packer & 2 3 PU w/ 2 7/8" work string sed packer & tested all casines, unsuccessful.6/1 on. 6/3 of Intent to run & cement lines.	y state all pertinent 14 NMAC. For M 14 NMAC. For M 15 NDWH, release 16 NDWH, release 16 NDWH, release 17 Set Packer @ 293 Sed @ 3110'. PU Set 3670', circulated 6 S670'. POOH w/tb 1800', tested casin 1 Pkr, Tested 2 3/8' 18'' IPC tubing, set 2 Set plug @ 2948 Set plug @	details, and giultiple Compled packer. NUAD-1 Packer. O'. Tried to rewivel & clean clean. LD Swog. & D.C.'s. ng, test good. ' IPC tbg., test Pkr @ 2930'. '; tested plug, 8' to 600 psi, 1	ve pertinent dates, in etions: Attach wellt BOP, POOH w/ tbg RU tbg. tester & hy in MIT twice, lost pred to 3165', circulate ivel.RIH w/ tbg., tag RIH w/ plug & pkr. 5/25-5/29 t good. Tried to run MIT to test good. POOH to	ore diagram of . & pkr. RIH wanter dro-tested tubing essure. POOH ved clean. 5/23-5/ ged @ 3610'. P Tested tubing in MIT Twice, wor vice, lost pressur	/ 4 3/4" g in w/ tbg. /24 U n hole, uldn't
OTHER: 13. Describe proposed or comof starting any proposed oproposed completion or r 1) MIRU PU. Rig stuck, brown Bit & tubing, tagged @ 3 hole, no leaks. 5/17-5/22 2) Racked work string, MI rewing & pkr. RIH w/ 4 3/4" Bit 3) RIH w/ tbg., tagged @ 316 Swivel, croke circulation good. Set Plug @ 2940', 4) POOH, LD work string, pkhole pressure. RIH w/ 5 1 RIH w/ 5 1/2" Plug & pkr 600 psi, test good. Release 5) Tried to run MIT three tim 6) RDMO PU, cleaned location.	ppleted operations. (Clearly work). SEE RULE 19.15.7. ecompletion. ke down; Speared broken to 126'. POOH w/ tubing & B verse unit. Set 5 1/2" Arrow, drill collars & tubing, tagg 55'. PU Swivel & cleaned to bridge at 3610', cleaned to tested plug, okay. POOH to tr., & plug. PU 5 1/2" AD-/2" Arrow Set Packer & 2 3 PU w/ 2 7/8" work string sed packer & tested all casines, unsuccessful.6/1 on. 6/3 of Intent to run & cement lines.	y state all pertinent 14 NMAC. For M 14 NMAC. For M 15 NDWH, release 15 NDWH, release 16 NDWH, release 16 NDWH, release 17 NDWH, release 17 NDWH, release 18 NDWH, release 18 NDWH, rested 2 36 NDWH, rested 2 3/8 NDWH, release 10 NDWH, rested 2 3/8 NDWH, rested	details, and giultiple Compled packer. NUAD-1 Packer. O'. Tried to rewivel & clean clean. LD Swog. & D.C.'s. ng, test good. ' IPC tbg., test Pkr @ 2930'. '; tested plug, 8' to 600 psi, 1	ve pertinent dates, in etions: Attach wells BOP, POOH w/ tbg RU tbg. tester & hy in MIT twice, lost pred to 3165', circulate ivel.RIH w/ tbg., tag RIH w/ plug & pkr. 5/25-5/29 t good. Tried to run Tried to run MIT to test good. 5/30-5/31	ore diagram of . & pkr. RIH wanter dro-tested tubing essure. POOH ved clean. 5/23-5/ ged @ 3610'. P Tested tubing in MIT Twice, wor vice, lost pressur	/ 4 3/4" g in w/ tbg. /24 U n hole, uldn't
OTHER: 13. Describe proposed or comof starting any proposed oproposed completion or r 1) MIRU PU. Rig stuck, brown Bit & tubing, tagged @ 3 hole, no leaks. 5/17-5/22 2) Racked work string, MI rewell & pkr. RIH w/ 4 3/4" Bit 3) RIH w/ tbg., tagged @ 316 Swivel, croke circulation good. Set Plug @ 2940', 4) POOH, LD work string, pk hole pressure. RIH w/ 5 1 RIH w/ 5 1/2" Plug & pkr 600 psi, test good. Release 5) Tried to run MIT three tim 6) RDMO PU, cleaned location. * Filing Form 3160-5 Notice of the proposed of the p	ppleted operations. (Clearly work). SEE RULE 19.15.7. ecompletion. ke down; Speared broken to 126'. POOH w/ tubing & B verse unit. Set 5 1/2" Arrow, drill collars & tubing, tagg 55'. PU Swivel & cleaned to bridge at 3610', cleaned to tested plug, okay. POOH to tr., & plug. PU 5 1/2" AD-/2" Arrow Set Packer & 2 3 PU w/ 2 7/8" work string sed packer & tested all casines, unsuccessful.6/1 on. 6/3 of Intent to run & cement lines.	y state all pertinent 14 NMAC. For M 14 NMAC. For M 15 NDWH, release 16 NDWH, release 16 NDWH, release 17 Set Packer @ 293 Sed @ 3110'. PU Set 3670', circulated 6 S670'. POOH w/tb 1800', tested casin 1 Pkr, Tested 2 3/8' 18'' IPC tubing, set 2 Set plug @ 2948 Set plug @	details, and giultiple Compled packer. NUAD-1 Packer. O'. Tried to rewivel & clean clean. LD Swog. & D.C.'s. ng, test good. ' IPC tbg., test Pkr @ 2930'. '; tested plug, 8' to 600 psi, 1	ve pertinent dates, in etions: Attach wells BOP, POOH w/ tbg RU tbg. tester & hy in MIT twice, lost pred to 3165', circulate ivel.RIH w/ tbg., tag RIH w/ plug & pkr. 5/25-5/29 t good. Tried to run Tried to run MIT to test good. 5/30-5/31	ore diagram of . & pkr. RIH wanter dro-tested tubing essure. POOH ved clean. 5/23-5/ ged @ 3610'. P Tested tubing in MIT Twice, wor vice, lost pressur	/ 4 3/4" g in w/ tbg. /24 U n hole, uldn't
OTHER: 13. Describe proposed or comof starting any proposed oproposed completion or r 1) MIRU PU. Rig stuck, brown Bit & tubing, tagged @ 3 hole, no leaks. 5/17-5/22 2) Racked work string, MI rewind & pkr. RIH w/ 4 3/4" Bit 3) RIH w/ tbg., tagged @ 316 Swivel, croke circulation good. Set Plug @ 2940', 4) POOH, LD work string, pk hole pressure. RIH w/ 5 1 RIH w/ 5 1/2" Plug & pkr 600 psi, test good. Release 5) Tried to run MIT three tim 6) RDMO PU, cleaned location. * Filing Form 3160-5 Notice of RUS Date: RU 5/17/11	npleted operations. (Clearly work). SEE RULE 19.15.7. ecompletion. ke down; Speared broken the 126'. POOH w/ tubing & Boverse unit. Set 5 1/2" Arrow, drill collars & tubing, tagg 15'. PU Swivel & cleaned to bridge at 3610', cleaned to bridge at 3610', cleaned to stested plug, okay. POOH to tar., & plug. PU 5 1/2" AD-/2" Arrow Set Packer & 2 3'. PU w/ 2 7/8" work string sed packer & tested all casines, unsuccessful.6/1 on. 6/3 of Intent to run & cement ling.	y state all pertinent 14 NMAC. For Mog. NDWH, release bit. RIH w/ 5 1/2" A Set Packer @ 293 ged @ 3110'. PU S 20 3670', circulated 6 3670'. POOH w/ the 1800', tested casin 1 Pkr, Tested 2 3/8' k/8" IPC tubing, set & set plug @ 2948 geg f/ surface to 294 mer.	details, and giultiple Compled packer. NUAD-1 Packer. O'. Tried to ruwivel & clean clean. LD Swog. & D.C.'s. ng, test good. ' IPC tbg., tes Pkr @ 2930'. S'; tested plug, 8' to 600 psi, to 600	ve pertinent dates, in etions: Attach wellth BOP, POOH w/ tbg RU tbg. tester & hy in MIT twice, lost pred to 3165', circulate ivel.RIH w/ tbg., tag RIH w/ plug & pkr. 5/25-5/29 t good. Tried to run Tried to run MIT to test good. 5/30-5/31	ore diagram of . & pkr. RIH wanter dro-tested tubing essure. POOH ved clean. 5/23-5/ ged @ 3610'. P Tested tubing in MIT Twice, wor vice, lost pressur	/ 4 3/4" g in w/ tbg. /24 U n hole, uldn't
OTHER: 13. Describe proposed or comof starting any proposed oproposed completion or r 1) MIRU PU. Rig stuck, brown Bit & tubing, tagged @ 3 hole, no leaks. 5/17-5/22 2) Racked work string, MI rewell & pkr. RIH w/ 4 3/4" Bit 3) RIH w/ tbg., tagged @ 316 Swivel, croke circulation good. Set Plug @ 2940', 4) POOH, LD work string, pk hole pressure. RIH w/ 5 1 RIH w/ 5 1/2" Plug & pkr 600 psi, test good. Release 5) Tried to run MIT three tim 6) RDMO PU, cleaned location. * Filing Form 3160-5 Notice of the proposed of the p	npleted operations. (Clearly work). SEE RULE 19.15.7. ecompletion. ke down; Speared broken the 126'. POOH w/ tubing & Boverse unit. Set 5 1/2" Arrow, drill collars & tubing, tagg 15'. PU Swivel & cleaned to bridge at 3610', cleaned to bridge at 3610', cleaned to stested plug, okay. POOH to tar., & plug. PU 5 1/2" AD-/2" Arrow Set Packer & 2 3'. PU w/ 2 7/8" work string sed packer & tested all casines, unsuccessful.6/1 on. 6/3 of Intent to run & cement ling.	y state all pertinent 14 NMAC. For Mog. NDWH, release bit. RIH w/ 5 1/2" A Set Packer @ 293 ged @ 3110'. PU S 20 3670', circulated 6 3670'. POOH w/ the 1800', tested casin 1 Pkr, Tested 2 3/8' k/8" IPC tubing, set & set plug @ 2948 geg f/ surface to 294 mer.	details, and giultiple Compled packer. NUAD-1 Packer. O'. Tried to ruwivel & clean clean. LD Swog. & D.C.'s. ng, test good. ' IPC tbg., tes Pkr @ 2930'. S'; tested plug, 8' to 600 psi, to 600	ve pertinent dates, in etions: Attach wellth BOP, POOH w/ tbg RU tbg. tester & hy in MIT twice, lost pred to 3165', circulate ivel.RIH w/ tbg., tag RIH w/ plug & pkr. 5/25-5/29 t good. Tried to run Tried to run MIT to test good. 5/30-5/31	ore diagram of . & pkr. RIH wanter dro-tested tubing essure. POOH ved clean. 5/23-5/ ged @ 3610'. P Tested tubing in MIT Twice, wor vice, lost pressur	/ 4 3/4" g in w/ tbg. /24 U n hole, uldn't
OTHER: 13. Describe proposed or comof starting any proposed oproposed completion or r 1) MIRU PU. Rig stuck, brown Bit & tubing, tagged @ 3 hole, no leaks. 5/17-5/22 2) Racked work string, MI rewell & pkr. RIH w/ 4 3/4" Bit 3) RIH w/ tbg., tagged @ 316 Swivel, croke circulation good. Set Plug @ 2940', 4) POOH, LD work string, pk hole pressure. RIH w/ 5 1 RIH w/ 5 1/2" Plug & pkr 600 psi, test good. Released 5) Tried to run MIT three time 6) RDMO PU, cleaned location * Filing Form 3160-5 Notice of the string form 3160-5	npleted operations. (Clearly work). SEE RULE 19.15.7. ecompletion. ke down; Speared broken the 126'. POOH w/ tubing & Boverse unit. Set 5 1/2" Arrow, drill collars & tubing, tagg 15'. PU Swivel & cleaned to bridge at 3610', cleaned to bridge at 3610', cleaned to stested plug, okay. POOH to tar., & plug. PU 5 1/2" AD-/2" Arrow Set Packer & 2 3'. PU w/ 2 7/8" work string sed packer & tested all casines, unsuccessful.6/1 on. 6/3 of Intent to run & cement ling.	y state all pertinent 14 NMAC. For Mog. NDWH, release bit. RIH w/ 5 1/2" A Set Packer @ 293 ged @ 3110'. PU S 20 3670', circulated 6 3670'. POOH w/ the 1800', tested casin 1 Pkr, Tested 2 3/8' k/8" IPC tubing, set & set plug @ 2948 geg f/ surface to 294 mer.	details, and giultiple Compled packer. NUAD-1 Packer. O'. Tried to ruwivel & clean clean. LD Swog. & D.C.'s. ng, test good. ' IPC tbg., tes Pkr @ 2930'. S'; tested plug, 8' to 600 psi, to 600	ve pertinent dates, in etions: Attach wellth BOP, POOH w/ tbg RU tbg. tester & hy in MIT twice, lost pred to 3165', circulate ivel.RIH w/ tbg., tag RIH w/ plug & pkr. 5/25-5/29 t good. Tried to run Tried to run MIT to test good. 5/30-5/31	ore diagram of . & pkr. RIH wanter dro-tested tubing essure. POOH ved clean. 5/23-5/ ged @ 3610'. P Tested tubing in MIT Twice, wor vice, lost pressur	/ 4 3/4" g in w/ tbg. /24 U n hole, uldn't
OTHER: 13. Describe proposed or comof starting any proposed oproposed completion or r 1) MIRU PU. Rig stuck, brown Bit & tubing, tagged @ 3 hole, no leaks. 5/17-5/22 2) Racked work string, MI rewind & pkr. RIH w/ 4 3/4" Bit 3) RIH w/ tbg., tagged @ 316 Swivel, croke circulation good. Set Plug @ 2940', 4) POOH, LD work string, pk hole pressure. RIH w/ 5 1 RIH w/ 5 1/2" Plug & pkr 600 psi, test good. Release 5) Tried to run MIT three tim 6) RDMO PU, cleaned location. * Filing Form 3160-5 Notice of RUS Date: RU 5/17/11	npleted operations. (Clearly work). SEE RULE 19.15.7. ecompletion. ke down; Speared broken the 126'. POOH w/ tubing & Boverse unit. Set 5 1/2" Arrow, drill collars & tubing, tagg 15'. PU Swivel & cleaned to bridge at 3610', cleaned to bridge at 3610', cleaned to stested plug, okay. POOH to tar., & plug. PU 5 1/2" AD-/2" Arrow Set Packer & 2 3'. PU w/ 2 7/8" work string sed packer & tested all casines, unsuccessful.6/1 on. 6/3 of Intent to run & cement ling.	y state all pertinent 14 NMAC. For M og. NDWH, release bit. RIH w/ 5 1/2" A Set Packer @ 293 ged @ 3110'. PU S o 3670', circulated of 3670'. POOH w/ the 1800', tested casin 1 Pkr, Tested 2 3/8' s/8" IPC tubing, set & set plug @ 2948 gr f/ surface to 294 mer. Release Date:	details, and giultiple Compled packer. NUAD-1 Packer. O'. Tried to ruwivel & clean clean. LD Swog. & D.C.'s. ng, test good. ' IPC tbg., tes Pkr @ 2930'. S'; tested plug, 8' to 600 psi, to 600	ve pertinent dates, in etions: Attach wellth BOP, POOH w/ tbg RU tbg. tester & hy in MIT twice, lost pred to 3165', circulate ivel.RIH w/ tbg., tag RIH w/ plug & pkr. 5/25-5/29 t good. Tried to run Tried to run MIT to test good. 5/30-5/31	ore diagram of . & pkr. RIH wanter dro-tested tubing essure. POOH ved clean. 5/23-5/ ged @ 3610'. P Tested tubing in MIT Twice, wor vice, lost pressur	/ 4 3/4" g in w/ tbg. /24 U n hole, uldn't
OTHER: 13. Describe proposed or comof starting any proposed oproposed ompletion or r 1) MIRU PU. Rig stuck, brown Bit & tubing, tagged @ 3 hole, no leaks. 5/17-5/22 2) Racked work string, MI rewight & pkr. RIH w/ 4 3/4" Bit words, tagged @ 316 Swivel, croke circulation good. Set Plug @ 2940', which was a string, pk hole pressure. RIH w/ 5 1 RIH w/ 5 1/2" Plug & pkr 600 psi, test good. Released by Tried to run MIT three times of RDMO PU, cleaned location with the string form 3160-5 Notice of RU 5/17/15. Spud Date: RU 5/17/15	npleted operations. (Clearly work). SEE RULE 19.15.7. ecompletion. ke down; Speared broken the 126'. POOH w/ tubing & Boverse unit. Set 5 1/2" Arrow, drill collars & tubing, tagg 55'. PU Swivel & cleaned to bridge at 3610', cleaned to tested plug, okay. POOH test., & plug. PU 5 1/2" AD-/2" Arrow Set Packer & 2 3 are PU w/ 2 7/8" work string sed packer & tested all casines, unsuccessful.6/1 on. 6/3 of Intent to run & cement limited above is true and completed.	y state all pertinent 14 NMAC. For M ng. NDWH, release it. RIH w/ 5 1/2" A Set Packer @ 293 ged @ 3110'. PU S 0 3670', circulated of 3670'. POOH w/ th 0 1800', tested casin 1 Pkr, Tested 2 3/8' 6/8" IPC tubing, set & set plug @ 2948 ng f/ surface to 294 her. Release Date: Engineer	details, and giultiple Compl d packer. NU AD-1 Packer. 0'. Tried to ruwivel & clean clean. LD Sw og. & D.C.'s. ng, test good. ' IPC tbg., tes Pkr @ 2930'. ''; tested plug, 8' to 600 psi, to	ve pertinent dates, in etions: Attach wellth BOP, POOH w/ tbg RU tbg. tester & hy in MIT twice, lost pred to 3165', circulate ivel.RIH w/ tbg., tag RIH w/ plug & pkr. 5/25-5/29 t good. Tried to run MIT to test good. POOH to test good. 5/30-5/31 ad belief. DATE DATE	ore diagram of . & pkr. RIH want water to the water of the control of the contro	/ 4 3/4" g in w/ tbg. / 24 U n hole, uldn't re. asing to
OTHER: 13. Describe proposed or comof starting any proposed oproposed completion or r 1) MIRU PU. Rig stuck, brown Bit & tubing, tagged @ 3 hole, no leaks. 5/17-5/22 2) Racked work string, MI rewell & pkr. RIH w/ 4 3/4" Bit 3) RIH w/ tbg., tagged @ 316 Swivel, croke circulation good. Set Plug @ 2940', 4) POOH, LD work string, pk hole pressure. RIH w/ 5 1 RIH w/ 5 1/2" Plug & pkr 600 psi, test good. Released 5) Tried to run MIT three time 6) RDMO PU, cleaned location * Filing Form 3160-5 Notice of the string form 3160-5	npleted operations. (Clearly work). SEE RULE 19.15.7. ecompletion. ke down; Speared broken the 126'. POOH w/ tubing & Boverse unit. Set 5 1/2" Arrow, drill collars & tubing, tagg 55'. PU Swivel & cleaned to bridge at 3610', cleaned to tested plug, okay. POOH test., & plug. PU 5 1/2" AD-/2" Arrow Set Packer & 2 3 are PU w/ 2 7/8" work string sed packer & tested all casines, unsuccessful.6/1 on. 6/3 of Intent to run & cement limited above is true and completed.	y state all pertinent 14 NMAC. For M ng. NDWH, release it. RIH w/ 5 1/2" A Set Packer @ 293 ged @ 3110'. PU S 0 3670', circulated of 3670'. POOH w/ th 0 1800', tested casin 1 Pkr, Tested 2 3/8' 6/8" IPC tubing, set & set plug @ 2948 ng f/ surface to 294 her. Release Date: Engineer	details, and giultiple Compl d packer. NU AD-1 Packer. 0'. Tried to ruwivel & clean clean. LD Sw og. & D.C.'s. ng, test good. ' IPC tbg., tes Pkr @ 2930'. ''; tested plug, 8' to 600 psi, to	ve pertinent dates, in etions: Attach wellth BOP, POOH w/ tbg RU tbg. tester & hy in MIT twice, lost pred to 3165', circulate ivel.RIH w/ tbg., tag RIH w/ plug & pkr. 5/25-5/29 t good. Tried to run MIT to test good. POOH to test good. 5/30-5/31	ore diagram of . & pkr. RIH want water to the water of the control of the contro	/ 4 3/4" g in w/ tbg. / 24 U n hole, uldn't re. asing to

_TITLE____

DATE ____

APPROVED BY:
Conditions of Approval (if any):

