Submit 1 Copy To Appropriate District Office State of New Mexico	Form C-103
District I – (575) 393-6161 Energy, Minerals and Natural Resource	Revised August 1, 2011
1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
811 S. First St., Artesia, NM 88210 OIL CONSERVATION DIVISION	5 Indicate Type of Lease
District III – (505) 334-6178 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410	STATE FEE
District IV – (505) 476-3460 Santa Fe, NM 87505	6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505	
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A	
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	LOVINGTON PADDICK UNIT
1. Type of Well: Oil Well Gas Well Other	8. Well Number: 86
2. Name of Operator	9. OGRID Number
CHEVRON MIDCONTINENT, L.P. 3. Address of Operator	241333 10. Pool name or Wildcat
6301 DEAUVILLE BLVD, MIDLAND, TX 79706 RM.N3002	PADDOCK
4. Well Location	
Unit Letter G: 1595 feet from the NORTH line an	ad 2485 feet from the EAST line
	36E NMPM County Lea
11. Elevation (Show whether DR, RKB, RT, GR	
12. Check Appropriate Box to Indicate Nature of No	tice, Report or Other Data
NOTICE OF INTENTION TO:	SUBSEQUENT F
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒ REMEDIAL	WORK [
	E DRILLING OPNS. [INT TO PAR. X
PULL OR ALTER CASING	
DOWNHOLE COMMINGLE	P&A R
	1 0A IX
OTHER:	TGAN
OTHER: OTHER: OTHER: OTHER: OTHER:	
OTHER:	ils, and give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent detail	ils, and give pertinent dates, including estimated date
 Describe proposed or completed operations. (Clearly state all pertinent detail of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multip proposed completion or recompletion. 	ils, and give pertinent dates, including estimated date
13. Describe proposed or completed operations. (Clearly state all pertinent detail of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multip	ils, and give pertinent dates, including estimated date
 Describe proposed or completed operations. (Clearly state all pertinent detail of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multip proposed completion or recompletion. 	ils, and give pertinent dates, including estimated date
 Describe proposed or completed operations. (Clearly state all pertinent detair of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multip proposed completion or recompletion. Call and notify NMOCD 24 hrs. before operations begin. MIRU. NDWH. NU BOPE. 	ils, and give pertinent dates, including estimated date le Completions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearly state all pertinent detail of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multip proposed completion or recompletion. Call and notify NMOCD 24 hrs. before operations begin. MIRU. NDWH. NU BOPE. RIH and tag CIBP@5,970', circulate well w/9.5 ppg mud a 	ils, and give pertinent dates, including estimated date le Completions: Attach wellbore diagram of
 Describe proposed or completed operations. (Clearly state all pertinent detair of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multip proposed completion or recompletion. Call and notify NMOCD 24 hrs. before operations begin. MIRU. NDWH. NU BOPE. RIH and tag CIBP@5,970', circulate well w/9.5 ppg mud a test casing. 	ils, and give pertinent dates, including estimated date le Completions: Attach wellbore diagram of and spot 25sx of cmt. on top. Pressure
 Describe proposed or completed operations. (Clearly state all pertinent detail of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multip proposed completion or recompletion. Call and notify NMOCD 24 hrs. before operations begin. MIRU. NDWH. NU BOPE. RIH and tag CIBP@5,970', circulate well w/9.5 ppg mud at test casing. Spot 25sx of Class "C" cement from 3,109'-2,900', WOC& 	ils, and give pertinent dates, including estimated date le Completions: Attach wellbore diagram of and spot 25sx of cmt. on top. Pressure &Tag. (B.Salt)
 Describe proposed or completed operations. (Clearly state all pertinent detair of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multip proposed completion or recompletion. Call and notify NMOCD 24 hrs. before operations begin. MIRU. NDWH. NU BOPE. RIH and tag CIBP@5,970',circulate well w/9.5 ppg mud a test casing. Spot 25sx of Class "C" cement from 3,109'-2,900', WOC& 5. Spot 50sx of Class "C" cement from 2,202'-1,762', WOC& 	ils, and give pertinent dates, including estimated date le Completions: Attach wellbore diagram of and spot 25sx of cmt. on top. Pressure &Tag. (B.Salt) &Tag. (Shoe/T.Salt)
 Describe proposed or completed operations. (Clearly state all pertinent detair of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multip proposed completion or recompletion. Call and notify NMOCD 24 hrs. before operations begin. MIRU. NDWH. NU BOPE. RIH and tag CIBP@5,970', circulate well w/9.5 ppg mud a test casing. Spot 25sx of Class "C" cement from 3,109'-2,900', WOC& 5. Spot 50sx of Class "C" cement from 2,202'-1,762', WOC& 6. Spot 40sx of Class "C" cement from 350' to surface. (FW/starting) 	ils, and give pertinent dates, including estimated date le Completions: Attach wellbore diagram of and spot 25sx of cmt. on top. Pressure &Tag. (B.Salt) &Tag. (Shoe/T.Salt) surface)
 Describe proposed or completed operations. (Clearly state all pertinent detair of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multip proposed completion or recompletion. Call and notify NMOCD 24 hrs. before operations begin. MIRU. NDWH. NU BOPE. RIH and tag CIBP@5,970',circulate well w/9.5 ppg mud a test casing. Spot 25sx of Class "C" cement from 3,109'-2,900', WOC& 5. Spot 50sx of Class "C" cement from 2,202'-1,762', WOC& 6. Spot 40sx of Class "C" cement from 350' to surface. (FW/57. Verify cement to surface on all casings. Cut off wellhead a 	ils, and give pertinent dates, including estimated date le Completions: Attach wellbore diagram of and spot 25sx of cmt. on top. Pressure &Tag. (B.Salt) &Tag. (Shoe/T.Salt) surface)
 Describe proposed or completed operations. (Clearly state all pertinent detair of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multip proposed completion or recompletion. Call and notify NMOCD 24 hrs. before operations begin. MIRU. NDWH. NU BOPE. RIH and tag CIBP@5,970', circulate well w/9.5 ppg mud a test casing. Spot 25sx of Class "C" cement from 3,109'-2,900', WOC& 5. Spot 50sx of Class "C" cement from 2,202'-1,762', WOC& 6. Spot 40sx of Class "C" cement from 350' to surface. (FW/77. Verify cement to surface on all casings. Cut off wellhead a dryhole marker and clean location. 	ils, and give pertinent dates, including estimated date le Completions: Attach wellbore diagram of and spot 25sx of cmt. on top. Pressure Tag. (B.Salt) Tag. (Shoe/T.Salt) Surface) Ind anchors 3' below grade. Weld on
 Describe proposed or completed operations. (Clearly state all pertinent detair of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multip proposed completion or recompletion. Call and notify NMOCD 24 hrs. before operations begin. MIRU. NDWH. NU BOPE. RIH and tag CIBP@5,970', circulate well w/9.5 ppg mud a test casing. Spot 25sx of Class "C" cement from 3,109'-2,900', WOC& 5. Spot 50sx of Class "C" cement from 2,202'-1,762', WOC& 6. Spot 40sx of Class "C" cement from 350' to surface. (FW/57. Verify cement to surface on all casings. Cut off wellhead a dryhole marker and clean location. 	ils, and give pertinent dates, including estimated date le Completions: Attach wellbore diagram of and spot 25sx of cmt. on top. Pressure &Tag. (B.Salt) &Tag. (Shoe/T.Salt) surface) and anchors 3' below grade. Weld on ide
 Describe proposed or completed operations. (Clearly state all pertinent detair of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multip proposed completion or recompletion. Call and notify NMOCD 24 hrs. before operations begin. MIRU. NDWH. NU BOPE. RIH and tag CIBP@5,970', circulate well w/9.5 ppg mud a test casing. Spot 25sx of Class "C" cement from 3,109'-2,900', WOC& 5. Spot 50sx of Class "C" cement from 2,202'-1,762', WOC& 6. Spot 40sx of Class "C" cement from 350' to surface. (FW/7). Verify cement to surface on all casings. Cut off wellhead a dryhole marker and clean location. Closed loop above ground tank system will be used for fluit 	ils, and give pertinent dates, including estimated date le Completions: Attach wellbore diagram of and spot 25sx of cmt. on top. Pressure Tag. (B.Salt) Tag. (Shoe/T.Salt) Surface) and anchors 3' below grade. Weld on ids.
 Describe proposed or completed operations. (Clearly state all pertinent detair of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multip proposed completion or recompletion. Call and notify NMOCD 24 hrs. before operations begin. MIRU. NDWH. NU BOPE. RIH and tag CIBP@5,970',circulate well w/9.5 ppg mud attest casing. Spot 25sx of Class "C" cement from 3,109'-2,900', WOC& Spot 50sx of Class "C" cement from 2,202'-1,762', WOC& Spot 40sx of Class "C" cement from 350' to surface. (FW/7). Verify cement to surface on all casings. Cut off wellhead a dryhole marker and clean location. Closed loop above ground tank system will be used for fluit NOTIF 	ils, and give pertinent dates, including estimated date le Completions: Attach wellbore diagram of and spot 25sx of cmt. on top. Pressure Tag. (B.Salt) Tag. (Shoe/T.Salt) Surface) anchors 3' below grade. Weld on ids. BY OCD 24 HOURS PRIOR TO SUNING PLUGGING OPERATIONS
 Describe proposed or completed operations. (Clearly state all pertinent detair of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multip proposed completion or recompletion. Call and notify NMOCD 24 hrs. before operations begin. MIRU. NDWH. NU BOPE. RIH and tag CIBP@5,970', circulate well w/9.5 ppg mud a test casing. Spot 25sx of Class "C" cement from 3,109'-2,900', WOC& 5. Spot 50sx of Class "C" cement from 2,202'-1,762', WOC& 6. Spot 40sx of Class "C" cement from 350' to surface. (FW/7). Verify cement to surface on all casings. Cut off wellhead a dryhole marker and clean location. Closed loop above ground tank system will be used for fluit 	ils, and give pertinent dates, including estimated date le Completions: Attach wellbore diagram of and spot 25sx of cmt. on top. Pressure &Tag. (B.Salt) &Tag. (Shoe/T.Salt) surface) and anchors 3' below grade. Weld on ide
 Describe proposed or completed operations. (Clearly state all pertinent detair of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multip proposed completion or recompletion. Call and notify NMOCD 24 hrs. before operations begin. MIRU. NDWH. NU BOPE. RIH and tag CIBP@5,970',circulate well w/9.5 ppg mud attest casing. Spot 25sx of Class "C" cement from 3,109'-2,900', WOC& Spot 50sx of Class "C" cement from 2,202'-1,762', WOC& Spot 40sx of Class "C" cement from 350' to surface. (FW/7). Verify cement to surface on all casings. Cut off wellhead a dryhole marker and clean location. Closed loop above ground tank system will be used for fluit NOTIF 	ils, and give pertinent dates, including estimated date le Completions: Attach wellbore diagram of and spot 25sx of cmt. on top. Pressure Tag. (B.Salt) Tag. (Shoe/T.Salt) Surface) anchors 3' below grade. Weld on ids. BY OCD 24 HOURS PRIOR TO SUNING PLUGGING OPERATIONS
 Describe proposed or completed operations. (Clearly state all pertinent detair of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multip proposed completion or recompletion. Call and notify NMOCD 24 hrs. before operations begin. MIRU. NDWH. NU BOPE. RIH and tag CIBP@5,970',circulate well w/9.5 ppg mud attest casing. Spot 25sx of Class "C" cement from 3,109'-2,900', WOC& Spot 50sx of Class "C" cement from 2,202'-1,762', WOC& Spot 40sx of Class "C" cement from 350' to surface. (FW/7). Verify cement to surface on all casings. Cut off wellhead a dryhole marker and clean location. Closed loop above ground tank system will be used for fluit NOTIF 	ils, and give pertinent dates, including estimated date le Completions: Attach wellbore diagram of and spot 25sx of cmt. on top. Pressure Tag. (B.Salt) Tag. (Shoe/T.Salt) Surface) anchors 3' below grade. Weld on ids. BY OCD 24 HOURS PRIOR TO SUNING PLUGGING OPERATIONS
 Describe proposed or completed operations. (Clearly state all pertinent detain of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multip proposed completion or recompletion. Call and notify NMOCD 24 hrs. before operations begin. MIRU. NDWH. NU BOPE. RIH and tag CIBP@5,970', circulate well w/9.5 ppg mud attest casing. Spot 25sx of Class "C" cement from 3,109'-2,900', WOC& 5. Spot 50sx of Class "C" cement from 2,202'-1,762', WOC& 6. Spot 40sx of Class "C" cement from 350' to surface. (FW/7). Verify cement to surface on all casings. Cut off wellhead addryhole marker and clean location.	ils, and give pertinent dates, including estimated date le Completions: Attach wellbore diagram of and spot 25sx of cmt. on top. Pressure &Tag. (B.Salt) &Tag. (Shoe/T.Salt) &Tag. (Shoe/T
13. Describe proposed or completed operations. (Clearly state all pertinent detain of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multip proposed completion or recompletion. 1. Call and notify NMOCD 24 hrs. before operations begin. 2. MIRU. NDWH. NU BOPE. 3. RIH and tag CIBP@5,970', circulate well w/9.5 ppg mud a test casing. 4. Spot 25sx of Class "C" cement from 3,109'-2,900', WOC& 5. Spot 50sx of Class "C" cement from 2,202'-1,762', WOC& 6. Spot 40sx of Class "C" cement from 350' to surface. (FW/7). Verify cement to surface on all casings. Cut off wellhead a dryhole marker and clean location. Closed loop above ground tank system will be used for fluid NOTIF BEGIN SIGNATURE	ils, and give pertinent dates, including estimated date le Completions: Attach wellbore diagram of and spot 25sx of cmt. on top. Pressure Tag. (B.Salt) Tag. (Shoe/T.Salt) Surface) and anchors 3' below grade. Weld on ids. Y OCD 24 HOURS PRIOR TO SINING PLUGGING OPERATIONS
13. Describe proposed or completed operations. (Clearly state all pertinent detain of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multip proposed completion or recompletion. 1. Call and notify NMOCD 24 hrs. before operations begin. 2. MIRU. NDWH. NU BOPE. 3. RIH and tag CIBP@5,970', circulate well w/9.5 ppg mud at test casing. 4. Spot 25sx of Class "C" cement from 3,109'-2,900', WOC& 5. Spot 50sx of Class "C" cement from 2,202'-1,762', WOC& 6. Spot 40sx of Class "C" cement from 350' to surface. (FW/7) Verify cement to surface on all casings. Cut off wellhead a dryhole marker and clean location. Closed loop above ground tank system will be used for fluid I hereby certify that the information above is true and complete to the best SIGNATURE	ils, and give pertinent dates, including estimated date de Completions: Attach wellbore diagram of and spot 25sx of cmt. on top. Pressure Tag. (B.Salt) (Shoe/T.Salt) (Sho
13. Describe proposed or completed operations. (Clearly state all pertinent detain of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multip proposed completion or recompletion. 1. Call and notify NMOCD 24 hrs. before operations begin. 2. MIRU. NDWH. NU BOPE. 3. RIH and tag CIBP@5,970', circulate well w/9.5 ppg mud at test casing. 4. Spot 25sx of Class "C" cement from 3,109'-2,900', WOC& 5. Spot 50sx of Class "C" cement from 2,202'-1,762', WOC& 6. Spot 40sx of Class "C" cement from 350' to surface. (FW/7) Verify cement to surface on all casings. Cut off wellhead a dryhole marker and clean location. Closed loop above ground tank system will be used for fluid I hereby certify that the information above is true and complete to the best SIGNATURE	ils, and give pertinent dates, including estimated date le Completions: Attach wellbore diagram of and spot 25sx of cmt. on top. Pressure &Tag. (B.Salt) &Tag. (Shoe/T.Salt) &Tag. (Shoe/T

Well: Field: Lovington Paddock Unit 86

Lovington

Reservoir:

Paddock

API: St.:

Loc:

30-025-31066-00

New Mexico

1595' FNL and 2485' FEL


Sec:

36

Tws: Rng:

16S 36E

Spud Date: 2/16/1991 TD Date: 3/1/1991 Comp Date: 3/23/1991



8-5/8" 24# K55 ST&C @ 1962' (45 jts)

907sx CI "C" lead & 300sx CI "C" tail CMT:

TOC: Surface (circ)

HOLE: 12-1/4"

5-1/2" 15.5# K55 LT&C @ 6335' (144 jts)

CMT: 1300sx CI "C" lead & 600sx CI "C" tail

TOC: Surface (circ)

HOLE: 7-7/8"

CIBP @ 5970' (12/19/2007)

COTD: PBTD:

TD:

6350'

= = =

=

=

Perforations

6002-6287'

PROPOSED WELLBORE DIAGRAM

Lease: Location:		N PADDOC _ & 2485' F		Well No	o: 86 36-T16S-R36E	_	Field: PADDOCK			
County:	Lea	St:		Refno:		API:	30-025-31	066	Cost Center:	
				_						
Surface Csg Size: Wt.:	8-5/8" 24#	_					Spot 40sx (FW/surfa		ass "C" Cement from 350'-surface.	
Set @: Sxs cmt: Circ: TOC: Hole Size:	1962' 1207 Yes Surf 12-1/4"	-			MLF					
Production			2	4		7	Spot 50sx WOC&TA		ass "C" Cement from 2202'-1762'. Salt/Shoe)	
Size: Wt.: Set @: Sxs Cmt:	5-1/2" 15.5# 6335' 1900	-								
Circ: Hole Size: PBTD: TD:	Yes 7-7/8"	-			MLF					
							Spot 25sx WOC&TA		ass "C" Cement from 3109'-2900'. Salt)	
T.Salt B.Salt Yates San Andres	2152' 3059' 3105' 4649'					,				
Glorieta	6000'				MLF					
		CIRDAFO	70!	=			Tag CIBP	@5970	o' and spot 25sx on top thru tubing.	
		CIBP@597	J	=						
		600	2'-6287'	=						
Remarks:		-								
		Updated by: LRQS Prepared by:								
				D	ate: 03/01/17			Date		