

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIANGLE
(Other Instructions on
reverse side)

Budget Bureau No. 1004-6135
Expires August 31, 1985

5. LEASE DESIGNATION AND SERIAL NO.

LC-063623

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR
Dyco Petroleum Corporation

3. ADDRESS OF OPERATOR
7130 S. Lewis Galleria Tower I Ste 300, Tulsa, OK 74136

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface 1980' FSL + 660' FEL Sec 31-T9S-R38E
Unit H

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Union Federal

9. WELL NO.

10. FIELD AND POOL OR WILDCAT

Sawyer

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec 31, T9S, R38E

12. COUNTY OR PARISH 13. STATE

Lea New Mexico

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANE

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

- 1) Fill hole with plugging mud and pull tubing out of hole
- 2) Set CIBP @ 4350' and cap with 35' cement using a dump bailer
- 3) Determine free point of casing and cut casing above free point
- 4) Spot 100' cement at cut in casing (50' in and out of cut)
- 5) Pull casing to 2,500' and spot 100' cement from 2,400-2,500' (ton of salt)
- 6) Pull casing to 363' and spot 100' cement across base of surface casing from 263-363" (50' in and out of casing).
- 7) Pull remainder of casing out of hole and set 50' cement surface plug
- 8) Weld on cap and mark well as per regulations
- 9) Clean and restore location to original condition or as per field inspector's requests

Plug Date 5-23-83

RECEIVED
NOV 18 10 56 AM '87
CARLSBAD SURGE
AREA HEADQUARTERS

18. I hereby certify that the foregoing is true and correct

SIGNED

W. A. Baker

TITLE

Production Clerk

DATE

Nov 16, 87

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

8-15-88

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side